

HEIDENHAIN



GAGE-CHEK 2000

Operating Instructions

Evaluation Unit

English (en) 06/2021

Contents

1	Fundamentals	13
2	Safety	23
3	Transport and storage	29
4	Mounting	35
5	Installation	41
6	Basic operation	51
7	Commissioning	77
8	Setup	123
9	Measuring	161
10	File management	177
11	Settings	185
12	Servicing and maintenance	223
13	What to do if	237
14	Removal and disposal	241
15	Specifications	243
16	Index	249
17	List of figures	252

1.1 Overview 14 1.2 Information on the product. 14 1.3 Overview of new and modified functions. 15 1.4 Demo software for the product. 16 1.5 Documentation on the product. 16 1.5.1 Validity of the documentation. 16 1.5.2 Notes on reading the documentation. 17 1.5.3 Storage and distribution of the documentation. 18 1.6 About these instructions. 18 1.6.1 Document category. 18 1.6.2 Target groups for the instructions. 18 1.6.3 Target groups according to user types. 19 1.6.4 Contents of the chapters. 19 1.6.5 Notes in this documentation. 21 1.6.6 Symbols and fonts used for marking text. 22 2 Safety. 23 2.1 Overview. 24 2.2 General safety precautions. 25 2.6 Obligations of the operating company. 25 2.7 Ejectrical safety precautions. 26	1	1 Fundamentals			
1.3 Overview of new and modified functions		1.1	Overview	14	
1.4 Demo software for the product 16 1.5 Documentation on the product 16 1.5.1 Validity of the documentation 16 1.5.2 Notes on reading the documentation 17 1.5.3 Storage and distribution of the documentation 18 1.6 About these instructions 18 1.6.1 Document category 18 1.6.2 Target groups for the instructions 18 1.6.3 Target groups according to user types 19 1.6.4 Contents of the chapters 19 1.6.5 Notes in this documentation 21 1.6.6 Symbols and fonts used for marking text 22 2 Safety 23 2.1 Overview 24 2.2 General safety precautions 24 2.3 Intended use 24 2.5 Personnel qualification 25 2.6 Obligations of the operating company 25 2.7 General safety precautions 26 2.7.1 Symbols on the product 26		1.2	Information on the product	14	
1.5 Documentation on the product 16 1.5.1 Validity of the documentation 16 1.5.2 Notes on reading the documentation 17 1.5.3 Storage and distribution of the documentation 18 1.6 About these instructions 18 1.6.1 Document category 18 1.6.2 Target groups for the instructions 18 1.6.3 Target groups according to user types 19 1.6.4 Contents of the chapters 19 1.6.5 Notes in this documentation 21 1.6.6 Symbols and fonts used for marking text 22 2 Safety 23 2.1 Overview 24 2.2 General safety precautions 24 2.3 Intended use 24 2.4 Improper use 24 2.5 Personnel qualification 25 2.6 Obligations of the operating company 25 2.7 General safety precautions 26 2.7.1 Symbols on the product 26		1.3	Overview of new and modified functions	15	
1.5 Documentation on the product 16 1.5.1 Validity of the documentation 16 1.5.2 Notes on reading the documentation 17 1.5.3 Storage and distribution of the documentation 18 1.6 About these instructions 18 1.6.1 Document category 18 1.6.2 Target groups for the instructions 18 1.6.3 Target groups according to user types 19 1.6.4 Contents of the chapters 19 1.6.5 Notes in this documentation 21 1.6.6 Symbols and fonts used for marking text 22 2 Safety 23 2.1 Overview 24 2.2 General safety precautions 24 2.3 Intended use 24 2.4 Improper use 24 2.5 Personnel qualification 25 2.6 Obligations of the operating company 25 2.7 General safety precautions 26 2.7.1 Symbols on the product 26		1 4	Demo software for the product	16	
1.5.1 Validity of the documentation					
1.5.2 Notes on reading the documentation 17 1.5.3 Storage and distribution of the documentation 18 1.6 About these instructions 18 1.6.1 Document category 18 1.6.2 Target groups for the instructions 18 1.6.2 Target groups according to user types 19 1.6.3 Target groups according to user types 19 1.6.4 Contents of the chapters 19 1.6.5 Notes in this documentation 21 1.6.6 Symbols and fonts used for marking text 22 2 Safety 23 2.1 Overview 24 2.2 General safety precautions 24 2.3 Intended use 24 2.4 Improper use 24 2.5 Personnel qualification 25 2.6 Obligations of the operating company 25 2.7 General safety precautions 26 2.7.1 Symbols on the product 26		1.5			
1.5.3 Storage and distribution of the documentation 18 1.6 About these instructions 18 1.6.1 Document category 18 1.6.2 Target groups for the instructions 18 1.6.3 Target groups according to user types 19 1.6.4 Contents of the chapters 19 1.6.5 Notes in this documentation 21 1.6.6 Symbols and fonts used for marking text 22 2 Safety 23 2.1 Overview 24 2.2 General safety precautions 24 2.3 Intended use 24 2.4 Improper use 24 2.5 Personnel qualification 25 2.6 Obligations of the operating company 25 2.7 General safety precautions 26 2.7.1 Symbols on the product 26			,		
1.6 About these instructions. 18 1.6.1 Document category. 18 1.6.2 Target groups for the instructions. 18 1.6.3 Target groups according to user types. 19 1.6.4 Contents of the chapters. 19 1.6.5 Notes in this documentation. 21 1.6.6 Symbols and fonts used for marking text. 22 2 Safety. 23 2.1 Overview. 24 2.2 General safety precautions. 24 2.3 Intended use. 24 2.4 Improper use. 24 2.5 Personnel qualification. 25 2.6 Obligations of the operating company. 25 2.7 General safety precautions. 26 2.7.1 Symbols on the product. 26					
1.6.1 Document category			1.5.3 Storage and distribution of the documentation	18	
1.6.2 Target groups for the instructions		1.6	About these instructions	18	
1.6.3 Target groups according to user types 19 1.6.4 Contents of the chapters 19 1.6.5 Notes in this documentation 21 1.6.6 Symbols and fonts used for marking text 22 2 Safety 23 2.1 Overview 24 2.2 General safety precautions 24 2.3 Intended use 24 2.4 Improper use 24 2.5 Personnel qualification 25 2.6 Obligations of the operating company 25 2.7 General safety precautions 26 2.71 Symbols on the product 26			1.6.1 Document category	18	
1.6.4 Contents of the chapters. 19 1.6.5 Notes in this documentation. 21 1.6.6 Symbols and fonts used for marking text. 22 2 Safety. 23 2.1 Overview. 24 2.2 General safety precautions. 24 2.3 Intended use. 24 2.4 Improper use. 24 2.5 Personnel qualification. 25 2.6 Obligations of the operating company. 25 2.7 General safety precautions. 26 2.7.1 Symbols on the product. 26			1.6.2 Target groups for the instructions	18	
1.6.5 Notes in this documentation 21 1.6.6 Symbols and fonts used for marking text 22 2 Safety 23 2.1 Overview 24 2.2 General safety precautions 24 2.3 Intended use 24 2.4 Improper use 24 2.5 Personnel qualification 25 2.6 Obligations of the operating company 25 2.7 General safety precautions 26 2.7.1 Symbols on the product 26					
1.6.6 Symbols and fonts used for marking text			·		
2 Safety					
2.1 Overview			1.6.6 Symbols and fonts used for marking text	22	
2.1 Overview	2	Cofe	-4	22	
2.2 General safety precautions 24 2.3 Intended use 24 2.4 Improper use 24 2.5 Personnel qualification 25 2.6 Obligations of the operating company 25 2.7 General safety precautions 26 2.7.1 Symbols on the product 26	2	Sare	ety	23	
2.3 Intended use242.4 Improper use242.5 Personnel qualification252.6 Obligations of the operating company252.7 General safety precautions262.7.1 Symbols on the product26		2.1	Overview	24	
2.4Improper use		2.2	General safety precautions	24	
2.4Improper use		2.3	Intended use	24	
2.5 Personnel qualification					
2.6 Obligations of the operating company		2.4	Improper use	24	
2.7 General safety precautions		2.5	Personnel qualification	25	
2.7.1 Symbols on the product		2.6	Obligations of the operating company	25	
2.7.1 Symbols on the product		2.7	General safety precautions	26	
,		,			
			,		

3	Tran	Transport and storage		
	3.1	Overview	. 30	
	3.2	Unpacking	. 30	
	3.3	Items supplied and accessories	30	
	0.0	3.3.1 Items supplied		
		3.3.2 Accessories	31	
	3.4	In case of damage in transit	33	
	3.5	Repackaging and storage	33	
	5.5	3.5.1 Repackaging the product		
		3.5.2 Storage of the product		
4	Mou	ınting	. 35	
	4.1	Overview	. 36	
	4.2	Assembly of the product	. 36	
		4.2.1 Mounting on Single-Pos stand	37	
		4.2.2 Mounting on Duo-Pos stand	38	
		4.2.3 Mounting on Multi-Pos stand		
		4.2.4 Mounting on Multi-Pos holder	40	
5	Insta	allation	.41	
	5.1	Overview	. 42	
	5.2	General information	12	
	5.3	Device overview		
	5.4	Connecting encoders	. 45	
	5.5	Connecting touch probes	. 46	
	5.6	Wiring switching inputs and outputs	47	
	5.7	Connecting input devices	48	
	5.8	Connecting a network peripheral	49	
	5.9	Connecting the line voltage	49	

6	Basi	c opera	tion	51
	6.1	Overvie	ew	52
	6.2	Using t	the touchscreen and input devices	52
	0.12	6.2.1	Touchscreen and input devices	
		6.2.2	Gestures and mouse actions.	
	6.3	Genera	l operating elements and functions	54
	6.4	GAGE-	CHEK 2000 – switch-on and switch-off	56
		6.4.1	Switching on the GAGE-CHEK 2000	56
		6.4.2	Activating and deactivating the energy saving mode	56
		6.4.3	Switching off the GAGE-CHEK 2000	57
	6.5	User lo	ogin and logout	57
		6.5.1	User login	58
		6.5.2	User logout	
	6.6	Satting	the language	50
		•		
	6.7		ning the reference mark search after startup	
	6.8	User in	iterface	59
		6.8.1	User interface after switch-on	60
		6.8.2	Main menu of the user interface	
		6.8.3	Measure menu	
		6.8.4	File management menu	
		6.8.5	User login menu	
		6.8.6	Settings menu	
		6.8.7	Switch-off menu	66
	6.9	Position	n display	66
		6.9.1	Operating elements of the position display	66
	6.10	Custom	nizing the workspace	67
		6.10.1	Hiding and showing the main menu	67
		6.10.2	Hiding or displaying the function bar	
		6.10.3	Scrolling the function bar	67
		6.10.4	Moving functions on the function bar	68
	6.11	Using t	the function bar	68
		6.11.1	Operating elements of the function bar	
		6.11.2	Function elements	
		6.11.3	Adjusting settings in the quick access menu	
	6 12	Massac	ges and audio feedback	72
	0.12	6.12.1	Messages	
		0.12.1	IVIE55aye5	/3

		6.12.2	Wizard	
		6.12.3	Audio feedback	75
7	Con	nmissior	ning	77
	7.1	Overvie	9W	78
	7.2	Loggin	g in for commissioning	79
	1.2		-	
		7.2.1 7.2.2	User login Performing the reference mark search after startup	
		7.2.2 7.2.3	Setting the language	
		7.2.3 7.2.4	Changing the password	
		7.2.4	Changing the password	00
	7.3	Steps f	or commissioning	80
	7.4	Basic s	ettings	81
		7.4.1	Activating the Software options	81
		7.4.2	Setting the date and time	84
		7.4.3	Setting the units of measure	84
		o (:	ıring a touch probe	95
	7.5	Configu	aring a touch probe	
	7.5 7.6		uring the axes	
		_		85
		Configu	uring the axes	
		Configu 7.6.1	uring the axes	85 86
		Configu 7.6.1 7.6.2	Configuring Alias assignment for axis names Overview of typical encoders	
		7.6.1 7.6.2 7.6.3	Configuring Alias assignment for axis names Overview of typical encoders Configuring axes for encoders with EnDat interface	
		76.1 76.2 76.3 76.4	Configuring Alias assignment for axis names Overview of typical encoders Configuring axes for encoders with EnDat interface Configuring the axes for encoders with a 1 V _{PP} or 11 µA _{PP} interface	
		7.6.1 7.6.2 7.6.3 7.6.4 7.6.5	Configuring Alias assignment for axis names Overview of typical encoders Configuring axes for encoders with EnDat interface Configuring the axes for encoders with a 1 V _{PP} or 11 µA _{PP} interface Configuring axes for encoders with TTL interface	
		76.1 76.2 76.3 76.4 76.5 7.6.6	Configuring Alias assignment for axis names Overview of typical encoders Configuring axes for encoders with EnDat interface Configuring the axes for encoders with a 1 V _{PP} or 11 µA _{PP} interface Configuring axes for encoders with TTL interface Performing error compensation	
		Configu 7.6.1 7.6.2 7.6.3 7.6.4 7.6.5 7.6.6 7.6.7 7.6.8	Configuring Alias assignment for axis names Overview of typical encoders Configuring axes for encoders with EnDat interface Configuring the axes for encoders with a 1 V _{PP} or 11 µA _{PP} interface Configuring axes for encoders with TTL interface Performing error compensation Coupling axes	
	7.6	Configu 7.6.1 7.6.2 7.6.3 7.6.4 7.6.5 7.6.6 7.6.7 7.6.8	Configuring Alias assignment for axis names Overview of typical encoders Configuring axes for encoders with EnDat interface Configuring the axes for encoders with a 1 V _{PP} or 11 µA _{PP} interface Configuring axes for encoders with TTL interface Performing error compensation Coupling axes Activating the reference mark search	
	7.6	Configu 7.6.1 7.6.2 7.6.3 7.6.4 7.6.5 7.6.6 7.6.7 7.6.8	Configuring Alias assignment for axis names Overview of typical encoders Configuring axes for encoders with EnDat interface Configuring the axes for encoders with a 1 V _{PP} or 11 µA _{PP} interface Configuring axes for encoders with TTL interface Performing error compensation Coupling axes Activating the reference mark search	
	7.6	Configu 7.6.1 7.6.2 7.6.3 7.6.4 7.6.5 7.6.6 7.6.7 7.6.8 OEM at 7.7.1	Configuring Alias assignment for axis names Overview of typical encoders Configuring axes for encoders with EnDat interface Configuring the axes for encoders with a 1 V _{PP} or 11 µA _{PP} interface Configuring axes for encoders with TTL interface Performing error compensation Coupling axes Activating the reference mark search	
	7.6	Configuration 7.6.1 7.6.2 7.6.3 7.6.4 7.6.5 7.6.6 7.6.7 7.6.8 OEM at 7.7.1 7.7.2 7.7.3	Configuring Alias assignment for axis names Overview of typical encoders Configuring axes for encoders with EnDat interface Configuring the axes for encoders with a 1 V _{PP} or 11 µA _{PP} interface Configuring axes for encoders with TTL interface Performing error compensation Coupling axes Activating the reference mark search Adding documentation Adding a startup screen	
	7.6	Configuration 7.6.1 7.6.2 7.6.3 7.6.4 7.6.5 7.6.6 7.6.7 7.6.8 OEM at 7.7.1 7.7.2 7.7.3	Configuring Alias assignment for axis names	

8	Set	up		123
	8.1	Overvi	ew	124
	0.1	OVCIVI	CVV	164
	8.2	Loggin	g in for setup	124
		8.2.1	User login	124
		8.2.2	Performing the reference mark search after startup	125
		8.2.3	Setting the language	125
		8.2.4	Changing the password	126
	8.3	Single	steps for setup	127
	0.5			
		8.3.1	Basic settings	
		8.3.2	Adding function elements	
		8.3.3	Configuring probing functions	
		8.3.4	Configuring the MinMax function	
		8.3.5	Configuring the Diameter/Radius function	
		8.3.6	Configuring the Relative function	
		8.3.7	Configuring the Mastering function	
		8.3.8	Configure the Dial gage function	
		8.3.9	Creating a preset table	
		8.3.10	Configuring the measured value output	
		8.3.11	Configuring the Part function	156
	8.4	Back u	p settings	159
	8.5	Back u	p user files	160
			•	
9	Mea	asuring		161
			ew	
	9.1	Overvi	ew	
	9.2	Condu	cting a measurement	162
		9.2.1	Preparing a measurement	162
		9.2.2	Selecting a preset	164
		9.2.3	Measuring lengths and angles	166
		9.2.4	Measuring with a touch probe	167
		9.2.5	Measuring with probing functions	167
		9.2.6	Acquiring the minimum, maximum, and range	169
		9.2.7	Displaying the diameter	170
		9.2.8	Performing a relative measurement	171
		9.2.9	Measure with dial gage	172
		9.2.10	Sending measured values to a computer	174
		9.2.11	Using part management	175

10	File	management17	77
	10.1	Overview1	78
		File types1	
	10.3	Managing folders and files1	79
	10.4	Viewing and opening files1	81
	10.5	Exporting files	82
	10.6	Importing files	83

11	Sett	ıngs		185
	11.1	Overvie	eW	186
		11.1.1	Overview of the Settings menu	187
	11.0	C	I	400
	11.2			
		11.2.1 11.2.2	Device information	
			Display	
		11.2.3 11.2.4	Input devices	
		11.2.4	Sounds	
		11.2.6	Printers	
		11.2.7	Date and time	
		11.2.8	Units	
		11.2.9	Copyrights	
		11.2.10	Service info	
		11.2.11	Documentation	193
	11.3	Concor	S	104
	11.3			
		11.3.1	Touch probe	
	11.4	Interfac	ces	195
		11.4.1	Network	195
		11.4.2	Network drive	196
		11.4.3	USB	
		11.4.4	RS-232	
		11.4.5	Data transfer	
		11.4.6	Switching functions	
		11.4.7	Position-dependent switching functions	199
	11.5	User		200
		11.5.1	OEM	200
		11.5.2	Setup	200
		11.5.3	Operator	201
		11.5.4	Adding User	201
	11.6	Axes		202
		11.6.1	Reference marks	202
		11.6.2	Information	203
		11.6.3	Error compensation	203
		11.6.4	Nonlinear error compensation (NLEC)	203
		11.6.5	Squareness error compensation (SEC)	204
		11.6.6	Alias assignment for axis names	204
		11.6.7	<axis name=""> (settings of the axis)</axis>	204
		11.6.8	Encoder	206
		11.6.9	Reference marks (Encoder)	210
		11.6.10	Reference point displacement	211

	11.6.11	Diagnostics for encoders with EnDat interface	212
	11.6.12	Diagnostics for encoders with 1 V _{PP} /11 μA _{PP}	214
	11.6.13	Linear error compensation (LEC)	215
	11.6.14	Segmented linear error compensation (SLEC)	215
	11.6.15	Create table of supporting points	216
11.7	Service	s	217
	11.7.1	Firmware information	217
	11.7.2	Back up and restore	218
	11.7.3	Firmware update	219
	11.7.4	Reset	219
	11.7.5	OEM area	220
	11.7.6	Startup screen	220
	11.7.7	Documentation	220
	11.7.8	Software options	221
Serv	icing ar	nd maintenance	223
12.1	Overvie	ew	224
12.2	Cleanin	ıg	224
12.3	Mainte	nance plan	225
12.4	Resumi	ing operation	225
12.5	Updatir	ng the firmware	226
12.6	Encode	er diagnostics	228
	12.6.1	Diagnostics for encoders with 1 V _{PP} /11 μA _{PP} interface	228
	12.6.2	Diagnostics for encoders with EnDat interface	
12.7	Restori	ng files and settings	232
	12.7.1	Restore OEM-specific folders and files	232
	12.7.2	Restore user files	
	12.7.3	Restore settings	234
12.8	Reset a	all settings	235
12.9	Reset t	o shipping conditions	235
	Serv 12.1 12.2 12.3 12.4 12.5 12.6	11.6.12 11.6.13 11.6.14 11.6.15 11.7 Service 11.7.1 11.7.2 11.7.3 11.7.4 11.7.5 11.7.6 11.7.7 11.7.8 Servicing at 12.1 Overvice 12.2 Cleaning 12.3 Mainte 12.4 Resum 12.5 Updation 12.6.1 12.6.2 12.7.1 12.7.2 12.7.3 12.8 Reset at 12.7.3	11.6.12 Diagnostics for encoders with 1 V _{PP} /11 µA _{PP}

13	Wha	t to do	if	237
	13.1	Overvie	W	238
	13.2	System	or power failure	238
		13.2.1	Restoring the firmware	
		13.2.2	Restore settings	
	40.0	N.A 16	ctions	000
	13.3			
		13.3.1	Troubleshooting	239
14	Rem	oval and	d disposal	241
	14.1	Overnie		242
	14.2	Remova	al	242
	14.3	Disposa	ıl	242
15	Spec	cification	าร	243
	15.1	Overvie	W	244
	15.2	Product	data	244
	15.3	Product	dimensions and mating dimensions	
		15.3.1	Product dimensions with Single-Pos stand	
		15.3.2	Product dimensions with Duo-Pos stand	
		15.3.3	Product dimensions with Multi-Pos stand	
		15.3.4	Product dimensions with Multi-Pos holder	248
16	Inde	X		249
17	List	of figure	es	252

Fundamentals

1.1 Overview

This chapter contains information about the product and this manual.

1.2 Information on the product

Product designation	ID	Firmware version	Index
GAGE-CHEK 2000	1089181-xx	1248580.1.4.x	

The ID label is provided on the rear panel of the product. Example:



- 1 Product designation
- 2 Index
- 3 Part number (ID)

1.3 Overview of new and modified functions

This document provides a short overview of new and modified functions or settings becoming available with version 1248580.1.4.x.

Encoder diagnostics

The diagnostic function allows you to perform a fundamental functional check of the connected encoders.

Further information: "Diagnostics for encoders with 1 V_{PP}/11 μA_{PP} interface", Page 228

Further information: "Diagnostics for encoders with EnDat interface", Page 230

Scrolling the function bar

Once you have assigned the lowest function element, a new function element will be added and the function bar becomes scrollable.

Further information: "Scrolling the function bar", Page 67

Moving functions in the function bar

You can move the functions in the function bar by drag-and-drop as needed.

Further information: "Moving functions on the function bar", Page 68

Part function

The **Part** function encompasses the required functions for the object to be measured. When the **Part** function is activated, all irrelevant functions are hidden.

Further information: "Configuring the Part function", Page 156

MinMax function

The **MinMax** function was expanded to include name and comment. The comment is shown when the function is executed and can be used as work instructions, for example.

In the configuration menu of the **MinMax** function, another page was added in which the measurement can be stopped or started, or in which a restart can be triggered with a switching function.

Further information: "Configuring the MinMax function", Page 136

Further information: "Switching functions", Page 199

Preset table

The configuration dialog of the **Preset table** has been changed.

Further information: "Creating a preset table", Page 142

Mastering function

The **Mastering** function can now be run while another function, such as **dial gage**, is active.

Further information: "Configuring the Mastering function", Page 139

Conversational languages

You can now select the conversational languages **Suomi** or **Svenska**.

Further information: "Setting the language", Page 59

1.4 Demo software for the product

GAGE-CHEK 2000 Demo is software you can install on a computer regardless of the device. GAGE-CHEK 2000 Demo helps you to become familiar with, try out or present the functions of the device.

You can download the current version of the software here: www.heidenhain.de



To download the installation file from the HEIDENHAIN Portal, you need access rights to the **Software** portal folder in the directory of the appropriate product.

If you do not have access rights to the Portal's **Software** folder, you can request the access rights from your HEIDENHAIN contact person.

1.5 Documentation on the product

1.5.1 Validity of the documentation

Before using the documentation and the product, you need to verify that the documentation matches the product.

- ► Compare the ID number and the index indicated in the documentation with the corresponding data given on the ID label of the product
- ► Compare the firmware version given in the documentation with the firmware version of the product

Further information: "Device information", Page 188

> If the ID numbers and indexes as well as the firmware versions match, the documentation is valid



If the part numbers and indexes do not match so that the documentation is not valid, you will find the current documentation for the product at **www.heidenhain.com**.

1.5.2 Notes on reading the documentation

A WARNING

Fatal accidents, personal injury or property damage caused by noncompliance with the documentation!

Failure to comply with the documentation may result in fatal accidents, personal injury or property damage.

- ▶ Read the documentation carefully from beginning to end
- Keep the documentation for future reference

The table below lists the components of the documentation in the order of priority for reading.

Documentation	Description
Addendum	An addendum supplements or supersedes the corresponding contents of the Operating Instructions and, if applicable, of the Installation Instructions. If an addendum is included in the shipment, it has the highest priority for reading. All other contents of the documentation retain their validity.
Installation Instructions	The Installation Instructions contain all of the information and safety precautions needed for the proper mounting and installation of the product. The Installation Instructions are contained as an excerpt from the Operating Instructions in every delivery. The Installation Instructions have the second highest level of priority for reading.
Operating Instructions	The Operating Instructions contain all the information and safety precautions needed for the proper operation of the product according to its intended use. The Operating Instructions are included on the supplied storage medium and can also be downloaded in the download area from www.heidenhain.com . The Operating Instructions must be read before the unit is put into service. The Operating Instructions have the third highest level of priority for reading.

Have you found any errors or would you like to suggest changes?

We continuously strive to improve our documentation for you. Please help us by sending your suggestions to the following e-mail address:

userdoc@heidenhain.de

1.5.3 Storage and distribution of the documentation

The instructions must be kept in the immediate vicinity of the workplace and must be available to all personnel at all times. The operating company must inform the personnel where these instructions are kept. If the instructions have become illegible, the operating company must obtain a new copy from the manufacturer.

If the product is given or resold to any other party, the following documents must be passed on to the new owner:

- Addendum (if supplied)
- Installation Instructions
- Operating Instructions

1.6 About these instructions

These instructions provide all the information and safety precautions needed for the safe operation of the device.

1.6.1 Document category

Operating Instructions

These instructions are the **Operating Instructions** for the product.

The Operating Instructions

- Is oriented to the product life cycle
- Contains all information and safety precautions needed for the proper operation of the product according to its intended use

1.6.2 Target groups for the instructions

These instructions must be read and observed by every person who performs any of the following tasks:

- Mounting
- Installation
- Commissioning and configuration
- Operation
- Service, cleaning and maintenance
- Troubleshooting
- Removal and disposal

1.6.3 Target groups according to user types

The target groups of these instructions refer to the various user types of the product and their authorizations.

The product features the following user types:

OEM user

The **OEM** (Original Equipment Manufacturer) user has the highest level of permissions. This user is allowed to configure the product's hardware (e.g. connection of encoders and sensors). He can create **Setup** and **Operator**-type users, and configure the **Setup** and **Operator** users. The **OEM** user cannot be duplicated or deleted. This user cannot be logged in automatically.

Setup user

The **Setup** user configures the product for use at the place of operation. This user can create **Operator**-type users. The **Setup** user cannot be duplicated or deleted. This user cannot be logged in automatically.

Operator user

The **Operator** user is permitted to use the basic functions of the product. An **Operator**-type user cannot create additional users, but is allowed to edit various operator-specific settings, such as his name or the language. A user of the **Operator** group can be logged in automatically as soon as the product is switched on.

1.6.4 Contents of the chapters

The table below shows:

- from which chapters these instructions are derived from
- which information the chapters of the instructions contain
- to which target groups the chapters of the instructions mainly apply

Section	Contents		Target group		
	This chapter contains information about	OEM	Setup	Operator	
1 "Fundamentals"	this product	ſ	1	1	
	these instructions				
2 "Cofoty"	Safety regulations and safety measures				
	for mounting the product		,	,	
2 "Safety"	for installing the product	V	✓	tor	
	for operating the product				
	transporting the product				
2 "Transport and store va"	storing the product	,	,		
3 "Transport and storage"	items supplied with the product	√	√		
	accessories for the product				
4 "Mounting"	correct mounting of the product	✓	✓		
5 "Installation"	correct installation of the product	✓	✓		

Section	Contents		Target group		
	This chapter contains information about	ОЕМ	Setup	Operator	
6 "Basic operation"	the operating elements of the product user interface the user interface of the product basic functions of the product	✓	✓	✓	
7 "Commissioning"	commissioning the product	√			
8 "Setup"	correct setup of the product		✓		
9 "Measuring"	the performance of a measurement the transmission of measured values to a computer (measured value output)			✓	
10 "File management"	the functions of the "File management" menu	✓	✓	✓	
11 "Settings"	setting options and associated setting parameters for the product	✓	✓	✓	
12 "Servicing and maintenance"	general maintenance work on the product	✓	✓	✓	
13 "What to do if"	causes of faults or malfunctions of the product corrective actions for faults or malfunctions of the product	✓	✓	✓	
14 "Removal and disposal"	disassembly and disposal of the product environment protection specifications	✓	✓	✓	
15 "Specifications"	the technical data of the product product dimensions and mating dimensions (drawings)	✓	✓	✓	
16 "Index"	This chapter enables accessing the content of these instructions according to specific topics.	✓	✓	✓	

1.6.5 Notes in this documentation

Safety precautions

Precautionary statements warn of hazards in handling the product and provide information on their prevention. Precautionary statements are classified by hazard severity and divided into the following groups:

A DANGER

Danger indicates hazards for persons. If you do not follow the avoidance instructions, the hazard **will result in death or severe injury**.

A WARNING

Warning indicates hazards for persons. If you do not follow the avoidance instructions, the hazard **could result in death or serious injury**.

ACAUTION

Caution indicates hazards for persons. If you do not follow the avoidance instructions, the hazard **could result in minor or moderate injury**.

NOTICE

Notice indicates danger to material or data. If you do not follow the avoidance instructions, the hazard **could result in property damage**.

Informational notes

Informational notes ensure reliable and efficient operation of the product. Informational notes are divided into the following groups:



The information symbol indicates a tip.

A tip provides additional or supplementary information.



The gear symbol indicates that the function described **depends on the machine**, e.g.

- Your machine must feature a certain software or hardware option
- The behavior of the functions depends on the configurable machine settings



The book symbol represents a **cross reference** to external documentation, e.g. the documentation of your machine tool builder or other supplier.

1.6.6 Symbols and fonts used for marking text

In these instructions the following symbols and fonts are used for marking text:

Depiction	Meaning	
>	Identifies an action and the result of this action	
>	Example:	
	▶ Tap OK	
	> The message is closed	
	Identifies an item of a list	
	Example:	
	TTL interface	
	EnDat interface	
	■	
Bold	Identifies menus, displays and buttons	
	Example:	
	► Tap Shut down	
	> The operating system shuts down	
	► Turn the power switch off	

Safety

2.1 Overview

This chapter provides important safety information needed for the proper operation of the unit.

2.2 General safety precautions

General accepted safety precautions, in particular the applicable precautions relating to the handling of live electrical equipment, must be followed when operating the system. Failure to observe these safety precautions may result in personal injury or damage to the product.

It is understood that safety rules within individual companies vary. If a conflict exists between the material contained in these instructions and the rules of a company using this system, the more stringent rules take precedence.

2.3 Intended use

The products of the GAGE-CHEK 2000 series are advanced digital evaluation electronics for the measurement of exact measured values and for positioning tasks in metrology applications. The products are used primarily on measuring machines and positioning equipment.

The products of this series

- must only be used in commercial applications and in an industrial environment
- must be mounted on a suitable stand or holder to ensure the correct and intended operation of the product
- are intended for indoor use in an environment in which the contamination caused by humidity, dirt, oil and lubricants complies with the requirements of the specifications



The products support the use of peripheral devices from different manufacturers. HEIDENHAIN cannot make any statements on the intended use of these devices. The information on their intended use, which is provided in the respective documentation, must be observed.

2.4 Improper use

In particular, the products of the GAGE-CHEK 2000 series must not be used in the following applications:

- Use and storage outside the operating conditions specified in "Specifications"
- Outdoor use
- Use in potentially explosive atmospheres
- Use of the products of the GAGE-CHEK 2000 series as part of a safety function

2.5 Personnel qualification

The personnel for mounting, installation, operation, service, maintenance and removal must be appropriately qualified for this work and must have obtained sufficient information from the documentation supplied with the product and with the connected peripherals.

The personnel required for the individual activities to be performed on the product are indicated in the respective sections of these instructions.

The personnel groups are specified in detail as follows with regard to their qualifications and tasks.

Operator

The operator uses and operates the product within the framework specified for the intended use. He is informed by the operating company about the special tasks and the potential hazards resulting from incorrect behavior.

Qualified personnel

The qualified personnel are trained by the operating company to perform advanced operation and parameterization. The qualified personnel have the required technical training, knowledge and experience and know the applicable regulations, and are thus capable of performing the assigned work regarding the application concerned and of proactively identifying and avoiding potential risks.

Electrical specialist

The electrical specialist has the required technical training, knowledge and experience and knows the applicable standards and regulations, and is thus capable of performing work on electrical systems and of proactively identifying and avoiding potential risks. Electrical specialists have been specially trained for the environment they work in.

Electrical specialists must comply with the provisions of the applicable legal regulations on accident prevention.

2.6 Obligations of the operating company

The operating company owns or leases the device and the peripherals. At all times, the operating company is responsible for ensuring that the intended use is complied with.

The operating company must:

- Assign the different tasks to be performed on the device to suitable, qualified and authorized personnel
- Verifiably train the personnel in the authorizations and tasks
- Provide all materials and means necessary in order for the personnel to complete the assigned tasks
- Ensure that the device is operated only when in perfect technical condition
- Ensure that the device is protected from unauthorized use

2.7 General safety precautions



The safety of any system incorporating the use of this product is the responsibility of the assembler or installer of the system.



The product supports the use of a wide variety of peripheral devices from different manufacturers. HEIDENHAIN cannot make any statements on the specific safety precautions to be taken for these devices. The safety precautions provided in the respective documentation must be observed. If there is no documentation at hand, it must be obtained from the manufacturers concerned.

The specific safety precautions required for the individual activities to be performed on the product are indicated in the respective sections of these instructions.

2.7.1 Symbols on the product

The following symbols are used to identify the product:

Symbol	Meaning
<u>^</u>	Observe the safety precautions regarding electricity and the power connection before you connect the product.
	Functional ground connection as per IEC/EN 60204-1. Observe the information on installation.
S S S S S S S S S S S S S S S S S S S	Product seal. Breaking or removing the product seal will result in forfeiture of warranty and guarantee.

2.7.2 Electrical safety precautions

A WARNING

Hazard of contact with live parts when opening the product.

This may result in electric shock, burns or death.

- Never open the housing
- ▶ Only the manufacturer is permitted to access the inside of the product

AWARNING

Hazard of dangerous amount of electricity passing through the human body upon direct or indirect contact with live electrical parts.

This may result in electric shock, burns or death.

- ► Work on the electrical system and live electrical components is to be performed only by trained specialists
- ► For power connection and all interface connections, use only cables and connectors that comply with applicable standards
- ► Have the manufacturer exchange defective electrical components immediately
- Regularly inspect all connected cables and all connections on the product. Defects, such as loose connections or scorched cables, must be removed immediately

NOTICE

Damage to internal parts of the product!

If you open the product, the warranty and the guarantee will become void.

- Never open the housing
- Only the product manufacturer is permitted to access the inside of the product

3

Transport and storage

3.1 Overview

This chapter contains information on the transportation and storage of the product and provides an overview of the items supplied and the available accessories for the product.



The following steps must be performed only by qualified personnel.

Further information: "Personnel qualification", Page 25

3.2 Unpacking

- ► Open the top lid of the box
- Remove the packaging materials
- Unpack the contents
- Check the delivery for completeness
- ► Check the delivery for damage

3.3 Items supplied and accessories

3.3.1 Items supplied

The following items are included in delivery:

Name	Description
Single-Pos stand	Stand for rigid mounting, inclination angle 20°, fixing hole pattern 50 mm x 50 mm
Installation Instructions	Printed issue of the Installation Instructions in the currently available languages
Product	Evaluation Unit GAGE-CHEK 2000
Operating Instructions	PDF issue of the Operating Instructions on a memory medium in the currently available languages
Addendum (optional)	Supplements or supersedes the contents of the Operating Instructions and, if applicable, of the Installation Instructions.

3.3.2 Accessories



Software options need to be enabled on the product via a license key. Before you can use the associated hardware components, you need to enable the respective software option.

Further information: "Activating the Software options", Page 81

The following accessories are optionally available and can be ordered from HEIDENHAIN:

Acces- sories	Name	Description	ID		
For insta	For installation				
	Adapter cable for touch-probe connection, DIN 5-pin female	Conversion of the pin layout from HEIDENHAIN touch probe interface to Renishaw touch probe interface	1095709-xx		
	Adapter connector for 11 μΑρρ	Conversion of the 11 µA _{PP} interface from installation in D-sub connector, 2-row, female, 9-pin to D-sub connector, 2-row, with locking screws, male, 15-pin	1089213-01		
	Adapter connector for 1 Vpp	Conversion of the 1 V _{PP} interface from installation in D-sub connector, 2-row, male, 15-pin to D-sub connector, 2-row, with locking screws, male, 15-pin	1089214-01		
	Adapter connector for 2 Vpp	Pin layout conversion from HEIDENHAIN 1 V _{PP} to Mitutoyo-2 V _{PP}	1089216-01		
	Adapter connector for TTL	Conversion of the pin layout from HEIDENHAIN TTL to RSF TTL and Renishaw TTL	1089210-01		
	Cables	For information on connecting cables, see "Cables and Connectors for HEIDENHAIN Products" brochure.			
	Foot switch	Foot switch for external opera- tion with two freely assigna- ble keys; cable length 2.4 m	681041-04		
	KT 130 edge finder	Touch probe for probing a workpiece (for setting presets)	283273-xx		
	Power cable	Power cable with European plug (type F), length: 3 m	223775-01		
	RS-232 connecting cable	RS-232 connecting cable, complete with two 9-pin D- sub connectors (female)	366964-xx		

Acces- sories	Name	Description	ID
	TS 248 touch probe	Touch probe for probing a workpiece (for setting presets), axial cable outlet	683110-xx
	TS 248 touch probe	Touch probe for probing a workpiece (for setting presets), radial cable outlet	683112-xx
	USB connecting cable	USB connecting cable for connector type A to type B	354770-xx
For mour	nting		
	Duo-Pos stand	Stand for rigid mounting, inclination angle 20° or 45°, fixing hole pattern 50 mm x 50 mm	1089230-06
	Mounting arm	Mounting arm for mounting to a machine	1089207-01
	Multi-Pos holder	Holder for fastening the device on an arm, continuously tiltable within an angle of 90°, fixing hole pattern 50 mm x 50 mm	1089230-08
	Multi-Pos stand	Stand for continuously variable tilting with a tilting range of 90°, fixing hole pattern 50 mm x 50 mm	1089230-07
	Single-Pos stand	Stand for rigid mounting, inclination angle 20°, fixing hole pattern 50 mm x 50 mm	1089230-05

Recommended RS-232 adapters

HEIDENHAIN recommends the following RS-232 adapters:

Part no.	Model designation	Manufacturer	Interface	Conversion
DA-70156	DIGITUS USB – serial adapter	ASSMANN Electronic GmbH	USB 2.0	Serial
-	USB to RS232 connecting cable	STEINWALD daten- technik GmbH	USB 2.0	Serial
UC232R-10	USB - RS232 adapter cable	Future Technology Devices International Limited	USB 2.0	Serial



If you connect a USB-to-RS232 connecting cable from the manufacturer STEINWALD datentechnik GmbH to the product, the data interface is configured automatically and is ready immediately. The data format **Steinwald** is used for measured value output. The settings are not configurable.



For more information on transferring data with products or the data format from **Steinwald**, please refer to:

STEINWALD datentechnik GmbH

+49 (9231) 9630-10

vertrieb@steinwald.com

3.4 In case of damage in transit

- ▶ Have the shipping agent confirm the damage
- ► Keep the packaging materials for inspection
- ► Notify the sender of the damage
- ► Contact the distributor or machine manufacturer for replacement parts



If damage occurred during transit:

- ▶ Keep the packaging materials for inspection
- ► Contact HEIDENHAIN or the machine manufacturer

This applies also if damage occurred to requested replacement parts during transit.

3.5 Repackaging and storage

Repackage and store the product carefully in accordance with the conditions stated below.

3.5.1 Repackaging the product

Repackaging should correspond to the original packaging as closely as possible.

- ▶ Re-attach all mounting parts and dust protection caps to the product as received from the factory, or repackage them in the original packaging as received from the factory
- Repackage the product in such a way that
 - it is protected from impact and vibration during transit
 - it is protected from the ingress of dust or humidity
- ▶ Place all accessories that were included in the shipment in the original packaging

Further information: "Items supplied and accessories", Page 30

► Enclose all the documentation that was included in the original packaging

Further information: "Storage and distribution of the documentation", Page 18



If the product is returned for repair to the Service department:

Ship the product without accessories, without encoders and without peripherals

3.5.2 Storage of the product

- ▶ Package the product as described above
- ► Observe the specified ambient conditions Further information: "Specifications", Page 243
- ▶ Inspect the product for damage after any transport or longer storage times

Mounting

4.1 Overview

This chapter describes the mounting of the product. It contains instructions about how to correctly mount the product on stands or holders.



The following steps must be performed only by qualified personnel.

Further information: "Personnel qualification", Page 25

4.2 Assembly of the product

General mounting information

The mount for the mounting variants is provided on the rear panel. The mounting hole pattern corresponds to a grid of 50 mm x 50 mm.




Figure 1: Dimensions of rear panel of the product

The materials for attachment of the mounting variants on the device are included in delivery.

You will also need the following:

- Torx T20 screwdriver
- Torx T25 screwdriver
- Allen key, size 2.5 (Duo-Pos stand)
- Materials for mounting on a supporting surface



The unit must be mounted to a stand or a holder to ensure the correct and intended use of the product.

4.2.1 Mounting on Single-Pos stand


You can fasten the Single-Pos stand to the product at a 20° angle.

▶ Use the provided M4 x 8 ISO 14581 countersunk head screws to fasten the stand to the upper threaded holes on the rear panel



Comply with the permissible tightening torque of 2.6 Nm

- ► Fasten the stand with two suitable screws from above to a supporting surface or
- Attach self-adhesive rubber pads to the underside of the stand
- ▶ Route the cables from behind through the opening in the stand and then to the connections






Figure 2: Product mounted on Single-Pos stand

Figure 3: Cable routing on Single-Pos stand

Further information: "Product dimensions with Single-Pos stand", Page 247

4.2.2 Mounting on Duo-Pos stand

You can fasten the Duo-Pos stand to the product at a 20° or 45° angle.



If you screw the Duo-Pos stand into the product at a 45° angle, you must attach the product at the upper end of the mounting slots. Use a power cable cable with an angled connector.

▶ Use the provided M4 x 8 ISO 7380 hexagon socket screws to fasten the stand to the lower threaded holes on the rear panel




Comply with the permissible tightening torque of 2.6 Nm

▶ Using the mounting slots (width = 4.5 mm), screw the stand to a supporting surface

or

- Set up the device freely at the desired location
- ▶ Route the cable from behind through the two supports of the stand and then through the lateral openings to the connections






Figure 4: Product mounted on Duo-Pos stand

Figure 5: Cable routing on Duo-Pos stand

Further information: "Product dimensions with Duo-Pos stand", Page 247

4.2.3 Mounting on Multi-Pos stand

▶ Use the provided M4 x 8 ISO 14581 countersunk head screws (black) to fasten the stand to the threaded holes on the rear panel




Comply with the permissible tightening torque of 2.6 Nm

- ▶ Using two M5 screws, you can also optionally screw the stand to a supporting surface from the bottom
- Adjust the desired angle of inclination
- ▶ To fix the stand: Tighten the T25 screw



Comply with the tightening torque for screw T25

- Recommended tightening torque: 5.0 Nm
- Maximum permissible tightening torque: 15.0 Nm
- ▶ Route the cable from behind through the two supports of the stand and then through the lateral openings to the connections






Figure 6: Product mounted on Multi-Pos stand

Figure 7: Cable routing on Multi-Pos stand

Further information: "Product dimensions with Multi-Pos stand", Page 248

4.2.4 Mounting on Multi-Pos holder

▶ Use the provided M4 x 8 ISO 14581 countersunk head screws (black) to fasten the holder to the threaded holes on the rear panel



Comply with the permissible tightening torque of 2.6 Nm

► Mount the holder with the supplied M8 screw, the washers, the handle and the M8 hexagon nut to an arm

or

- ► Mount the holder with two screws <7 mm through the two holes to the intended surface
- ► Adjust the desired angle of inclination
- ▶ To fix the holder in place: tighten the T25 screw



Comply with the tightening torque for screw T25

- Recommended tightening torque: 5.0 Nm
- Maximum permissible tightening torque: 15.0 Nm
- ▶ Route the cable from behind through the two supports of the holder and then through the lateral openings to the connections




Figure 8: Product mounted on Multi-Pos holder




Figure 9: Cable routing on Multi-Pos holder

Further information: "Product dimensions with Multi-Pos holder", Page 248

5

Installation

5.1 Overview

This chapter describes the Installation of the product. It contains information about the product's connections and instructions about how to correctly connect the peripheral devices.



The following steps must be performed only by qualified personnel.

Further information: "Personnel qualification", Page 25

5.2 General information

NOTICE

Interference from sources of high electromagnetic emission!

Peripheral devices, such as frequency inverters or servo drives, may cause interference.

To increase the noise immunity to electromagnetic influences:

- ▶ Use the optional functional ground connection as per IEC/EN 60204-1
- ▶ Use only USB peripherals with continuous shielding, e.g. by metalized film and metal braiding or a metal housing. The degree of coverage provided by the braiding must be 85 % or higher. The shield must be connected around the entire circumference of the connectors (360° connection).

NOTICE

Damage to the device from the engaging and disengaging of connecting elements during operation!

Damage to internal components may result.

Do not engage or disengage any connecting elements while the unit is under power

NOTICE

Electrostatic discharge (ESD)!

This device contains electrostatic sensitive components that can be destroyed by electrostatic discharge (ESD).

- ▶ It is essential to observe the safety precautions for handling ESD-sensitive components
- ▶ Never touch connector pins without ensuring proper grounding
- ▶ Wear a grounded ESD wristband when handling device connections

NOTICE

Damage to the product due to incorrect wiring!

The incorrect wiring of inputs or outputs can cause damage to the product or to peripheral devices.

- Comply with the pin layouts and specifications of the product
- Assign only pins or wires that will be used

Further information: "Specifications", Page 243

5.3 Device overview

The connections on the rear panel of the device are protected by dust protection caps from contamination and damage.

NOTICE

Contamination or damage may result if the dust protection caps are missing!

If no dust protection caps are fitted to unused connections, this may impair the proper functioning of the contacts or destroy them.

- ► Remove dust protection caps only when connecting measuring devices or peripherals
- ▶ If you remove a measuring device or peripheral, re-attach the dust protection cap to the connection



The type of connections for encoders may vary depending on the product version.

Rear panel without dust protection caps




Figure 10: Rear panel on devices with ID 1089181-01

Connections:

- 5 X1 to X3: device variant with 15-pin D-sub connections for encoders with 1 V_{PP} , 11 μA_{PP} or EnDat 2.2 interface
 - **X21 to X23**: Device variant with 9-pin D-sub connections for encoders with a TTL interface
 - **X1**, **X2**, **X21**: Device variant with two 15-pin D-sub connections for encoders with the 1 V_{PP} , 11μ A_{PP} , or EnDat 2.2 interfaces, and a 9-pin D-sub connection for encoders with a TTL interface
- **7** X32: USB 2.0 Hi-speed connection (type A) for printers, input devices or USB mass storage
- 10 Speaker
- 8 Functional ground connection as per IEC/EN 60204-1
- **6 X116**: RJ45 Ethernet connection for communication and data exchange with subsequent systems or PC
- **4 X113**: 15-pin D sub connection for touch probes (e.g., HEIDENHAIN touch probe)
- **9 X100**: Power switch and power connection

5.4 Connecting encoders



For encoders with an EnDat 2.2 interface: If the corresponding encoder input has already been assigned to an axis in the device settings, then the encoder is automatically detected upon restart, and the settings are adapted. Alternatively, you can assign the encoder input after you have connected the encoder.

- ► Comply with the pin layout
- Remove and save the dust protection cap
- ▶ Route the cables depending on the mounting variant


Further information: "Assembly of the product", Page 36

▶ Connect the encoder cables tightly to the respective connections

Further information: "Device overview", Page 43

▶ If the cable connectors include mounting screws, do not overtighten them

Pin layout of X1, X2, X3



Pin layout of X21, X22, X23

TTL								
5 4 3 0 0 8 9 8 0 0	3 2 1 7 6							
1	2	3	4	5	6	7	8	9
/	U _{a1}	$\overline{U_{a1}}$	U _{a2}	$\overline{U_{a2}}$	0 V	Up	$\overline{U_{a0}}$	U _{a0}

5.5 Connecting touch probes



The following touch probes can be connected to the unit:

- HEIDENHAIN TS 248 touch probe
- HEIDENHAIN KT 130 edge finder
- Renishaw touch trigger probe

Further information: "Items supplied and accessories", Page 30

- Comply with the pin layout
- Remove and save the dust protection cap
- ▶ Route the cables depending on the mounting variant

Further information: "Assembly of the product", Page 36

Connect the touch probe firmly

Further information: "Device overview", Page 43

▶ If the cable connectors include mounting screws, do not overtighten them


Pin layout of X113

8 7 6 0 0 0 15 14 1	5 4 3 2 0 0 0 0 3 12 11 10 0 0 0						
1	2	3	4	5	6	7	8
LED+	B 5 V	B 12 V	Dout 0	DC 12 V	DC 5 V	Din 0	GND
9	10	11	12	13	14	15	
Din 1	Din 2	TP	GND	TP	Din 3	LED-	


B - Probe signals, readiness

TP - Touch Probe, normally closed


Digital inputs:



Digital outputs:



Touch probe:



5.6 Wiring switching inputs and outputs



Depending on the peripherals to be connected, the connection work may need to be carried out by an electrical specialist.

Example: Safety Extra Low Voltage (SELV) exceeded **Further information:** "Personnel qualification", Page 25



The product fulfills the requirements of standard IEC 61010-1 only if the power to the peripheral devices is supplied from a secondary circuit with current limitation as per IEC 61010-1^{3rd Ed.}, Section 9.4 or with power limitation as per IEC 60950-1^{2nd Ed.}, Section 2.5 or from a Class 2 secondary circuit as specified in UL1310.

In place of IEC 61010-1^{3rd Ed.}, Section 9.4, the corresponding sections of standards DIN EN 61010-1, EN 61010-1, UL 61010-1 and CAN/CSA-C22.2 No. 61010-1 can be used, and, in place of IEC 60950-1^{2nd Ed.}, Section 2.5, the corresponding sections of standards DIN EN 60950-1, EN 60950-1, UL 60950-1, CAN/CSA-C22.2 No. 60950-1 can be applied.

- ▶ Wire switching inputs and outputs in accordance with the following pin layout
- Remove and save the dust protection cap
- Route the cables depending on the mounting variant

Further information: "Assembly of the product", Page 36

▶ Connect the connecting cables of the peripherals tightly to their connectors

Further information: "Device overview", Page 43

▶ If the cable connectors include mounting screws, do not overtighten them



The digital or analog inputs and outputs must be assigned in the device settings of the respective switching function.


Pin layout of X113

8 7 6 0 0 0 15 14 1	5 4 3 2 0 0 0 0 3 12 11 10 0 0 0	0					
1	2	3	4	5	6	7	8
LED+	B 5 V	B 12 V	Dout 0	DC 12 V	DC 5 V	Din 0	GND
9	10	11	12	13	14	15	
Din 1	Din 2	TP	GND	TP	Din 3	LED-	


B - Probe signals, readiness

TP - Touch Probe, normally closed


Digital inputs:



Digital outputs:



Touch probe:



5.7 Connecting input devices


- Comply with the pin layout
- Remove and save the dust protection cap
- ▶ Route the cables based on the mounting variant

Further information: "Assembly of the product", Page 36

► Connect USB mouse or USB keyboard to USB Type-A port (X32). Make sure the USB cable connector is fully inserted

Further information: "Device overview", Page 43

Pin layout of X32,



5.8 Connecting a network peripheral

- Comply with the pin layout
- Remove and save the dust protection cap
- ▶ Route the cables depending on the mounting variant

Further information: "Assembly of the product", Page 36

Connect the network peripheral to Ethernet port X116 using a standard CAT.5 cable. The cable connector must firmly engage in the port

Further information: "Device overview", Page 43

Pin layout of X116

12345678							
1	2	3	4	5	6	7	8
D1+ (TX+)	D1- (TX-)	D2+ (RX+)	D3+	D3-	D2- (RX-)	D4+	D4-

5.9 Connecting the line voltage

A WARNING

Risk of electric shock!

Improper grounding of electrical devices may result in serious personal injury or death by electric shock.

- Always use 3-wire power cables
- ► Make sure the ground wire is correctly connected to the ground of the building's electrical installations

A WARNING


Fire hazard due to wrong power cable!

Use of a power cable that does not meet the requirements of the mounting location may cause a fire hazard.

- ▶ Use only a power cable that meets at least the national requirements of the respective country in which the product is mounted
- Comply with the pin layout
- Connect the power connection to a 3-wire grounded power outlet using a power cable that meets requirements

Further information: "Device overview", Page 43

Pin layout X100



6

Basic operation

6.1 Overview

This chapter describes the user interface, operating elements, and basic functions of the product.

6.2 Using the touchscreen and input devices

6.2.1 Touchscreen and input devices

The operating elements on the user interface of the unit are operated via a touchscreen or a connected USB mouse.

To enter data, you can use the screen keyboard of the touchscreen or a connected USB keyboard.

NOTICE

Malfunctions of the touchscreen caused by humidity or contact with water!

Humidity or water can impair the proper functioning of the touchscreen.

Protect the touchscreen from humidity or contact with water Further information: "Product data", Page 244

6.2.2 Gestures and mouse actions

To activate, switch or move the operating elements of the user interface, you can use the unit's touchscreen or a mouse. Gestures are used to operate the touchscreen and the mouse.



The gestures for operating the touchscreen may differ from the gestures for operating the mouse.

If the gestures for operating the touchscreen differ from those for operating the mouse, then these instructions describe both operating options as alternative actions.

The alternative actions for operating the touchscreen or the mouse are identified by the following symbols:



Operation using the touchscreen



Operation using the mouse

The following overview describes the different gestures for operating the touchscreen or the mouse:

Tapping



Means touching the screen briefly with your fingertip



Means pressing the left mouse button once

The actions initiated by tapping include



- Selection of menus, features, or parameters
- Entering characters with the screen keyboard
- Closing dialogs
- Displaying and hiding the main menu in the Measure menu
- Displaying and hiding the function bar in the Measure menu

Holding (long press)



Means touching the screen and holding your finger(s) on it for a few seconds



Means pressing the left mouse button once and holding it down

The actions initiated by holding are



 Quickly changing the values in input fields with plus and minus buttons

Dragging



Is a combination of long press and then swipe, moving a finger over the touchscreen when at least the starting point of motion is defined



Means pressing the left mouse button once and holding it down while moving the mouse; at least the starting point of the motion is defined

The actions initiated by dragging include



Scrolling through lists and texts

Swiping



A flowing movement of a finger across the touchscreen without a defined starting and end point



Single pressing and holding down of the left mouse button while simultaneously moving the mouse; the starting point and end point of the movement are not clearly defined

The actions initiated by swiping include

Changes views



6.3 General operating elements and functions

The operating elements described below are available for configuration and operating the product via the touchscreen or input devices.

Screen keyboard

With the screen keyboard, you can enter text into the input fields of the user interface. Depending on the input field, a numeric or alphanumeric screen keyboard is shown.



Figure 11: Screen keyboard

- ► To enter values, tap an input field
- > The input field is highlighted
- > The screen keyboard is displayed
- ► Enter text or numbers
- > The correctness of the entry in the input field is shown with a green check mark, if applicable
- > If the entry is incomplete or incorrect, a red exclamation mark is displayed. In this case, the entry cannot be completed
- ► To apply the values, confirm the entry with **RET**
- > The values are displayed
- > The screen keyboard disappears

Input fields with plus and minus buttons

To adjust a numerical value, use the + (plus) and - (minus) buttons to the left and right of the numerical value.



- ▶ Tap + or until the desired value is displayed
- Long-press + or to scroll through the values more quickly
- > The selected value is displayed

Toggle switch

Use the toggle switch to switch between functions.



- ► Tap the desired function
- > The active function is shown in green
- > The inactive function is shown in light gray

Slide switch

With the slide switch, you can activate or deactivate a function.



- Drag the slide switch to the desired position or
- Tap the slide switch



Slider

Use the slider (horizontal or vertical) to continuously adjust values.



- ▶ Drag the slider to the desired position
- > The selected value is displayed graphically or in percent

Drop-down list

Buttons that open drop-down lists are indicated by a triangle pointing down.



- ▶ Tap the button
- > The drop-down list opens
- > The active entry is highlighted in green
- ► Tap the desired entry
- > The selected entry is applied

Undo

With this button, you can undo the last action.

Processes that have already been concluded cannot be undone.



- ► Tap **Undo**
- > The last action is undone

Add



- ► To add a feature, tap Add
- > The new feature is added

Close



Tap Close to close a dialog

Confirm



► Tap **Confirm** to conclude an activity

Back



► Tap **Back** to return to the higher level in the menu structure

6.4 GAGE-CHEK 2000 – switch-on and switch-off

6.4.1 Switching on the GAGE-CHEK 2000



Before using the product, you need to perform the commissioning and setup steps. Depending on the purpose of use, you may have to configure additional setup parameters.

Further information: "Commissioning", Page 77

- ► Turn the power switch on The power switch is located on the rear side of the product
- > The unit powers up. This can take a moment
- > If automatic user login is active and the last user who logged in was of the **Operator** type, the user interface opens with the **Measure** menu
- > If automatic user login is not active, the **User login** menu is displayed **Further information:** "User login and logout", Page 57

6.4.2 Activating and deactivating the energy saving mode

If you will not be using the unit for a while, you should activate the energy-saving mode. This switches the unit to an inactive state without interrupting the power supply. The screen is switched off in this state.

Activating energy-saving mode



► Tap **Switch off** in the main menu



- ► Tap Energy-saving mode
- > The screen switches off

Deactivating energy-saving mode



- ► Tap anywhere on the touchscreen
- > An arrow appears at the bottom of the screen
- Drag the arrow up
- The screen is switched on and shows the user interface last displayed

6.4.3 Switching off the GAGE-CHEK 2000

NOTICE

Damage to the operating system!

Disconnecting the power source while the product is on can damage the operating system of the product.

- ▶ Use the **Switch-off** menu to shut down the product
- ▶ Do not disconnect the power source while the product is on
- ▶ Do not turn the power switch off until the product has shut down



► Tap **Switch off** in the main menu



- ► Tap Shut down
- > The operating system shuts down
- ► Wait until the following message appears on the screen: You can switch off the device now.
- ► Turn the power switch off

6.5 User login and logout

In the **User login** menu, you can log in and out of the product as a user. Only one user can be logged in to the product at a time. The logged-in user is displayed. Before a new user can log in, the logged-in user has to log out.



The product provides various authorization levels that grant the user full or restricted access to management and operation functionality.

6.5.1 User login



- ► Tap **User login** in the main menu
- ▶ Select the user in the drop-down list
- ► Tap the **Password** input field
- ▶ Enter the user's password

User	Default password	Target group
OEM	oem	Commissioner, machine tool builder
Setup	setup	Setup engineer, system configurer
Operator	operator	Operator



If the password does not match the default password, ask a **Setup** user or **OEM** user for the assigned password.

If the password is no longer known, contact a HEIDENHAIN service agency.

- ► Confirm entry with **RET**
- Ð
- Tap Log in
- > The user is logged in and the Measure menu is displayed

Further information: "Target groups according to user types", Page 19

6.5.2 User logout



► Tap **User login** in the main menu



- ▶ Tap Log out
- > The user is logged out
- All functions of the main menu are inactive, except for Switch off
- > The product can only be used again after a user has logged in

6.6 Setting the language

The user interface language is English. You can change to another language, if desired.



► Tap **Settings** in the main menu



- Tap User
- > The logged-in user is indicated by a check mark
- ► Select the logged-in user
- > The language selected for the user is indicated by a national flag in the **Language** drop-down list
- Select the flag for the desired language from the Language drop-down list
- > The user interface is displayed in the selected language

6.7 Performing the reference mark search after startup



If the reference mark search after unit start is active, then all of the unit's functions will be disabled until the reference mark search has been successfully completed.

Further information: "Reference marks (Encoder)", Page 210



The reference mark search does not need to be performed for serial encoders with EnDat interface, because the axes are automatically homed.

If the reference mark search is active on the unit, then a wizard will ask you to traverse the reference marks of the axes.

- ▶ After logging in, follow the instructions of the wizard
- > The Reference symbol stops blinking upon successful completion of the reference mark search

Further information: "Operating elements of the position display", Page 66 **Further information:** "Activating the reference mark search", Page 116

6.8 User interface



The unit is available in different versions, which are variously equipped. The user interface and available functions may vary depending on the version.

6.8.1 User interface after switch-on

Factory default user interface

The figure shows the user interface in the product's factory default setting. This user interface will also be displayed after the product has been reset to its factory default setting.




Figure 12: The user interface in the product's factory default setting

User interface after start-up

If automatic user login is activated, and the last user who logged in was of the **Operator** type, then the product displays the **Measure** menu with the workspace and the function bar after starting up.

Further information: "Measure menu", Page 62

If automatic user login is not activated, then the product opens the **User login** menu.

Further information: "User login menu", Page 64

6.8.2 Main menu of the user interface



Figure 13: User interface

- 1 Message display area, displays the time and the number of unclosed messages
- 2 Main menu with operating elements

Main menu operating elements

Operating element	Function				
Δ 3	Message				
$\Delta 3$	Display of an overview of all messages as well as the number of messages that have not been closed				
	Further information: "Messages", Page 73				
	Measure				
	Positioning and measurement of minimum, maximum, and range; perform relative measurements				
	Further information: "Measure menu", Page 62				
	File management				
	Management of the files that are available on the product				
	Further information : "File management menu", Page 63				
	User login				
\bigcap	Login and logout of the user				
	Further information: "User login menu", Page 64				
	If a user with additional permissions (Setup or OEM user type) is logged in, then the gear symbols appears.				
£~~	Settings				
(0)	Settings of the product, such as setting up users, configuring sensors, or updating the firmware				
	Further information: "Settings menu ", Page 65				

Operating element	Function
(1)	Switch-off
	Shutdown of the operating system or activation of power- saving mode
	Further information: "Switch-off menu", Page 66

6.8.3 Measure menu

Calling up



- ► Tap **Measure** in the main menu
- > The user interface for measuring and positioning is displayed

Short description




Figure 14: **Measure** menu

- 1 The workspace shows the current position of the measuring plate
- 2 The function bar provides the quick access menu and the function elements

6.8.4 File management menu

Calling up



- ► Tap **File management** in the main menu
- > The file management user interface is displayed

Short description




Figure 15: File management menu

- 1 List of available storage locations
- **2** List of folders in the selected storage location

The **File management** menu shows an overview of the files stored in the product's memory.

Any connected USB mass storage devices (FAT32 format) or available network drives are shown in the list of storage locations. The USB mass storage devices and the network drives are displayed with their name or drive designation.

Further information: "File management", Page 177

6.8.5 User login menu

Calling up



- ► Tap **User login** in the main menu
- > The user interface for user login and logout is displayed

Short description




Figure 16: User login menu

- 1 Display of the logged-in user
- 2 User login

The **User login** menu shows the logged-in user in the column on the left. The login of a new user is displayed in the right-hand column.

To log in another user, the logged-in user must first log out.

Further information: "User login and logout", Page 57

6.8.6 Settings menu

Calling up



- ► Tap **Settings** in the main menu
- > The user interface for the product settings is displayed

Short description




Figure 17: **Settings** menu

- **1** List of setting options
- **2** List of setting parameters

The **Settings** menu shows all of the options for configuring the product. With the setting parameters, you can adapt the product to on-site requirements.

Further information: "Settings", Page 185



The product provides various authorization levels that grant the user full or restricted access to management and operation functionality.

6.8.7 Switch-off menu

Calling up



- ► Tap **Switch off** in the main menu
- > The operating elements for shutting down the operating system, for activating the energy-saving mode and for activating the cleaning mode are displayed

Short description

The **Switch off** menu provides the following options:

Operating element	Function
	Shut down
U	Shuts down the operating system
[3]	Energy saving mode
3	Switches the screen off and puts the operating system into energy-saving mode
	Cleaning mode
	Switches the screen off; the operating system continues unchanged

Further information: "GAGE-CHEK 2000 – switch-on and switch-off", Page 56

Further information: "Cleaning the screen", Page 224

6.9 Position display

The unit's position display shows the axis positions and additional information about the configured axes (if applicable).

6.9.1 Operating elements of the position display

Symbol	Meaning
V	Axis key
	Axis key functions:
	Tapping the axis key: opens the input field for position value
	 Holding down the axis key: sets the current position as zero point
R	Reference mark search performed successfully
Ø	Reference mark search not performed or no reference mark detected
<u></u>	Minimum : Lowest measured value (if the MinMax function is active)

Symbol	Meaning
$\overline{\uparrow}$	Maximum : Highest measured value (if the MinMax function is active)
<u> </u>	Range: Difference between the maximum and minimum (if the MinMax function is active)
Ø	Position value is equivalent to the diameter (when D/R function activated)

6.10 Customizing the workspace

In the **Measure** menu, you can enlarge the workspace by hiding the main menu or the function bar.

Calling up



- ► Tap **Measure** in the main menu
- > The user interface for measuring and positioning appears

6.10.1 Hiding and showing the main menu



- ► Tap the **tab**
- > The main menu is hidden
- > The arrow changes direction
- To show the main menu, tap the tab again

6.10.2 Hiding or displaying the function bar



- ► Tap the **tab**
- > The function bar is hidden
- > The arrow changes direction
- To show the function bar, tap the tab again

6.10.3 Scrolling the function bar

The function bar becomes scrollable if it has more function elements than can be displayed at one time. Once you have assigned a function to the lowest empty field, an empty field will be added to the function bar and it becomes scrollable.



- Swipe up or down on the function bar
- > The functions are scrolled up or down

6.10.4 Moving functions on the function bar

You can move the functions on the function bar by drag-and-drop as needed.

- ▶ Hold a function on the function bar
- > The drag-and-drop mode is activated. The function bar is displayed dark
- ← 💮 →
- ▶ Touch a function and drag it to the desired location
- > The function is displayed in green
- ▶ To end the drag-and-drop mode, tap a function
- > The function bar is displayed bright


6.11 Using the function bar

6.11.1 Operating elements of the function bar

The function bar provides the following areas and operating elements:

Operating element

Function



Quick access menu

The quick access menu displays the current settings:

- Unit for linear values (Millimeters or Inch)
- Unit for angular values (Radian, Decimal degrees, or Deg-Min-Sec)
- ► To adjust the settings of the quick access menu, tap the quick access menu

Further information: "Adjusting settings in the quick access menu", Page 72

6.11.2 Function elements

Function elements are operating elements that you can add to the function bar and configure individually.

The following function elements are available:

Basic functions

Function element	Short description
	Presets
- 	Displays the current preset; tapping opens the preset table
'	Further information: "Activating the preset", Page 164
	Calculator
	Tapping opens a calculator with basic mathematical functions; the last result is shown in the calculator and on the function bar
	Reference mark search (REF)
ויייןייין	Tapping starts the reference mark search

Functions for measurements

Function element	Short description				
П	Part				
#	Groups all relevant functions; tapping hides all functions that are irrelevant to the measurement				
· ·	Mastering				
	Saves the measured values of a reference part as master or adopts the position values of the position display as master; corresponding axes can be selected				
	Further information: "Configuring the Mastering function", Page 139				

Function element	Short description
	dial gage
	Displays the nominal values, warning thresholds, and tolerance limits via a dial gage; tapping opens the views of the dial gage function
	Further information: "Configure the Dial gage function", Page 139
f(x)	MinMax
	Acquires the minimum, maximum, and range; tapping starts the acquisition of measured values according to the configuration
	Further information: "Acquiring the minimum, maximum, and range", Page 169
	Relative
	Tapping activates Relative measurement ; the zeroing of axes or the overwriting of a position value has no effect on the selected preset when the Relative function is activated
	Further information: "Performing a relative measurement", Page 171
\varnothing	D/R
	Displays the position values of radial axes; tapping switches from radius to diameter; the product displays the doubled position value
	Further information: "Displaying the diameter", Page 170
F	and a large and and

Functions for measured value output

Function element	Short description
	Manual output of measured values
	Sends the measured values to a computer; tapping starts the data transfer according to the configuration
	Further information: "Sending measured values to a computer", Page 174
	Measured value output triggered by touch probe
	Sends the measured values to a computer; tapping activates the automatic output of measured values according to the configuration; the data is transferred when the stylus is deflected
	Further information: "Sending measured values to a computer", Page 174
$ ightharpoonup^{C}$	Continuous output of measured values
	Sends the measured values to a computer; tapping activates the automatic output of measured values according to the configuration; the data is transferred continuously at intervals of approx. 200 ms
	Further information: "Sending measured values to a computer", Page 174

Functions for probing

Function element	Short description
:.*.:	Edge probing (probing)
	Tapping starts the wizard for probing an object of measurement
	Further information: "Measuring with probing functions", Page 167
	Determining the center line (probing)
	Tapping starts the wizard for probing an object of measurement
	Further information: "Measuring with probing functions", Page 167
- × ×	Determining the circle center (probing)
	Tapping starts the wizard for probing an object of measurement
	Further information: "Measuring with probing functions", Page 167

Adding a function element to the function bar


- Drag an empty function bar field to the left and into the workspace
- > A dialog box with all of the available function elements opens
- ► Tap the desired function element



- ► Tap Close
- > The function element is now available

▶ Drag the function element to the right

Removing a function element from the function bar





> The function element is removed

Saving the configuration of function elements



The function elements **dial gage**, **Mastering**, **Measured value output**, and **MinMax** allow you to save your configuration and open a configuration that has been saved.



- Drag the function element to the right
- Tap Save
- > The Save configuration dialog box appears
- ▶ Select the folder in which the configuration should be saved
- Specify a name for the XMG file
- Confirm entry with RET
- ▶ Tap Save
- > The file was saved



You can export or import saved configurations from or to your device via a USB mass storage product.

Further information: "Exporting files", Page 182 Further information: "Importing files", Page 183

Opening the configuration of function elements



- Drag the function element to the right
- Tap Open
- > The Open configuration dialog is opened
- Navigate to the folder in which the file is saved
- ► Tap the desired XMG file
- ► Tap **Open**
- > The file is opened

6.11.3 Adjusting settings in the quick access menu

In the quick access menu, you can adjust the following settings:

- Unit for linear values (Millimeters or Inch)
- Unit for angular values (Radian, Decimal degrees, or Deg-Min-Sec)



The available settings depend on the configuration of the product and the enabled software options.

Setting the units of measure

Before you start measuring, you need to set the desired units of measure in the quick access menu.



- ▶ Tap the **quick access menu** on the function bar
- Select the desired Unit for linear values
- Select the desired Unit for angular values
- ► To close the quick access menu, tap Close
- > The selected units are displayed in the quick access menu

6.12 Messages and audio feedback

6.12.1 Messages




Figure 18: Display of messages in the workspace

- Message display area; displays the time and the number of unclosed messages
- 2 Message list

The messages that appear at the top of the workspace are triggered by, for example, operator errors or uncompleted processes.

The messages are displayed upon occurrence of the message cause or via tapping on the **Messages** display area at the top left of the screen.

Viewing messages



- Tap Messages
- > The message list opens

Resizing the display area



- ► To enlarge the message display area, drag the handle down
- To make the message display area smaller, drag the handle
- To close the display area, drag the **handle** up out of the screen
- > The number of unclosed messages is indicated in **Messages**

Closing messages

Depending on the content of the messages, you can close messages by means of the following operating elements:



- ► To close an informational message, tap **Close**
- > The message disappears

or

- ► To close a message that potentially has an effect on the application, tap **OK**
- If applicable, the message will now be taken into account by the application
- > The message disappears

6.12.2 Wizard




Figure 19: Display of messages in the wizards

1 Wizard (example)

The wizard assists you in carrying out action steps, programs, or teach processes. You can move the wizard within the workspace .

The following operating elements of the wizard are shown based on the action step or process.



To return to the last action step or to repeat the process, tap Undo



- ► To confirm the displayed action step, tap **Confirm**
- > The wizard proceeds to the next step or completes the process



► Tap Close to close the wizard

6.12.3 Audio feedback

The product can provide audio feedback to indicate user actions, completed processes or malfunctions.

The available sounds are grouped into categories. The sounds differ within a category.

You can define the audio feedback settings in the **Settings** menu.

Further information: "Sounds", Page 190

Commissioning

7.1 Overview

This chapter contains all the information necessary for commissioning the product.

During commissioning, the machine manufacturer's commissioning engineer (**OEM**) configures the product for use on the specific measuring machine.

The settings can be reset to the factory defaults.

Further information: "Reset", Page 219



Make sure that you have read and understood the "Basic operation" chapter before carrying out the actions described below.

Further information: "Basic operation", Page 51



The following steps must be performed only by qualified personnel.

Further information: "Personnel qualification", Page 25

7.2 Logging in for commissioning

7.2.1 User login

To commission the product, the **OEM** user must log in.




- ► Tap **User login** in the main menu
- ▶ If required, log out the user who is currently logged in
- ► Select the **OEM** user
- ► Tap the **Password** input field
- ► Enter the password "oem"



If the password does not match the default password, ask a **Setup** user or **OEM** user for the assigned password.

If the password is no longer known, contact a HEIDENHAIN service agency.





- ► Tap Log in
- > The user is logged in
- > The product opens the Measure menu

7.2.2 Performing the reference mark search after startup



If the reference mark search after unit start is active, then all of the unit's functions will be disabled until the reference mark search has been successfully completed.

Further information: "Reference marks (Encoder)", Page 210



The reference mark search does not need to be performed for serial encoders with EnDat interface, because the axes are automatically homed.

If the reference mark search is active on the unit, then a wizard will ask you to traverse the reference marks of the axes.

- After logging in, follow the instructions of the wizard
- > The Reference symbol stops blinking upon successful completion of the reference mark search

Further information: "Operating elements of the position display", Page 66 Further information: "Activating the reference mark search", Page 116

7.2.3 Setting the language

The user interface language is English. You can change to another language, if desired.



► Tap **Settings** in the main menu



- Tap User
- > The logged-in user is indicated by a check mark
- Select the logged-in user
- > The language selected for the user is indicated by a national flag in the Language drop-down list
- ▶ Select the flag for the desired language from the Language drop-down list
- > The user interface is displayed in the selected language

7.2.4 Changing the password

You must change the password to prevent unauthorized configuration.

The password is confidential and must not be disclosed to any other person.



► Tap **Settings** in the main menu



- Tap User
- > The logged-in user is indicated by a check mark
- Select the logged-in user
- ► Tap **Password**
- ► Enter the current password
- ► Confirm entry with **RET**
- ► Enter the new password and repeat it
- ► Confirm entry with **RET**
- ► Tap **OK**
- ► Close the message with **OK**
- > The new password is available the next time the user logs in

7.3 Steps for commissioning



The following commissioning steps build on each other.

To correctly commission the product, make sure to perform the steps in the order described here

Prerequisite: You are logged on as a user of the **OEM** type (see "Logging in for commissioning", Page 78).

Basic settings

- Activating the Software options
- Setting the date and time
- Setting the units of measure

Configuring a touch probe

Configuring a touch probe

Configuring the axes

Configuring a touch probe

For EnDat interfaces:

- Configuring axes for encoders with EnDat interface
- Performing error compensation
- Ascertaining the line count per revolution

For 1 V_{PP} or 11 μ A_{PP} interfaces:

- Activating the reference mark search
- Configuring the axes for encoders with a 1 V_{PP} or 11 µA_{PP} interface
- Performing error compensation
- Ascertaining the line count per revolution

For TTL interface:

- Activating the reference mark search
- Configuring axes for encoders with TTL interface
- Performing error compensation
- Ascertaining the output signals per revolution

Coupling axes

OEM area

- Adding documentation
- Adding a startup screen
- Configuring the unit for screenshots

Backing up data

- Back up settings
- Back up user files

NOTICE

Loss of or damage to configuration data!

If the product is disconnected from the power source while it is on, the configuration data can be lost or corrupted.

Back up the configuration data and keep the backup for recovery purposes

7.4 Basic settings

7.4.1 Activating the Software options

Additional **Software options** can be enabled on the product via a **License key**.



You can view the enabled **Software options** on the overview page.

Further information: "Checking the Software options", Page 83

Requesting license key

You can request a license key by using the following procedure:

- Reading out device information for the license key request
- Creating a license key request

Reading out device information for the license key request



► Tap **Settings** in the main menu



- ► Tap **General**
- ► Tap **Device information**
- > An overview of the device information appears
- > The product designation, ID number, serial number, and firmware version are displayed
- Contact a HEIDENHAIN service agency and submit the displayed device information in order to request a license key for the product
- > The license key and the license file are generated and sent by e-mail

Creating a license key request



► Tap **Settings** in the main menu



- ▶ Tap Service
- Tap Software options
- To request a software option that is available for a fee, tap Request options
- ► To request a free trial option, tap **Request trial options**
- ▶ To select the desired software option, tap its check mark



- ► To deselect an entry, tap the check mark for the respective software option
- ► Tap Creating a request
- ► In the dialog, select the storage location in which you want to save the license key request
- ▶ Enter a suitable file name
- Confirm entry with RET
- Tap Save as
- > The license key request is created and saved in the selected folder
- ▶ If the license key request is stored on the unit, move the file to a connected USB mass storage device (FAT32 format) or to the network drive
 - Further information: "Moving a file", Page 180
- Contact a HEIDENHAIN service agency and submit the file you created in order to request a license key for the product
- The license key and the license file are generated and sent by e-mail

Activating a license key

You can activate a license key by

- Reading the license key from the provided license file into the product
- Entering the license key manually into the product

Uploading license key from license file



► Tap **Settings** in the main menu



- ► Tap **Service**
- Open in succession:
 - Software options
 - Activate options
- ► Tap Read license file
- Select the license file in the file system, on the USB mass storage device or on the network drive
- ► Confirm your selection with **Select**
- ► Tap **OK**
- > The license key is activated
- ► Tap **OK**
- > You may need to restart the product, depending on the software option
- Confirm the restart with OK
- > The activated software option is available

Entering license key manually



► Tap **Settings** in the main menu



- ▶ Tap Service
- Open in succession:
 - Software options
 - Activate options
- ▶ Enter the license key into the License key input field
- Confirm the entry with RET
- ▶ Tap **OK**
- > The license key is activated
- Tap **OK**
- You may need to restart the product, depending on the software option
- Confirm the restart with OK
- > The activated software option is available

Checking the Software options

On the overview page, you can check which **Software options** are enabled for the product.



► Tap **Settings** in the main menu



- ▶ Tap Service
- ► Open in succession:
 - Software options
 - Overview
- > A list of enabled **Software options** is displayed

7.4.2 Setting the date and time



► Tap **Settings** in the main menu



- ► Tap **General**
- ► Tap Date and time
- The set values are displayed in the following format: Year, month, day, hour, minute
- ➤ To set the date and time in the middle line, drag the columns up or down
- ► Tap **Set** to confirm
- ▶ Select the desired format from the **Date format** list:
 - MM-DD-YYYY: Display as month, day, year
 - DD-MM-YYYY: Display as day, month, year
 - YYYY-MM-DD: Display as year, month, day

Further information: "Date and time", Page 191

7.4.3 Setting the units of measure

You can set various parameters to define the units of measure, rounding methods and decimal places.



► Tap **Settings** in the main menu



- ▶ Tap General
- Tap Units
- ► To set a unit of measure, tap the corresponding drop-down list and select the unit
- To set the rounding method, tap the corresponding dropdown list and select the rounding method
- ► To set the number of decimal places displayed, tap or +

Further information: "Units", Page 191

7.5 Configuring a touch probe

You can use a touch probe to probe points on a workpiece. The stylus of the touch probe can be additionally fitted with a ruby ball tip. In order to use a touch probe, you need to configure the relevant parameters.



► Tap **Settings** in the main menu



- Tap **Sensors**
- ▶ Tap Touch probe
- Use the **ON/OFF** sliding switch to activate or deactivate the touch probe
- Enter the length difference of the touch probe in the Length input field
- Confirm the entry with **RET**
- Enter the stylus diameter of the touch probe in the **Diameter** input field
- Confirm the entry with RET



Use the touch-probe triggered output of measured values to automatically send the measured values to a computer when the stylus is deflected.

Further information: "Configuring the measured value output", Page 145

7.6 Configuring the axes

The procedure varies depending on the interface type of the connected encoder:

Encoders with EnDat interface: The encoder applies the parameters automatically

Further information: "Configuring axes for encoders with EnDat interface", Page 90

• Encoders with 1 V_{pp} or 11 μA_{pp} or TTL interface: The parameters must be configured manually

For the parameters of HEIDENHAIN encoders that are typically connected to the product, refer to the overview of typical encoders.

Further information: "Overview of typical encoders", Page 87

7.6.1 Configuring Alias assignment for axis names

Depending on your application, you can assign axis names yourself. You can assign new axis names for the following axes: C1, C2, and C3. The axis name is a two-digit numerical value, a two-character combination of letters, or a two-character combination of a numerical value and a letter.


Further information: "Alias assignment for axis names", Page 204



► Tap **Settings** in the main menu



- Tap Axes
- Tap General settings
- ► Tap Alias assignment for axis names
- ▶ Enter a name in the input fields
 - Setting range: 00 ... 99 and aA ... xX
- > The names are available in the axis configuration. They can be assigned to the respective encoder input





A

The **Standard** and **Steinwald** data formats transfer measured values only when the following axis names are assigned: X, Y, Z, Q, R, D, L, W, A, C, f, Lx, Ly, or Lz.

The minimum, maximum, and range values are transferred only if the axis names X, Y, or Q are assigned.



If you want to use specific axis names and transfer measured values to a computer, you must modify, for example, **MyFormat1.xml** or another format file you created by adding the axis names that you assigned.

Further information: "Creating your own data format", Page 151

7.6.2 Overview of typical encoders

The following overview lists the parameters of the HEIDENHAIN encoders that are typically connected to the product.



When connecting other encoders, refer to the encoder's documentation for the required parameters.

Linear encoders

Encoder series	Interface	Signal period	Reference mark	Maximum traverse path	
LS 328C	TTL	20 µ m	Coded / 1000	20 mm	
AK LIDA 27	TTL	20 µ m	One	-	
		4 µm			
		2 µm			
AK LIDA 47	TTL	4 µm	One	-	
		4 µm	Coded / 1000*)	20 mm	
		2 µm	One	-	
		2 µm	Coded / 1000*)	20 mm	
LS 388C	1 V _{PP}	20 µ m	Coded / 1000	20 mm	
AK LIDA 28	1 V _{PP}	200 µm	One	-	
AK LIDA 48	1 V _{PP}	20 µ m	One	-	
AK LIF 48	1 V _{PP}	4 µm	m One -		

^{*) &}quot;Coded / 1000" only in conjunction with the LIDA 4x3C scale

Examples of absolute encoders that are typically used

Encoder series	Interface	Measuring step
AK LIC 411	EnDat 2.2	1 nm
		5 nm
		10 nm
LIC 211 scanning head	EnDat 2.2	50 nm
		100 nm

Length gauges

Length gauge series	Interface	Signal period	Reference mark	Maximum traverse path
CT 250x	11 µ A _{PP}	2 µ m	One	25 mm
CT 600x	11 µA _{PP}	2 µm	One	60 mm
MT 1271	TTL	0.4 μm, 0.2 μm *)	One	12 mm
MT 128x	1 V _{PP}	2 µ	One	12 mm
MT 2571	TTL	0.4 μm, 0.2 μm *)	One	25 mm
MT 258x	1 V _{PP}	2 µm	One	25 mm
MT 60x	11 µA _{PP}	10 µm	One	60 mm
MT 101x	11 µ A _{PP}	10 µm	One	100 mm
ST 127x	TTL	4 μm, 2 μm *)	One	12 mm
ST 128x	1 V _{PP}	20 µm	One	12 mm
ST 307x	TTL	4 μm, 2 μm *)	One	30 mm
ST 308x	1 V _{PP}	20 µm	One	30 mm

 $^{^{*)}~~0.2~\}mu m$ or 2 μm with 10-fold evaluation 0.4 μm or 4 μm with 5-fold evaluation

Length gauge series	Interface	Measuring step	Maximum traverse path
AT 121x	EnDat 2.2	23 nm	12 mm
AT 301x	EnDat 2.2	368 nm	30 mm

Angle encoders

Encoder series	Interface	Line count/ outputs signals per revolution	Reference mark	Nominal increment
RON 225	TTLx2	18000	One	-
RON 285	1 V _{PP}	18000	One	-
RON 285C	1 V _{PP}	18000	Coded	20°
RON 785	1 V _{PP}	18000	One	-
RON 785C	1 V _{PP}	18000	Coded	20°
RON 786	1 V _{PP}	18000	One	-
RON 786C	1 V _{PP}	18000	Coded	20°
ROD 220	TTLx2	18000	One	-
ROD 280	1 V _{PP}	18000	One	-
ROD 280C	1 V _{PP}	18000	Coded	20°



The formulae below enable you to calculate the nominal increment of the distance-coded reference marks with angle encoders:

Nominal increment = $360^{\circ} \div \text{number of reference marks} \times 2$

Nominal increment = $(360^{\circ} \times \text{nominal increment in signal periods}) \div \text{line count}$

7.6.3 Configuring axes for encoders with EnDat interface

If the corresponding encoder input has already been assigned to an axis, a connected encoder with EnDat interface is automatically detected upon restart, and the settings are adapted. Alternatively, you can assign the encoder input after you have connected the encoder.

Prerequisite: An encoder with EnDat interface is connected to the product.



The configuration procedure is the same for each axis. The procedure will now be explained using one axis as an example.



► Tap **Settings** in the main menu



- Tap Axes
- ▶ Tap the axis name or **Not defined**, if applicable
- If applicable, select the axis name for the axis in the Axis name drop-down list
- ▶ Tap Encoder
- Select the connection for the corresponding encoder from the **Encoder input** drop-down list:
 - X1
 - X2
 - X3
- > The available encoder information is transmitted to the product
- > The settings are updated
- Select the encoder model from the Encoder model dropdown list:
 - Linear encoder
 - Angle encoder
 - Angle encoder as linear encoder
- If you selected Angle encoder as linear encoder, then enter the Mechanical ratio
- ▶ If you selected **Angle encoder**, specify the **Display mode**
- ► Tap Reference point displacement
- Use the ON/OFF slide switch to activate or deactivate Reference point displacement (calculation of the offset between the reference mark and the machine zero point)
- ▶ If activated, enter the offset value for Reference point displacement
- ► Confirm the entry with **RET**

or

- ▶ To apply the current position as the offset value, tap Apply under Current position for reference point shift
- To switch to the previous display, tap Back
- > To view the electronic ID label of the encoder, tap ID label
- In order to see the results of the encoder diagnosis, tap Diagnosis

Further information: "<Axis name> (settings of the axis)", Page 204

7.6.4 Configuring the axes for encoders with a 1 V_{PP} or 11 μA_{PP} interface



The configuration procedure is the same for each axis. The procedure will now be explained using one axis as an example.



► Tap **Settings** in the main menu



- Tap Axes
- Tap the axis name or Not defined, if applicable
- ▶ If applicable, select the axis name for the axis in the Axis name drop-down list
- ▶ Tap Encoder
- Select the connection for the corresponding encoder from the **Encoder input** drop-down list:
 - **X1**
 - X2
 - X3
- Select the type of incremental signal from the Incremental signal drop-down list:
 - 1 Vpp: Sinusoidal voltage signal
 - 11 µApp: Sinusoidal current signal
- Select the encoder model from the Encoder model dropdown list:
 - Linear encoder: Linear axis
 - Angle encoder: Rotary axis
 - Angle encoder as linear encoder: A rotary axis is displayed as a linear axis
- ▶ Depending on the selection, enter further parameters:
 - For Linear encoder, enter the Signal period (see "Linear encoders", Page 87)
 - For Angle encoder, enter the Line count (see "Angle encoders", Page 89), or determine it using a teach sequence (see "Ascertaining the line count per revolution", Page 93)
 - For an Angle encoder as linear encoder, enter the Line count and the Mechanical ratio
- ► Confirm each input with **RET**
- ► For **Angle encoder**, select the **Display mode**, if applicable
- ▶ Tap Reference marks
- Select the reference mark from the Reference mark dropdown list:
 - None: There is no reference mark
 - One: The encoder has one reference mark
 - **Coded**: The encoder has distance-coded reference marks
- If the linear encoder has coded reference marks, enter the Maximum traverse path (see "Linear encoders", Page 87)

91

- ▶ If the angle encoder has coded reference marks, enter the parameter for the **Nominal increment** (see "Angle encoders", Page 89)
- ► Confirm the entry with **RET**
- Use the ON/OFF slider to activate or deactivate the Inversion of reference mark pulses function
- Tap Reference point displacement
- ► Use the **ON/OFF** slide switch to activate or deactivate **Reference point displacement** (calculation of the offset between the reference mark and the machine zero point)
- ▶ If activated, enter the offset value for Reference point displacement
- ► Confirm the entry with **RET**
- ► To apply the current position as the offset value, tap **Apply** under **Current position for reference point shift**
- In order to switch to the previous display, tap **Back** twice
- Select the frequency of the low-pass filter for suppressing high-frequency interference signals from the Analog filter frequency drop-down list:
 - 33 kHz: Interference frequencies above 33 kHz
 - 400 kHz: Interference frequencies above 400 kHz
- Use the ON/OFF slider to activate or deactivate the Terminating resistor function



The terminating resistor is automatically deactivated for incremental signals of the current signal type (11 μ A_{PP})

- Select the type of error monitoring from the Error monitor drop-down list:
 - Off: Error monitoring not active
 - **Amplitude**: Error monitoring of the signal amplitude
 - **Frequency**: Error monitoring of the signal frequency
 - **Frequency & amplitude**: Error monitoring of the signal amplitude and signal frequency
- Select the desired counting direction from the Counting direction drop-down list:
 - Positive: The direction of traverse is in the counting direction of the encoder
 - Negative: The direction of traverse is opposite to the counting direction of the encoder

Further information: "<Axis name> (settings of the axis)", Page 204



Ascertaining the line count per revolution

For angle encoders with interfaces of the type 1 V_{PP} or 11 μA_{PP} you can use a teach sequence to ascertain the exact line count per revolution.



► Tap **Settings** in the main menu



- Tap Axes
- ▶ Tap the desired axis designation or **Not defined**, if applicable
- ▶ If applicable, select the name of the axis from the Axis name drop-down list
- Tap Encoder
- From the Encoder model drop-down list, select Angle encoder
- ► For **Display mode** select the ∞ ... ∞ option
- ► Tap **Reference marks**
- ► Select one of the following options from the **Reference mark** drop-down list:
 - None: There is no reference mark
 - One: The encoder has one reference mark
- In order to switch to the previous axis, tap **Back**
- ► To start the teach sequence, tap **Start**
- > The teach sequence is started and the wizard is displayed
- ▶ Follow the instructions of the wizard
- > The line count determined during the teach sequence is transferred to the **Line count** field



The ascertained line count remains stored if you select a different display mode after the teach sequence.

Further information: "Settings for encoders with interfaces of the type 1 V_{PP} or 11 A_{PP} ", Page 207



7.6.5 Configuring axes for encoders with TTL interface



The configuration procedure is the same for each axis. The procedure will now be explained using one axis as an example.



Tap Settings in the main menu



- Tap Axes
- Tap the axis name or Not defined, if applicable
- ▶ If applicable, select the axis name for the axis in the Axis name drop-down list
- ► Tap **Encoder**
- Select the connection for the corresponding encoder from the Encoder input drop-down list:
 - X21
 - **X22**
 - X23
- Select the encoder model from the Encoder model dropdown list:
 - Linear encoder: Linear axis
 - Angle encoder: Rotary axis
 - Angle encoder as linear encoder: A rotary axis is displayed as a linear axis
- ▶ Depending on the selection, enter further parameters:
 - For Linear encoder, enter the Signal period (see "Linear encoders", Page 87)
 - For Angle encoder, enter the Output signals per revolution (see "Angle encoders", Page 89), or determine it using a teach sequence (see "Ascertaining the output signals per revolution", Page 96)
 - For an Angle encoder as linear encoder, enter the Output signals per revolution and the Mechanical ratio
- ► Confirm each input with **RET**
- ► For **Angle encoder**, select the **Display mode**, if applicable
- Tap Reference marks
- Select the reference mark from the Reference mark dropdown list:
 - None: There is no reference mark
 - One: The encoder has one reference mark
 - **Coded**: The encoder has distance-coded reference marks
 - Reverse coded: The encoder has inverse-coded reference marks
- If the linear encoder has coded reference marks, enter the Maximum traverse path (see "Linear encoders", Page 87)
- ▶ If the angle encoder has coded reference marks, enter the parameter for the **Nominal increment** (see "Angle encoders", Page 89)
- Confirm the entry with RET

- ▶ If the encoder has coded reference marks, select the interpolation type from the **Interpolation** drop-down list:
 - None
 - 2-fold
 - 5-fold
 - 10-fold
 - 20-fold
 - 50-fold
- Use the ON/OFF slider to activate or deactivate the Inversion of reference mark pulses function
- ► Tap Reference point displacement
- Use the ON/OFF slide switch to activate or deactivate Reference point displacement (calculation of the offset between the reference mark and the machine zero point)
- If activated, enter the offset value for Reference point displacement
- ► Confirm the entry with **RET**
- ► To apply the current position as the offset value, tap **Apply** under **Current position for reference point shift**
- In order to switch to the previous display, tap **Back** twice
- ► Use the **ON/OFF** slider to activate or deactivate the **Terminating resistor** function
- Select the type of error monitoring from the Error monitor drop-down list:
 - Off: Error monitoring not active
 - **Frequency**: Error monitoring of the signal frequency
- Select the desired counting direction from the Counting direction drop-down list:
 - **Positive**: The direction of traverse is in the counting direction of the encoder
 - **Negative**: The direction of traverse is opposite to the counting direction of the encoder

Further information: "<Axis name> (settings of the axis)", Page 204



Ascertaining the output signals per revolution

For angle encoders with interfaces of the type TTL you can use a teach sequence to ascertain the exact quantity of output signals per revolution.



► Tap **Settings** in the main menu



- Tap Axes
- ▶ Tap the desired axis designation or **Not defined**, if applicable
- If applicable, select the name of the axis from the **Axis name** drop-down list
- ► Tap Encoder
- ► From the **Encoder model** drop-down list, select **Angle** encoder
- ► For **Display mode** select the ∞ ... ∞ option
- Tap Reference marks
- ► Select one of the following options from the **Reference mark** drop-down list:
 - None: There is no reference mark
 - One: The encoder has one reference mark
- In order to switch to the previous axis, tap **Back**
- To start the teach sequence, tap **Start**
- > The teach sequence is started and the wizard is displayed
- ▶ Follow the instructions of the wizard
- > The number of output signals determined during the teach sequence is transferred to the **Output signals per revolution** field



The ascertained quantity of output signals remains stored if you select a different display mode after the teach sequence.

Further information: "Settings for encoders with interfaces of the TTL type", Page 209



7.6.6 Performing error compensation

Mechanical influences such as guideway error, tilting in the end positions, mounting surface tolerances, or poor mounting (Abbe error) can cause measuring errors. With error compensation, the unit can automatically compensate for systematic measuring errors during measuring point acquisition. Through the comparison of nominal and actual values, one or more compensation factors can be defined and applied during subsequent measurements.

A distinction is made between the following methods:

Configuring error compensation for individual axes

- Linear error compensation (LEC): The compensation factor is calculated based on the specified length of a calibration standard (nominal length) and the actual distance traversed (actual length). The compensation factor is applied linearly to the entire measuring range.
- Segmented linear error compensation (SLEC): The axis is divided into multiple segments with the help of a maximum of 200 supporting points. A distinct compensation factor is defined and applied for every segment.

Configuring error compensation across axes

- Nonlinear error compensation (NLEC): By means of a maximum of a 99 supporting points, the measuring range is divided into a grid with multiple subareas. For every subarea, a distinct compensation factor is determined and applied.
- Squareness error compensation: The compensation factor is determined by comparing the nominal angle of the spatial axes with the measurement result. The compensation factor is applied to the entire measuring range.

NOTICE

Subsequent modifications to the encoder settings can result in measuring errors

If encoder settings such as the encoder input, encoder model, signal period, or reference marks are changed, previously determined compensation factors may no longer apply.

▶ If you change encoder settings, then you need to reconfigure the error compensation



For all methods, the actual error curve must be exactly measured (e.g., with the help of a comparator measuring device or calibration standard).



Linear error compensation and segmented linear error compensation cannot be combined with each other.



If you enable a reference point shift, then you need to reconfigure the error compensation. This helps you avoid measuring errors.

Configuring linear error compensation (LEC)

With linear error compensation (LEC), the product applies a compensation factor that is calculated from the specified length or angle of a reference standard (nominal length or nominal angle) and the actual traverse path (actual length and actual angle). The compensation factor is applied to the entire measuring range.



► Tap **Settings** in the main menu



- Tap Axes
- Select the axis
- Open in succession:
 - Error compensation
 - Linear error compensation (LEC)
- ► Enter the length or angle of the reference standard (nominal length or nominal angle)
- ► Confirm the entry with **RET**
- ► Enter the length or angle of the actual traverse path determined by measuring (actual length or actual angle)
- ► Confirm the entry with **RET**
- ► Activate Compensation with the ON/OFF slide switch

Further information: "Linear error compensation (LEC)", Page 215

Configuring segmented linear error compensation (SLEC)

For a segmented linear error compensation (SLEC), you divide the axis into short segments by defining up to 200 supporting points. The deviations between the actual distance traversed and the segment length in the individual segments determine the compensation values that compensate the mechanical influences acting on the axis.



If the - ∞ ... ∞ display mode is selected for the angle encoder, the error compensation of angle encoders does not affect negative values of the supporting points.



► Tap **Settings** in the main menu



- Tap Axes
- Select the axis
- ▶ Open in succession:
 - Error compensation
 - Segmented linear error compensation (SLEC)
- Use the ON/OFF slider to deactivate the Compensation function
- Tap Create table of supporting points
- ► Tap + or to set the desired **Number of supporting points** (max. 200)
- Enter the desired Spacing of the supporting points
- ► Confirm the entry with **RET**
- ► Enter a value in **Start point**
- ► Confirm the entry with **RET**
- ▶ Tap **Create** to create the table of supporting points
- > The table of supporting points is created
- > The table lists the supporting point positions (P) and the compensation values (D) of the individual segments
- ► Enter the compensation value (D) "0.0" for supporting point 0
- Confirm the entry with RET
- Enter the measured compensation value into the compensation value (D) input field for each supporting point created
- ► Confirm the entry with **RET**



- ► To switch to the previous display, tap **Back** twice
- Activate Compensation with the ON/OFF slide switch
- > The error compensation for the axis is applied

Further information: "Segmented linear error compensation (SLEC)", Page 215

Adjusting an existing table of supporting points

After a table of supporting points for segmented linear error compensation has been created, this table can then be modified as needed.



▶ Tap **Settings** in the main menu



<

- Tap Axes
- Select the axis
- ► Open in succession:
 - Error compensation
 - Segmented linear error compensation (SLEC)
- Use the ON/OFF slide switch to deactivate the Compensation function
- ► Tap Table of supporting points
- > The table lists the supporting point positions (P) and the compensation values (D) of the individual segments
- ▶ Adjust the **compensation value (D)** for the supporting points
- Confirm the entries with RET
- ► To switch to the previous display, tap **Back**
- ► Activate **Compensation** with the **ON/OFF** slide switch
- > The adjusted error compensation for the axis is applied

Further information: "Segmented linear error compensation (SLEC)", Page 215

Configuring the Nonlinear error compensation (NLEC)

For a **Nonlinear error compensation (NLEC)** the measuring range is divided into a grid of identically sized surface segments using up to 99 supporting points. For each of the surface segments, a specific compensation factor is determined by comparing nominal and actual values (the measured values) at the supporting points.

The following options are available for measuring the nominal and actual values of the supporting points:

Acquiring nominal values

- Read deviations from the calibration standard (ACF)
- Create a table of supporting points manually

Acquiring actual values

- Import the table of supporting points (TXT or XML)
- Determine the actual values using a teach sequence
- Acquire the actual values manually



The following specifications apply to import files:

- File names must not contain diacritics or special characters
- ▶ Use a point as decimal character



In the following situations, both nominal and actual values in the existing table of supporting points will be overwritten:

- If you change the number or spacing of the supporting points manually
- If you import a file that contains deviating information on the number or spacing of the supporting points

Further information: "Nonlinear error compensation (NLEC)", Page 203

Deactivating the nonlinear axis error compensation

Before you can configure the **Nonlinear error compensation (NLEC)**, you first need to deactivate it.



► Tap **Settings** in the main menu



- ► Open in succession:
 - Axes
 - General settings
 - Error compensation
 - Nonlinear error compensation (NLEC)
- ► Use the **ON/OFF** slider to deactivate the **Compensation** function
- > The table of supporting points is now released for editing

Reading deviations from the calibration standard



The manufacturer of the calibration standard usually provides you with specifications about the deviations.

Prerequisites:

An ACF file contains the nominal values; this file must match the import scheme of the product

Further information: "Creating an ACF import file", Page 102

■ Nonlinear error compensation (NLEC) is deactivated



► Tap **Settings** in the main menu



- ► Open in succession:
 - Axes
 - General settings
 - Error compensation
 - Nonlinear error compensation (NLEC)
- Tap Read deviations of calibration standard
- Navigate to the desired folder
- ► Tap the desired file (.ACF)
- ► Tap Select
- > The nominal values are imported from the file

Creating an ACF import file

To import the calibration data into the product, you must acquire these in an ACF file.

- Open a new file in the text editor of your computer
- ▶ Save the file under a unique name and the *.acf file extension
- ▶ Enter the values, separated by tab stops as shown in the schema below



The following specifications apply to import files:

- File names must not contain diacritics or special characters
- Use a point as decimal character

ACF schema

The ACF file contains the nominal values of the supporting points on the X and Y axes. The nominal values have been corrected by the deviations from the calibration standard.

The following example shows a grid of 5×5 supporting points with a spacing of 25 mm on the X axis and 20 mm on the Y axis, oriented along the X axis.

Example

Example	
MM	Χ
25.0	20.0
5	5
0.0000	0.0000
25.0012	-0.0010
50.0003	-0.0006
75.0010	0.0016
100.0021	0.0000
0.00005	20.0020
25.0013	20.0021
50.0013	20.0022
75.0005	20.0023
99.9996	20.0003
-0.00010	39.9998
24.9981	39.9979
49.9999	40.0001
75.0004	40.0021
100.0019	40.0008
0.00003	59.9992
25.0000	60.0018
50.0001	60.0003
75.0020	59.9990
100.0001	60.0001
-0.00003	80.0021
24.9979	80.0004
50.0020	79.9991
75.0001	79.9985
100.0010	80.0002

Explanation

The overview below shows the structure of the ACF import file.

Value	Explanation	Value	Explanation
MM	Millimeters (not configurable)	Χ	Alignment axis (X or Y)
25.0	Spacing of supporting points on the X axis	20.0	Spacing of supporting points on the Y axis
5	Number of supporting points on the X axis	5	Number of supporting points on the Y axis
0.0000	Nominal value of the first supporting point on the X axis	0.0000	Nominal value of the first supporting point on the Y axis
25.0012	Nominal value of the second supporting point on the X axis	-0.0010	Nominal value of the second supporting point on the Y axis



The file contains an additional row with X and Y values for each supporting point.



The supporting points can be indicated row by row or in a meandershaped sequence. The product adapts the reading direction automatically.

Row-b	y-row r	eading	direction	on	Meand	ler-shap	ed read	ding dire	ection
21	22	23	24	25	21	22	23	24	25
16	17	18	19	20	20	19	18	17	16
11	12	13	14	15	11	12	13	14	15
6	7	8	9	10	10	9	8	7	6
1	2	3	4	5	1	2	3	4	5

Creating a table of supporting points manually



► Tap **Settings** in the main menu



- ► Open in succession:
 - Axes
 - General settings
 - Error compensation
 - Nonlinear error compensation (NLEC)
- ▶ Enter the **Number of supporting points** for the first axis
- Confirm your input with RET
- ▶ Enter the **Spacing of the supporting points** for the first axis
- Confirm your input with RET
- Repeat this procedure for the second axis
- > The number and spacing of the supporting points are written to the table of supporting points
- > The existing table of supporting points is overwritten

Importing the table of supporting points

To adjust the actual values of the supporting points, you can import the following file types:

- XML: contains actual values
- TXT: contains actual values
- Extended TXT: contains deviations from the nominal values

Prerequisites:

- You have an XML or TXT file that matches the import scheme of the product
 Further information: "Creating an XML import file", Page 110
 Further information: "Creating a TXT import file", Page 106
- Nonlinear error compensation (NLEC) is deactivated



► Tap **Settings** in the main menu



- Open in succession:
 - Axes
 - General settings
 - Error compensation
 - Nonlinear error compensation (NLEC)
- ► Tap Import table of supporting points
- Navigate to the desired folder
- ► Tap the desired file (TXT or XML)
- ▶ Tap Select
- > Depending on the imported file type, the table of supporting points is adjusted as follows:
 - **XML**: The actual values are imported from the file
 - **TXT**: The actual values are imported from the file
 - Extended TXT: The actual values are corrected by the deviations



In order to keep the nominal values in the original table of supporting points, define the number and spacing in the import file in the same way as in the original table of supporting points. Otherwise, the nominal values will be overwritten by the grid specified in the import file. Any deviations from the calibration standard that have been read in before will be lost.

Creating a TXT import file

- Open a new file in the text editor of your computer
- Save the file under a unique name and add the *.txt file extension
- ▶ Enter the data, separated by tab stops according to one of the schemas below:
 - TXT schema: The file contains the actual values of the supporting points
 - Extended TXT schema: The file contains deviations from the theoretical nominal value



The following specifications apply to import files:

- File names must not contain diacritics or special characters
- Use a point as decimal character

TXT schema

The TXT file contains the actual values of the supporting points on the X and Y axes.

The following example shows a grid of 5 x 5 supporting points with a spacing of 25 mm on the X axis and 20 mm on the Y axis, oriented along the X axis.

Example

MM	Χ
25.0	20.0
5	5
0.0000	0.0000
25.0012	-0.0010
50.0003	-0.0006
75.0010	0.0016
100.0021	0.0000
0.00005	20.0020
25.0013	20.0021
50.0013	20.0022
75.0005	20.0023
99.9996	20.0003
-0.00010	39.9998
24.9981	39.9979
49.9999	40.0001
75.0004	40.0021
100.0019	40.0008
0.00003	59.9992
25.0000	60.0018
50.0001	60.0003
75.0020	59.9990
100.0001	60.0001
-0.00003	80.0021

MM	X
24.9979	80.0004
50.0020	79.9991
75.0001	79.9985
100.0010	80.0002

Explanation

The following overview explains the values that you can define individually. All values not listed here must be copied as is from the example. The values must be separated by tab stops.

Value	Explanation	Value	Explanation
MM	Unit of measurement: millimeters (alternatively: IN for inches)	X	Alignment axis (X or Y)
25.0	Spacing of supporting points on the X axis	20.0	Spacing of supporting points on the Y axis
5	Number of supporting points on the X axis	5	Number of supporting points on the Y axis
0.0000	Actual value of the first supporting point on the X axis	0.0000	Actual value of the first supporting point on the Y axis
25.0012	Actual value of the second supporting point on the X axis	-0.0010	Actual value of the second supporting point on the Y axis



The file contains an additional row with X and Y values for each supporting point.

Extended TXT schema

The extended TXT file contains the deviations of the supporting points from the nominal values on the X and Y axes.

The following example shows a grid with 5 x 5 supporting points with a spacing of 25 mm on the X axis and 20 mm on the Y axis.

Example

Example	
NLEC Data File	
0.91	
// Serial Number = CA-1288-6631-1710	
MM	
ON	
Number of Grid Points (x, y):	
5	5
Grid Block Size (x, y):	
25.0	20.0
Offset:	
0	0
Station (1, 1)	
0.00000	0.00000
Station (2, 1)	
0.00120	-0.00100
Station (3, 1)	
0.00030	-0.00060
Station (4, 1)	
0.00100	0.00160
Station (5, 1)	
0.00210	0.00000
Station (1, 2)	
0.00005	0.00200
Station (2, 2)	
0.00130	0.00210
Station (3, 2)	
0.00130	0.00220
Station (4, 2)	
0.00050	0.00230
Station (5, 2)	
-0.00040	0.00030
Station (1, 3)	
-0.00010	-0.00020
Station (2, 3)	
-0.00190	-0.00210
Station (3, 3)	
-0.00010	0.00010
Station (4, 3)	
0.00040	0.00210
Station (5, 3)	
0.00190	0.00080
Station (1, 4)	

NLEC Data File	
0.00003	-0.00080
Station (2, 4)	
0.00000	0.00180
Station (3, 4)	
-0.00010	0.00030
Station (4, 4)	
0.00200	-0.00100
Station (5, 4)	
0.00010	0.00010
Station (1, 5)	
-0.00003	0.00210
Station (2, 5)	
-0.00210	0.00040
Station (3, 5)	
0.00200	-0.00090
Station (4, 5)	
0.00010	-0.00150
Station (5, 5)	
0.00100	0.00020

Explanation

The following overview explains the values that you can define individually. All values not listed here must be copied as is from the example.

Value		Explanation	
// Serial Number	= CA-1288-6631-1710	Serial number (optional)	
MM		Unit of measurement: millimeters (alternatively: IN for inches)	
Number of Grid	Points (x, y):		
5	5	Number of supporting points on the X and Y axes	
Grid Block Size	(x, y):		
25.0	20.0	Spacing of the supporting points on the X and Y axes	
Station (1, 1):			
0.00000	0.00000	Deviation of the first supporting point on the X and Y axes	
Station (2, 1):			
0.00120	-0.00100	Deviation of the second supporting point on the X and Y axes	



The file contains a **Station** (x, y) section for each supporting point, indicating the deviations on the X and Y axes.

Creating an XML import file

To create an XML import file, you can either export the existing table of supporting points and edit it as required or create a new file from scratch.

Exporting and editing a table of supporting points



► Tap **Settings** in the main menu



- Open in succession:
 - Axes
 - General settings
 - Error compensation
 - Nonlinear error compensation (NLEC)
- Tap Export table of supporting points
- Select the desired location, e.g. an external storage medium
- Navigate to the desired folder
- Save file under a unique name
- Edit the values in the XML editor or in a text editor available on your computer



The exported XML file also contains the nominal values of the supporting points (**<group id="Standard"> </group>** section). This data will not be taken into account when the file is imported. You may remove this section from the import file, if desired.

Creating a new file

- Create a new file in the XML editor or in a text editor available on your
- ▶ Save the file under a unique name and add the *. xml file extension
- Enter the data as shown in the schema shown below



The following specifications apply to import files:

- File names must not contain diacritics or special characters
- Use a point as decimal character

XML schema

The XML file contains the actual values of the supporting points on the X and Y axes.

The following example shows a grid of 5 x 5 supporting points with a spacing of 25 mm on the X axis and 20 mm on the Y axis.

Example

- <?xml version="1.0" encoding="UTF-8"?> <configuration> <base id="Settings"> <group id="CellSize"> <element id="x">25</element> <element id="y">20</element> </group>
- <group id="General">
- <element id="enabled">false</element>

```
<?xml version="1.0" encoding="UTF-8"?>
</group>
<group id="GridSize">
<element id="x">5</element>
<element id="y">5</element>
</group>
<group id="Level0">
<element id="Position" Angle="0" Z="0" Y="0" X="0"/>
<element id="0-0" Y="0" X="0"/>
<element id="1-0" Y="-0.001" X="25.00120000000001"/>
<element id="2-0" Y="-0.000599999999999999" X="50.00030000000000"/>
<element id="3-0" Y="0.001600000000000001" X="75.00100000000005"/>
<element id="4-0" Y="0" X="100.0021"/>
<element id="1-1" Y="20.00209999999999" X="25.0013000000001"/>
<element id="2-1" Y="20.00219999999998" X="50.00130000000001"/>
<element id="3-1" Y="20.002300000000002" X="75.000500000000002"/>
<element id="4-1" Y="20.00029999999999" X="99.99960000000001"/>
<element id="0-2" Y="39.9998" X="-0.0001"/>
<element id="1-2" Y="39.99790000000001" X="24.99810000000001"/>
<element id="2-2" Y="40.00010000000003" X="49.9998999999997"/>
<element id="3-2" Y="40.00209999999999" X="75.00039999999999"/>
<element id="4-2" Y="40.00079999999998" X="100.0019000000001"/>
<element id="0-3" Y="59.99920000000002" X="3.000000000000001"/>
<element id="1-3" Y="60.00180000000003" X="25"/>
<element id="2-3" Y="60.000300000000003" X="49.99989999999997"/>
<element id="3-3" Y="59.99900000000002" X="75.0019999999995"/>
<element id="4-3" Y="60.00010000000003" X="100.0001"/>
<element id="0-4" Y="80.00209999999999" X="-3.00000000000001"/>
<element id="3-4" Y="79.998500000000007" X="75.000100000000003"/>
<element id="2-4" Y="79.99909999999999" X="50.00200000000000"/>
<element id="4-4" Y="80.00020000000007" X="100.001"/>
</group>
</base>
<base id="version" build="0" minor="4" major="1"/>
</configuration>
```

Explanation

The following overview explains the parameters and values that you can define individually. All items not listed here must be copied as is from the example.

Group	Parameters and values (example)	Explanation	
<pre><group id="CellSize"></group></pre>	<element id="x">25</element>	Spacing of supporting points on the X axis. In this example: 25 mm	
	<element id="y">20</element>	Spacing of supporting points on the Y axis. In this example: 20 mm	
<pre><group id="GridSize"></group></pre>	<element id="x">5</element>	Number of supporting points on the X axis. In this example: 5 supporting points	
	<element id="y">5</element>	Number of supporting points on the Y axis. In this example: 5 supporting points	
<group id="Level0"></group 	<element id="0-0" x="0" y="0"></element>	Actual value of the first supporting point in mm. In this example: X = 0 Y = 0	
	<pre><element id="1-0" x="25.00120000000001" y="-0.001"></element></pre>	Actual value of the supporting point in mm. In this example: X = -0.001 Y = 25.00120000000001	

For each supporting point, the group contains an additional element with these parameters.

Determining the actual values using a teach sequence



This action cannot be undone.



Tap Settings in the main menu



- Open in succession:
 - Axes
 - General settings
 - Error compensation
 - Nonlinear error compensation (NLEC)
- ► To start the teach sequence, tap **Start**
- > The wizard is displayed in the **Measure** menu
- ▶ Follow the instructions of the wizard
- Measure or construct the required feature
- Tap **Confirm** in the wizard to continue





The feature acquired last will be transferred to the table of supporting points.



- Tap **Close** to close the wizard
- > Values measured in the teach sequence are transferred as actual values to the table of supporting points
- After the teach sequence is complete, the **Measure** menu appears

Acquire the actual values manually



► Tap **Settings** in the main menu



- Open in succession:
 - Axes
 - General settings
 - Error compensation
 - Nonlinear error compensation (NLEC)
- Tap Table of supporting points
- ► Enter the actual values of the supporting points
- Confirm each entry with RET

Activating the nonlinear error compensation



► Tap **Settings** in the main menu



- ► Open in succession:
 - Axes
 - General settings
 - Error compensation
 - Nonlinear error compensation (NLEC)
- ► Activate Compensation with the ON/OFF slide switch
- The error compensation is applied from the next measurement

Configuring Squareness error compensation (SEC)

Squareness error compensation (SEC) enables angular errors to be compensated during measuring point acquisition. The compensation factor is determined by comparing the deviation of the actual measurement result from the nominal angle of the spatial axes. The compensation factor is applied to the entire measuring range.



► Tap **Settings** in the main menu



- Open in succession:
 - Axes
 - General settings
 - Error compensation
 - Squareness error compensation (SEC)
- > The measured values (M) and nominal values (S) of the three spatial axes are displayed
- Enter the measured values of the reference standard (= nominal values)
- ▶ Activate Compensation with the ON/OFF slide switch
- Squareness error compensation is applied from the next measurement

Further information: "Squareness error compensation (SEC)", Page 204

7.6.7 Coupling axes

If you couple axes with each other, the product offsets the position values of the two axes according to the selected calculation type. The position display shows only the principal axis with the calculated position value. Coupled axes are not shown in the position display.



► Tap **Settings** in the main menu



- Tap Axes
- ► Tap <Axis name> or, if applicable, **Not defined** for the axis you wish to couple with a principal axis
- ▶ Tap Axis type
- ▶ Select the **Coupled axis** axis type
- ► To switch to the previous display, tap **Back**
- Select the desired principal axis from the Coupled main axis drop-down list
- ► Select the desired calculation type from the **Calculation with** main axis drop-down list:
 - +: principal axis + coupled axis
 - -: principal axis coupled axis
- > The position values of both axes are offset against each other according to the selected type of calculation

Further information: "<Axis name> (settings of the axis)", Page 204



7.6.8 Activating the reference mark search

The product uses the reference marks to reference the machine table to the machine, for example. If the reference mark search has been activated, a wizard appears on startup of the product and asks the user to move the axes for the reference mark search.

Prerequisite: The installed encoders have reference marks that have been configured in the axis parameters.



The reference mark search does not need to be performed for serial encoders with EnDat interface, because the axes are automatically homed.



The automatic reference mark search on startup of the product can be canceled depending on the configuration.

Further information: "Reference marks (Encoder)", Page 210



► Tap **Settings** in the main menu



- ▶ Tap Axes
- Open in succession:
 - General settings
 - Reference marks
- Activate Reference mark search after unit start with the ON/OFF slide switch
- The reference marks must be traversed every time the product is started
- > The functions of the product will only be available after the reference mark search has been completed
- The Reference symbol stops blinking upon successful completion of the reference mark search Further information: "Operating elements of the position display", Page 66

7.7 OEM area

In the **OEM area**, commissioning engineers can customize the product in various ways:

- **Documentation**: Adding the OEM documentation, e.g. service information
- **Startup screen**: Defining a startup screen with the OEM's company logo
- Screenshots: Configuring the unit for screenshots with the program ScreenshotClient

7.7.1 Adding documentation

You can store and display the product's documentation right on the product.



Only documents in the *.pdf file format can be added as a documentation. The product does not display documents provided in other file formats.



► Tap **Settings** in the main menu



- ▶ Tap Service
- ▶ Open in succession:
 - OEM area
 - Documentation
 - Add OEM service info
- ► If required, connect a USB mass storage device (FAT32 format) to a USB port of the product
- ► To navigate to the desired file, tap the location where the file is stored



If you have accidentally tapped the wrong folder, you can return to the previous folder.

- ► Tap the file name that is displayed above the list
- Navigate to the folder containing the file
- ► Tap the file name
- ► Tap Select
- > The file is copied to the unit's **Service info** area **Further information:** "Service info", Page 193
- Confirm the successful transfer with OK

Further information: "Documentation", Page 220

Safely removing a USB mass storage device



- ► Tap **File management** in the main menu
- Navigate to the list of storage locations
- Tap Safely remove
 - > The message "The storage medium can be removed now." appears
 - Disconnect the USB mass storage device

7.7.2 Adding a startup screen

You can define an OEM-specific startup screen, e.g. the company name or logo, which will be displayed when the product is switched on. An image file with the following properties needs to be stored on the product for this purpose:

File type: PNG or JPGResolution: 96 ppi

Image format: 16:10 (other formats will be scaled proportionally)

■ Image size: Max. 1280 x 800 px

Adding a startup screen



► Tap **Settings** in the main menu



- Tap Service
- Open in succession:
 - OEM area
 - Startup screen
 - Add startup screen
- ► If required, connect a USB mass storage device (FAT32 format) to a USB port of the product
- To navigate to the desired file, tap the location where the file is stored




If you have accidentally tapped the wrong folder, you can return to the previous folder.

- ► Tap the file name that is displayed above the list
- ▶ Navigate to the folder containing the file
- ► Tap the file name
- Tap Select
- > The graphic file is copied to the product and displayed as the startup screen the next time the product is started
- Confirm the successful transfer with OK

Safely removing a USB mass storage device



- ► Tap File management in the main menu
- Navigate to the list of storage locations
- ► Tap Safely remove



- The message "The storage medium can be removed now." appears
- Disconnect the USB mass storage device



When you save the user files, the OEM-specific opening screen is also saved and can be restored.

Further information: "Back up user files", Page 121

7.7.3 Configuring the unit for screenshots

ScreenshotClient

With the ScreenshotClient PC software, you can use a computer to take screenshots of the active screen of the product.




Figure 20: The ScreenshotClient user interface

- 1 Connection status
- 2 File path and file name
- 3 Language selection
- 4 Status messages



ScreenshotClient is included in the standard installation of **GAGE-CHEK 2000 Demo**.



For a detailed description, please refer to the **GAGE-CHEK 2000 Demo User's Manual**. This User's Manual is available in the "Documentation" folder of the product website.

Further information: "Demo software for the product", Page 16

Activating remote access for screenshots

To connect ScreenshotClient with the product via the computer you need to activate **Remote access for screenshots** on the product.



► Tap **Settings** in the main menu



- Tap Service
- ► Tap **OEM area**
- Activate Remote access for screenshots with the ON/OFF slide switch

Further information: "OEM area", Page 220

7.8 Backing up data

7.8.1 Back up settings

The product's settings can be backed up as a file so that they are available after a reset to the factory default settings has been performed or for installation on multiple units.



► Tap **Settings** in the main menu



- ▶ Tap Service
- Open in succession:
 - Back up and restore
 - Back up settings

Performing a Complete backup

During a complete backup of the configuration, all settings of the product are backed up.

- ► Tap **Complete backup**
- ► If required, connect a USB mass storage device (FAT32 format) to a USB port of the product
- Select the folder to which you want to copy the configuration data
- Specify a name for the configuration data, e.g. "<yyyy-mm-dd>_config"
- ► Confirm the entry with **RET**
- Tap Save as
- ▶ Tap **OK** to confirm the successful backup of the configuration
- > The configuration file was backed up

Further information: "Back up and restore", Page 218

Safely removing a USB mass storage device



- Tap File management in the main menu
- Navigate to the list of storage locations
- ► Tap **Safely remove**
- The message "The storage medium can be removed now." appears
- ▶ Disconnect the USB mass storage device

7.8.2 Back up user files

The user files of the product can be backed up as a file to make it available after a reset to the factory default settings. This, together with the backing up of the settings, enables you to back up the complete configuration of your product.

Further information: "Back up settings", Page 120



All files from all user groups that are stored in the respective folders are backed up and can be restored as user files.

The files in the **System** folder are not restored.

Performing back up

The user files can be backed up as a ZIP file on a USB mass storage device or connected network drive.



► Tap **Settings** in the main menu



- ▶ Tap Service
- ► Open in succession:
 - Back up and restore
 - Back up user files
- Tap Save as ZIP
- ▶ If required, connect a USB mass storage device (FAT32 format) to a USB port of the product
- Select the folder to which you want to copy the ZIP file
- Specify a name for the ZIP file, e.g. "<yyyy-mm-dd>_config"
- Confirm the entry with RET
- ► Tap Save as
- ► Tap **OK** to confirm successful backup of the user files
- > The user files were backed-up.

Further information: "Back up and restore", Page 218

Safely removing a USB mass storage device



- ▶ Tap **File management** in the main menu
- Navigate to the list of storage locations
- ► Tap Safely remove
- > The message "The storage medium can be removed now."
- Disconnect the USB mass storage device



8

Setup

8.1 Overview

This chapter contains all the information necessary for setting up the product.

During setup, the setup engineer (**Setup**) configures the product for use with the measuring machine in the respective applications. This includes, for example, setting up operators and configuring networks and printers.



Make sure that you have read and understood the "Basic operation" chapter before carrying out the actions described below.

Further information: "Basic operation", Page 51



The following steps must be performed only by qualified personnel.

Further information: "Personnel qualification", Page 25

8.2 Logging in for setup

8.2.1 User login

To set up the product, the **Setup** user must log in.



- ► Tap **User login** in the main menu
- If required, log out the user who is currently logged in
- ► Select the **Setup** user
- ► Tap the **Password** input field
- ► Enter the password "setup"



If the password does not match the default password, ask a **Setup** user or **OEM** user for the assigned password.

If the password is no longer known, contact a HEIDENHAIN service agency.

- ► Confirm the entry with **RET**
- Tap Log in



8.2.2 Performing the reference mark search after startup



If the reference mark search after unit start is active, then all of the unit's functions will be disabled until the reference mark search has been successfully completed.

Further information: "Reference marks (Encoder)", Page 210



The reference mark search does not need to be performed for serial encoders with EnDat interface, because the axes are automatically homed.

If the reference mark search is active on the unit, then a wizard will ask you to traverse the reference marks of the axes.

- ▶ After logging in, follow the instructions of the wizard
- > The Reference symbol stops blinking upon successful completion of the reference mark search

Further information: "Operating elements of the position display", Page 66 **Further information:** "Activating the reference mark search", Page 116

8.2.3 Setting the language

The user interface language is English. You can change to another language, if desired.



► Tap **Settings** in the main menu



- ▶ Tap User
- > The logged-in user is indicated by a check mark
- ► Select the logged-in user
- > The language selected for the user is indicated by a national flag in the **Language** drop-down list
- Select the flag for the desired language from the Language drop-down list
- > The user interface is displayed in the selected language

8.2.4 Changing the password

You must change the password to prevent unauthorized configuration.

The password is confidential and must not be disclosed to any other person.



► Tap **Settings** in the main menu



- ► Tap **User**
- > The logged-in user is indicated by a check mark
- ► Select the logged-in user
- ► Tap **Password**
- ► Enter the current password
- ► Confirm entry with **RET**
- ▶ Enter the new password and repeat it
- ► Confirm entry with **RET**
- ► Tap **OK**
- ► Close the message with **OK**
- > The new password is available the next time the user logs in

8.3 Single steps for setup



The following setup steps build on each other.

 To correctly set up the product, make sure to perform the steps in the order described here

Prerequisite: You are logged on as a user of the **Setup** type (see "Logging in for setup", Page 124).

Basic settings

- Setting the date and time
- Setting the units of measure
- Entering and configuring users
- Adding the Operating Instructions
- Configuring the network
- Configuring the network drive
- Configuring operation with a mouse or touchscreen
- Configuring the USB keyboard

Configuring functions

- Adding function elements
- Configuring functions
 - Configuring probing functions
 - Configuring the MinMax function
 - Configuring the Diameter/Radius function
 - Configuring the Relative function
 - Configuring the Mastering function
 - Configure the Dial gage function
 - Configuring the Part function

Setting up the measuring application

Configuring the measured value output

Backing up data

- Back up settings
- Back up user files

NOTICE

Loss of or damage to configuration data!

If the product is disconnected from the power source while it is on, the configuration data can be lost or corrupted.

▶ Back up the configuration data and keep the backup for recovery purposes

8.3.1 Basic settings



The commissioning engineer (**OEM**) may have already carried out several basic settings.

Setting the date and time



► Tap **Settings** in the main menu



- Tap General
- ► Tap Date and time
- > The set values are displayed in the following format: Year, month, day, hour, minute
- ► To set the date and time in the middle line, drag the columns up or down
- ► Tap **Set** to confirm
- ▶ Select the desired format from the **Date format** list:
 - MM-DD-YYYY: Display as month, day, year
 - DD-MM-YYYY: Display as day, month, year
 - YYYY-MM-DD: Display as year, month, day

Further information: "Date and time", Page 191

Setting the units of measure

You can set various parameters to define the units of measure, rounding methods and decimal places.



Tap Settings in the main menu



- ► Tap **General**
- ▶ Tap Units
- ► To set a unit of measure, tap the corresponding drop-down list and select the unit
- ▶ To set the rounding method, tap the corresponding dropdown list and select the rounding method
- To set the number of decimal places displayed, tap or +

Further information: "Units", Page 191

Entering and configuring users

The following user types, which have different rights, are defined in the product's factory default settings:

- OEM
- Setup
- Operator

Creating a user and password

You can create new **Operator** users. You can use any characters for the user ID and the password. These entries are case-sensitive.

Prerequisite: An OEM or Setup user is logged in.



It is not possible to create new **OEM** or **Setup**-type users.



► Tap **Settings** in the main menu



Tap User



- Tap Add
- ► Tap the **User ID** input field



The **User ID** is displayed for user selection, e.g. at the login prompt.

The **User ID** cannot be changed once it has been defined.

- ▶ Enter the user ID
- ► Confirm the entry with **RET**
- ► Tap the **Name** input field
- ► Enter the name of the new user
- ► Confirm the entry with **RET**
- ► Tap the **Password** input field
- Enter the new password and repeat it
- ► Confirm the entry with **RET**



You can show the contents of the password fields in plain text and hide them again.

- Use the ON/OFF sliding switch to show or hide the contents
- ► Tap **OK**
- > A message appears
- ► Close the message with **OK**
- > The user is created with the basic data. The user can then further edit the data himself later

Configuring the user

After creating a new **Operator**-type user, you can add or edit the following user data:

- Name
- First name
- Department
- Password
- Language
- Auto login



If automatic user login is active for one or more users, the last user who logged in is automatically logged in when the product is switched on. Neither the user ID nor the password needs to be entered.



► Tap **Settings** in the main menu



- ► Tap **User**
- Select the user
- ► Tap the input field whose contents you want to edit: Name, First name, Department
- Edit the contents and confirm your changes with RET
- ► To change the password, tap **Password**
- > The Change password dialog box appears
- When changing the password of the logged-in user, enter the current password
- Confirm the entry with RET
- ▶ Enter the new password and repeat it
- ► Confirm the entries with **RET**
- ▶ Tap **OK**
- > A message appears
- ► Close the message with **OK**
- ► To change the language, select the flag for the desired language in the **Language** drop-down list
- Use the ON/OFF slider to activate or deactivate the Auto login function

Deleting users

You can remove **Operator**-type users that are no longer needed.



OEM and **Setup**-type users cannot be deleted.

Prerequisite: A user of **OEM** or **Setup**-type is logged in.



Tap Settings in the main menu



- ▶ Tap User
- Tap the user you want to delete
- ► Tap Remove user account
- ► Enter the password of the authorized user (**OEM** or **Setup**)
- ► Tap **OK**
- > The user is deleted

Adding the Operating Instructions

The product provides the possibility to upload the corresponding Operating Instructions in the desired language. You can copy the Operating Instructions from the supplied USB mass storage device to the product.

The most recent version of the Operating Instructions is also available at **www.heidenhain.com**.

Prerequisite: The Operating Instructions are available as a PDF file.



► Tap **Settings** in the main menu



- ▶ Tap Service
- Open in succession:
 - Documentation
 - Add Operating Instructions
- ► If required, connect a USB mass storage device (FAT32 format) to a USB port of the product
- Navigate to the folder containing the new Operating Instructions



If you have accidentally tapped the wrong folder, you can return to the previous folder.

- ► Tap the file name that is displayed above the list
- Select file
- ► Tap Select
- > The Operating Instructions are copied to the product
- > Any existing Operating Instructions will be overwritten
- Confirm the successful transfer with OK
- The Operating Instructions can be opened and displayed on the product

Configuring the network

Network settings



Contact your network administrator for the correct network settings for configuring the product.

Prerequisite: The unit is connected to a network.

Further information: "Connecting a network peripheral", Page 49



Tap Settings in the main menu



- ▶ Tap Interfaces
- ► Tap **Network**
- ► Tap the X116 interface
- > The MAC address is detected automatically
- Depending on the network environment, use the ON/OFF slider to activate or deactivate the DHCP function
- > If DHCP is active, the network settings are obtained automatically as soon as the IP address is assigned
- ► If DHCP is not active, enter the IPv4 address, IPv4 subnet mask and IPv4 standard gateway
- Confirm the entries with RET
- ▶ Depending on the network environment, use the ON/OFF slider to activate or deactivate the IPv6 SLAAC function
- If IPv6 SLAAC is active, the network settings are obtained automatically as soon as the IP address is assigned
- ▶ If IPv6 SLAAC is not active, enter the IPv6 address, IPv6 subnet prefix length and IPv6 standard gateway
- ► Confirm the entires with **RET**
- ► Enter the **Preferred DNS server** and, if required, the **Alternative DNS server**
- Confirm the entires with RET
- > The configuration of the network connection is applied

Further information: "Network", Page 195

Configuring the network drive

You will need the following data for configuring the network drive:

- Name
- Server IP address or host name
- Shared folder
- User name
- Password
- Network drive options



Contact your network administrator for the correct network settings for configuring the product.

Prerequisite: The product is connected to a network and a network drive is available.

Further information: "Connecting a network peripheral", Page 49



► Tap **Settings** in the main menu



- ► Tap Interfaces
- Tap Network drive
- ▶ Enter the network drive details
- Confirm the entries with RET
- Use the ON/OFF slider to activate or deactivate the Show password function
- If required, select Network drive options
 - Select Authentication for encrypting the password in the network
 - Configure the Mount options
 - Tap **OK**
- Tap Mount
- The connection to the network drive is established

Further information: "Network drive", Page 196

Configuring operation with a mouse or touchscreen

The product can be operated either via the touchscreen or a connected (USB) mouse. If the product is in its factory default setting, touching the touchscreen deactivates the mouse. Alternatively, you can set that the product is operated either only via the mouse or only via the touchscreen.

Prerequisite: A USB mouse is connected to the product. **Further information:** "Connecting input devices", Page 48



► Tap **Settings** in the main menu



- ▶ Tap General
- ► Tap Input devices
- Select the desired option from the Mouse substitute for multitouch gestures drop-down list

Further information: "Input devices", Page 189

Configuring the USB keyboard

The factory default language for the keyboard assignment is English. You can switch the keyboard assignment to the desired language.

Prerequisite: A USB keyboard is connected to the product. **Further information:** "Connecting input devices", Page 48



Tap Settings in the main menu



- ▶ Tap General
- ► Tap Input devices
- Select the flag for the desired language from the USB keyboard layout drop-down list
- The keyboard assignment corresponds to the selected language

Further information: "Input devices", Page 189

8.3.2 Adding function elements

The function bar provides empty fields to which you can assign function elements. If you add function elements to the function bar, then every user has access to the corresponding functions in the **Measure** menu.

The procedure is identical for all function elements.



For more information on the function elements, please refer to the "Basic operation" chapter.

Further information: "Function elements", Page 69

8.3.3 Configuring probing functions

The probing functions assist you in the acquisition of positions. The wizard guides you through each respective step.

When configuring the probing functions, you can specify whether the **Select preset** dialog box will be displayed afterwards and whether the measured values will be transferred automatically to a computer.

Prerequisites:

- The touch probe was configured
- The optional interface for data transmission was configured

Further information: "Configuring a touch probe", Page 85


Further information: "Configuring the measured value output", Page 145

The following probing functions are available:

lcon	Function	Scheme
::*::	Edge probing Probe the edge of a workpiece (one probing procedure) Determines the coordinate of the traversed axis	ZA
	Determining the center line Determine the centerline of a	z 🛦

(two probing procedures)

Determines the coordinate of the traversed axis






Determining the circle center

Determine the center point of a circular form (hole or cylinder) (four probing procedures)

Determines the coordinates of both axes and the circle diameter



Adding a function element



- ► Tap **Measure** in the main menu
- Drag an empty function bar field to the left and into the workspace
- > A dialog box for selecting the function element appears



- ► Tap the desired function element (e.g., **Determining the** circle center (probing))
- X
- ► Tap **Close**
- > The function element is now available

Configuring a function



- Drag the function element to the left in the workspace
- Use the **ON/OFF** sliding switch in the dialog to activate the desired functions:
 - **MVO**: The measured value is automatically transferred to the computer
 - **Select preset**: Once probing has completed, you can use the acquired coordinates as preset
- When using the **Determining the circle center** probing function, select the plane of the circle via the drop-down lists;

default: Plane of the X and Y axes



- ▶ Tap Close
- > The selection is saved



The product uses the data format for measured value output that is selected for manual data transmission in the product settings.

Further information: "Selecting a data format", Page 147

8.3.4 Configuring the MinMax function

The **MinMax** function helps you to acquire the following measured values:

Minimum Maximum Range

You can activate and deactivate this function by tapping the **MinMax** function element on the function bar. When the function is active, the measured values will be captured and shown in the position display. You can then transfer the measured values to a computer via the measured value output. If you activate the **MinMax** function again, then the existing measured values will be overwritten.

The following steps are necessary in order to configure the **MinMax** function:

- Add the MinMax function element to the function bar
- Select measured values that are to be captured and displayed when the MinMax function is active

Adding a function element



- ► Tap **Measure** in the main menu
- Drag an empty function bar field to the left and into the workspace
- > A dialog box for selecting the function element appears
- ► Tap the **MinMax** function element



- Tap Close
- > The MinMax function element is now available

Selecting measured values



- Drag the MinMax function element to the left in the workspace
- > A dialog box for selecting the measured values appears
- ▶ Enter a name in the Name input field
- ▶ Enter more information in the **Comment** input field if required
- ▶ Tap the desired measured values to select them



- ► Tap Close
- > The selection is saved
- > If you activate the **MinMax** function, the selected measured values will be captured and shown in the position display



Ensure that the **MinMax** function covers all measured values that you want to send to a computer as part of the measured value output. If measured values are missing then the value 0 is sent.




The measured value output always transmits the last position values acquired. If you do not move an axis, the previously acquired values will be transferred.

Activating a switching function

Prerequisite: The output is assigned to the switching function in the settings. **Further information:** "Switching functions", Page 199

The MinMax function can be assigned a switching function that triggers a **Stop / Start** or a **Restart** of the MinMax measurement.





- Activate the switching function using the slide switch
- Select the desired type of switching
 - Stop / Start
 - Restart

8.3.5 Configuring the Diameter/Radius function

The **Diameter/Radius** function allows you to double position values in the position display. With radial axes, you can thus switch between the radius and diameter. You can activate and deactivate the conversion by tapping the **D/R** function element on the function bar. When you configure the function element, you can define which axes will be affected by the conversion.

The following steps are necessary in order to configure the **Diameter/Radius** function:

- Add the D/R function element to the function bar
- Select the axes to be affected by the switch

Adding a function element



- ► Tap **Measure** in the main menu
- Drag an empty function bar field to the left and into the workspace
- > A dialog box for selecting the function element appears



► Tap the **D/R** function element



- ▶ Tap Close
- > The D/R function element is now available

Selecting axes



- ▶ Drag the **D/R** function element to the left in the workspace
- > A dialog box for selecting the axes appears



In order to select axes, tap each diameter symbol



- ▶ Tap Close
- > The selection is saved
- When you activate the D/R function, the product doubles the position value of the selected axes

8.3.6 Configuring the Relative function

The **Relative** function allows you to measure independently of the selected preset. When the **Relative** function is active, you can zero axes and perform measurements, for example, without these actions affecting the selected preset. When you deactivate the **Relative** function, all of the position values and measuring steps are once again referenced to the selected preset.

You can activate and deactivate this function by tapping the **Relative** function element on the function bar.

Adding a function element



- ► Tap **Measure** in the main menu
- Drag an empty function bar field to the left and into the workspace
- > A dialog box for selecting the function element appears



► Tap the **Relative** function element



- ► Tap Close
- > The **Relative** function element is now available

8.3.7 Configuring the Mastering function

The **Mastering** function allows you to set the position values in the position display. Measure, for example, a part on the measuring machine and save the values from the measuring log as a reference part. In addition, you can directly adopt the values of a part that you are using as a reference part from the position display. When configuring the function element, you specify the axes to be affected by **Mastering**.

The following steps are necessary in order to configure the **Mastering** function:

- Add the Mastering function element to the function bar
- Selecting axes
- Enter or apply values that should be set

Adding a function element



- ► Tap **Measure** in the main menu
- Drag an empty function bar field to the left and into the workspace
- > The dialog for selecting the function element is opened



► Tap the **Mastering** function element



- ► Tap Close
- > The **Mastering** function element is now available

Configure the values



- ▶ Drag the Mastering function element to the left and into the workspace
- > The **Configuration Mastering** dialog box appears
- ► Enter a name in the **Name** input field
- ▶ Enter more information in the **Comment** input field if required
- ► Tick the checkbox of the desired axes



- ► Tap **Apply** in order to adopt the values of the position display
- Enter values for the desired axes



► Tap **Close**

8.3.8 Configure the Dial gage function

The dial gauge provides a graphical depiction of the nominal values, the warning threshold values, and the tolerance limits. The **dial gage** function has various views.

With the dial gage, you can perform absolute measurements or difference measurements.

You can save the settings of the dial gage, use them on other devices, or call them again at a later time.

Absolute measurement

In an absolute measurement, the nominal value is entered with its limits. You can specify ahead of time whether you want to enter the limits as absolute or relative values. In the subsequent measurement, the actual value is determined and compared with the nominal value.

Difference measurement

In a difference measurement, the distance between the actual value and zero or a specified value is determined. For difference measurements, you can, for example, manufacture a reference part and then, for each measurement, **Zero the current axis values** of your axis or use **Mastering** to reset your axis.

Further information: "Configuring the Mastering function", Page 139

Comparison of graphical depictions



Figure 21: Example of an absolute measurement

- **1** Nominal value (e.g., 10.000)
- **2** Actual value (e.g., 10.012)



Figure 22: Example of a difference measurement

- **1** Nominal value (e.g., 0.000)
- 2 Difference from nominal value: (e.g., 0.012)

Adding a function element

The following steps are necessary in order to configure the **dial gage** function:

- Add the dial gage function element to the function bar
- Set the general parameters
 - Assign names
 - Value input
- Configure parameters of the individual axes
 - Activate the dial gage for the desired axes
 - Enter limit values
 - Activate and configure switching functions if required



- ► Tap **Measure** in the main menu
- Drag an empty function bar field to the left and into the workspace
- > The dialog for selecting the function element is opened



Tap the dial gage function element



- ► Tap Close
- > The dial gage function element is now available

Create general parameters



- Drag the dial gage function element to the left in the workspace
- > The dial gage dialog box appears
- ▶ Enter a name in the **Name** input field
- Select the desired entry in Value input:
 - absolute
 - relative

Activate axes

You can activate and display each axis separately. As soon as you have activated an axis, you can enter the corresponding values for this axis.

- ► Tap the desired axis in the **dial gage** dialog
- Activate the dial gage with the slide switch for the axis
 - > The input fields are populated with standard values



If you deactivate an activated axis with the slide switch, then the entered values are deleted. As soon as you reactivate the deactivated axis, the input fields are repopulated with default values.

Enter values

After you activated the dial gage for your axis, you can enter values.

The device offers two possibilities to enter values:

- Enter values individually
- Enter values symmetrically




Figure 23: Example of a value input for an axis

Enter values individually

- Tap the input field
- Enter the desired value
- Confirm the entry with RET
- > The entered value is applied

Enter values symmetrically

If you want your desired entry to exhibit identical positive and negative limit values, then you can change the magnitude of these limit values at the same time by using the **Warning limits**, **Tolerance limits**, and **Minimum/Maximum** input fields.

If you have selected **absolute** value input, then the respective values will be calculated based on the nominal value.

If you have selected **relative** value input, the entered value (positive and negative) will be transferred directly.



- ► Tap inside the desired input field
- ▶ Enter the desired value
- Confirm the entry with RET
- > The entered value is applied

Activate the switching function

Precondition: The output is assigned to the switching function in the settings **Further information:** "Switching functions", Page 199

You can assign a switching function to the axes that generates a triggering signal at the output X113.4 (Dout 0) when a limit you determined is exceeded. This way, you can further process an exceedance of a limit value as trigger signal.

- ► Tap the desired axis in the dial gage dialog
- > The dialog for entering the values is opened
- Swipe right to left over the touchscreen
- Activate the switching function with the slide switch for the axis
- Select the desired type of switching
 - High level on exceeding
 - Low level on exceeding
- Activate Pulse with the slide switch if required
- Enter Pulse time if required
- Select the desired limit that generates the triggering signal when exceeded
 - Warning limits
 - Tolerance limits

8.3.9 Creating a preset table

You can access the preset table on the status bar. The preset table contains the absolute positions of the presets with respect to the reference mark. You can save a maximum of 99 presets in the preset table.

Manually creating presets

If you create presets manually in the preset table, the following applies:

- The entry in the preset table assigns the new position values to the current actual position of the individual axes
- Clearing the entry with CE resets the position values for the individual axes to the machine datum again. The new position values are thus always referenced to the machine datum



- ► Tap **Measure** in the main menu
- Drag an empty function bar field to the left and into the workspace
- > A dialog box for selecting the function element appears







- ▶ Tap Close
- > The function element is now available



- Drag the Presets function element to the left and into the workspace
- > The **Preset table** dialog box appears



- ▶ Tap Add
- ▶ Enter a name in the **Description** input field
- ► Tap the input field for one or more desired axes and enter the appropriate position value
- ► Confirm with **RET**
- > The defined preset is added to the preset table



To protect a preset entry from accidental changes or deletion,



tap the **Lock** icon next to the preset entry

The icon changes and the entry is locked



- ► Tap Close
- > The **Preset table** dialog box is closed



Probing the preset

You can use a touch probe to determine presets by probing them. The wizard guides you through each respective step.

Prerequisites:

- The touch probe was configured
- The desired probing function is configured; the Select preset function is activated

Further information: "Configuring a touch probe", Page 85

Edge probing

Further information: "Configuring probing functions", Page 135

► Tap the desired function element on the function bar:



or



Determining the center line

or



- Determining the circle center
- ▶ Follow the instructions of the wizard
- > Measured values are acquired when the stylus deflects
- > The product determines the desired position from the measured values
- > The **Select preset** dialog box appears
- ► To overwrite an existing preset, select the entry from the preset table

or

- ► To add a new preset, enter a new number into the **Selected preset** input field
- ► Confirm the entry with **RET**
- ➤ To overwrite a position value, enter the desired value for the corresponding axis under Set position values
- ► Confirm the entry with **RET**

or

▶ In order to apply a measured position value as the new zero point, leave the input fields under Set position values empty



- ► Tap Confirm in the wizard
- > The position is applied as preset

Deleting presets



- Drag the Presets function element to the left and into the workspace
- > The **Preset table** dialog box appears



The entries in the preset table can be locked to prevent accidental modification or deletion. So you might need to unlock an entry first in order to edit it.



If necessary, tap **Unlock** at the end of the row



- > The entry is enabled for editing
- ▶ To select presets, tap the checkbox in the relevant row



- ► Tap **Delete**
- > A message appears
- Close the message with **OK**
- > The selected presets are deleted from the preset table



Tap CloseThe Preset table dialog box is closed

8.3.10 Configuring the measured value output

The product offers you various functions for manual or automatic transfer of the acquired measured values to a computer.

Prerequisites:

- The product must be connected to the computer via an RS-232 adapter
- Receiving software is installed on the computer (e.g.,)

The following steps are necessary in order to configure the measured value output:

- Configuring an interface
- Selecting a data format
- Adding the desired function elements to the function bar
- Selecting contents for the data transfer



If you connect a USB-to-RS232 connecting cable from the manufacturer STEINWALD datentechnik GmbH to the product, the data interface is configured automatically and is ready immediately. The data format **Steinwald** is used for measured value output. The settings are not configurable.

Functions for measured value output

The function bar provides the following functions for measured value output:

- Manual output of measured values: The user triggers transfer of the measured values manually.
- Touch-probe triggered output of measured values: The product automatically transfers the measured values each time the stylus is deflected.
- Continuous output of measured values: The product transfers the measured values continuously at intervals of approx. 200 ms

The overview shows which contents can be transferred with the respective functions:

Symbol	Function	Current	Minimum	Maximum	Range
	Manual output of measured values	✓	✓	✓	✓
∌ ¹	Touch-probe triggered output of measured values	✓	-	-	-
$ ightharpoons^{C}$	Continuous output of measured values	✓	✓	✓	✓



You can use the Manual output of measured values and Touch-probe triggered output of measured values in parallel. The Continuous output of measured values cannot be combined with any of the other measured value outputs.



See the **General Operation** chapter of this manual for a description of the function elements for the measured value output.

Further information: "Function elements", Page 69



As an alternative to the functions for measured value output that are provided on the function bar and described above, you can use the **Trigger measured value output** switching function for measured value output.

Further information: "Switching functions", Page 199

Configuring an interface

In the product settings you configure the interface for data transfer to the computer.



► Tap **Settings** in the main menu



- Tap Interfaces
- ▶ Tap RS-232
- ▶ Tap X32
- ► The following settings are sent through the RS-232 adapter, and can be adapted as needed for the receiver software:
 - Baud rate
 - Data bits
 - Parity
 - Stop bits
 - Flow control

Further information: "RS-232", Page 197

Selecting a data format

By assigning a data format to the functions for the measured value output, you specify the format in which the measured values will be sent to the computer. For this purpose, you can use the **Standard** and **Steinwald** data formats, or create your own data format (see "Creating your own data format", Page 151).

Selecting a data format



► Tap **Settings** in the main menu



- Tap Interfaces
- Tap Data transfer
- ▶ In the RS-232 drop-down list, select the type of interface



In the following drop-down lists you can choose a separate data format for each function:

- Data format for data transfer
- Data format for touch-probe-triggered data transfer
- Data format for continuous data transfer
- Data format for switching-function-triggered data transfer

Each drop-down list contains the data formats

Standard, Steinwald, MyFormat1, and all self-created data formats.

In order to assign a data format to a function, select the desired data format in the respective drop-down list

Further information: "Data transfer", Page 198

Brief description of the Standard and Steinwald data formats

In the following, you will find a description of data output in the **Standard** and **Steinwald** data formats. The **Standard** and **Steinwald** data formats cannot be changed.



The **Standard** and **Steinwald** data formats transfer measured values only when the following axis names are assigned: X, Y, Z, Q, R, D, L, W, A, C, f, Lx, Ly, or Lz.

The minimum, maximum, and range values are transferred only if the axis names X, Y, or Q are assigned.



If you want to use specific axis names and transfer measured values to a computer, you must modify, for example, **MyFormat1.xml** or another format file you created by adding the axis names that you assigned.

Further information: "Creating your own data format", Page 151

Data output in the data format Standard

```
2020-07-29T07:50:06.965

X 20.023

X HIN 19.987

X HAX 20.035

X RANGE 0.048

Y 24.090

Y HIN 23.952

Y HAX 24.190

Y RANGE 0.238
```

Figure 24: Example of a transfer for the X and Y axes with the active **MinMax** function in the data format **Standard**

Example: X MIN 19.987 mm

	Start of the transfer block						
	2020-07-29		T07:50:06.965			<cr></cr>	<lf></lf>
	Date in yyyy-mm-dd		Time in hh:mm:ss.f				
Х	MIN		19 . 987			<cr></cr>	<lf></lf>
1	2	3	4 5 6			7	8
	<cr> <lf></lf></cr>						<lf></lf>
	End of the transfer block, space						

- 1 Axis name
- 2 Function (MIN, MAX, RANGE)
- 3 Algebraic sign (< 0, then minus sign)
- 4 Digits before the decimal point
- 5 Decimal point
- 6 Digits after the decimal point
- 7 Backwards movement of the cursor to the beginning of the line (Carriage return)
- 8 Line feed

Data output in the data format Steinwald

```
START
2020-07-29T07:49:16.008
X 20.024 нн
X HIN 19.987 нн
X HAX 20.035 нн
X RANGE 0.048 нн
Y 24.090 нн
Y HIN 23.952 нн
Y HAX 24.190 нн
Y RANGE 0.238 нн
END
```

Figure 25: Example of a transfer for the X and Y axes with the active **MinMax** function in the data format **Steinwald**

Example: X MIN 19.987 mm

STAR	START						<cr></cr>	<lf></lf>
Start o	Start of the transfer block							
	2020-07-29 T07:49:16.008					<cr></cr>	<lf></lf>	
Date in yyyy-mm-dd			Time in hh:mm:ss.f					
Х	MIN		19		987	mm	<cr></cr>	<lf></lf>
1	2	3	4	4 5 6 7			8	9
END						<cr></cr>	<lf></lf>	
End o	End of the transfer block							

- 1 Axis name
- 2 Function (MIN, MAX, RANGE)
- 3 Algebraic sign (< 0, then minus sign)
- 4 Digits before the decimal point
- 5 Decimal point
- 6 Digits after the decimal point
- 7 Unit (in this example: millimeter)
- 8 Backwards movement of the cursor to the beginning of the line (Carriage return)
- 9 Line feed

Creating your own data format

In the file management you will find a file that you can copy to a storage medium and then adapt it individually on a computer. Then you can copy the new file to the file storage area of the product and assign it to a function.

Data formats are saved as XML files



- ► Tap **File management** in the main menu
- ► Open in succession:
 - Internal
 - User
 - DataTransfer
- > The folder contains the file MyFormat1.xml
- ► Copy the file **MyFormat1.xml** to a transfer medium
- ▶ Rename file
- ▶ Edit the file in an XML editor or the computer's text editor
- Copy the file from the transfer medium to the following folder of the product: Internal ► User ► DataTransfer



- Use the Switch-off menu to shut down the product and then restart it
- ➤ The data format can be selected through the following path:
 Settings ➤ Interfaces ➤ Data transfer



In order to prevent your data formats from being removed when the firmware is updated, save each file under a separate name.

When the firmware is updated, the **MyFormat1** file in the **DataTransfer** folder is reset to the status it had when shipped. The file is automatically recreated if it no longer exists. Other files in the **DataTransfer** folder are not affected by a firmware update.

Further information: "Copying a file", Page 180 Further information: "Data transfer", Page 198

XML schema of the MyFormat1.xml file




Figure 26: Data format MyFormat1.xml

- 1 Header
- 2 Name of the data format that appears in the **Settings** menu
- **3** General data format settings
- 4 Settings of the axes
- **5** Footer
- 6 End of the data format

The following overview explains the parameters and values that you can define individually. All elements not listed here must be kept as they are.

Element and parameter	Default value	Explanation			
group id	"MyFormat1"	Name of the file format that is displayed in the Settings menu			
element prefix	п п	Character string that is output before the send block or measured value			
		Numbering of send blocks: If in the line ID="General" the value is " $\%0x$ " then the send blocks are numbered sequentially; x defines the quantity of characters for the numbering (x = 0 9)			
		Example:			
		prefix="%04"			
		The first send block is assigned the number 0001			
element suffix	п п	Character string that is output after the send block or measured value			
element previousValues	"false"	"true": The previous send block is output in addition to the current send block			
		"false": Only the current send block is output			
element writeLabel	"true"	"true": The axis name is output before the measured value			
		"false": The axis name is not output			

Element and parameter	Default value	Explanation
element writeUnit	"true"	"true": The unit is output after the measured value Prerequisite: A value must be defined for the "element unit" parameter (see below)
		"false": The unit is not output
element writeTimestamp	"true"	Time stamp for the send block in the format "yyyy-MM-ddThh:mm:ss.zzz" The value is inserted after the prefix attribute.
		In combination with the previousValues="true" attribute, the first (current) value receives the current time upon sending. The second (previous) value retains its original time stamp
element	"true"	A page break is inserted after the time stamp
newlineAfterTimestamp		Only if attribute writeTimestamp="true"
element id	"X"	Measured value to which the subsequent parameters apply; each measured value is defined in its own line Possible values: "X": Current position of X axis "X MIN": Minimum of X axis "X MAX": Maximum of X axis "X RANGE": Range of X axis "Y": Current position of Y axis "Y MIN": Minimum of Y axis "Y MAX": Maximum of Y axis "Y RANGE": Range of Y axis "Z": Current position of Z axis "Z": Current position of Z axis "Z MIN": Minimum of Z axis "Z MAX": Maximum of Z axis "Z RANGE": Range of Z axis "C": Current position of Q axis "Q MIN": Minimum of Q axis "Q MAX": Maximum of Q axis "Q RANGE": Range of Q axis
element unit	"mm"	The measured value is output in the unit millimeters. Possible values: "mm", "inch", "deg", "dms", "rad" If no value is defined, the units are not adapted
element base	"10"	 "10": Measured value is output as a decimal value "16": Measured value is output as a hexadecimal value
element factor "1"		Factor by which the measured value is multiplied Example: Measured value: 43.67 factor="100" Measured value output: 4367.00

Element and parameter	Default value	Explanation			
element newline	"false"	"true": There is a line break after the measured value			
		"false": There is no line break after the measured value			
element decimalPlaces	"3"	Number of decimal places to which the measured value is rounded			
element digits	"O"	Number of digits before the decimal separator to which the measured value is rounded according to commercial practice			
		Example:			
		■ Measured value: 43.67			
		digits="4"			
		Measured value output: 0043.67			
element positiveSign	"false"	"true": Output a plus sign before the measured value			
		"false": Do not output a plus sign before the measured value			

Adding a function element



- ► Tap **Measure** in the main menu
- Drag an empty function bar field to the left and into the workspace
- > A dialog box for selecting the function element appears
- ► Tap one of the following function elements:
 - Manual output of measured values
 - Touch-probe triggered output of measured values
 - Continuous output of measured values



- ► Tap Close
- > The function element is now available

Selecting contents for the data transfer

When configuring the function element, you select which contents are to be transferred to the computer.



- Drag the function element to the left into the workspace
- > A dialog box for selecting the contents appears
- ► Tap the desired contents to select them
- > The function element shows which contents are selected for data transfer; selected contents are highlighted green




Figure 27: Display of selected contents for Measured value output



- ► Tap Close
- > The selection is saved



Ensure that the **MinMax** function covers all measured values that you want to send to a computer as part of the measured value output. If measured values are missing then the value 0 is sent.

Further information: "Configuring the MinMax function", Page 136

8.3.11 Configuring the Part function

The **Part** function encompasses the required functions for the object to be measured. When the **Part** function is activated, then all of the irrelevant functions are hidden. You can save the required functions separately for every object of measurement, and then export or import the saved functions. If you deactivate the **Part** function, then all of the active functions within the part will also be deactivated.

You can add the following functions to the **Part** function as many times as needed:

- Dial gage
- Mastering
- MinMax
- MVO




Figure 28: Example of active Part function with selected functions

Adding a function element



- ► Tap **Measure** in the main menu
- Drag an empty function bar field to the left and into the workspace
- > A dialog box for selecting the function element appears
- 曲
- Tap the **Part** function element



- ► Tap Close
- > The **Part** function element is now available

Configuring selected functions

Saving functions



- Drag the Part function element to the left and into the workspace
- > The **Part** dialog box appears
- ▶ Enter a name in the **Name** input field
- ▶ Enter more information in the **Comment** input field if required
- Select the functions that you want to add
- ▶ Use the + or buttons to enter how many times you want to add a specific function to the Part function



▶ Tap Close



When the **Part** function is activated, you can still add new functions to the function bar using the described procedure.

Further information: "Adding a function element to the function bar", Page 71

Activating the Part function



- ► Tap Part
- > The green lettering of the function element indicates that the function is active
- > All other functions of the function bar are hidden. Only the functions that you have previously selected are displayed

Configuring saved functions

You can configure the functions that you have saved. The configuration procedure is the same as the one you are familiar with from outside of a part.

In addition, you can import or export the saved configuration data using a file in XMG format.

Further information: "Configure the Dial gage function", Page 139
Further information: "Configuring the Mastering function", Page 139
Further information: "Configuring the MinMax function", Page 136
Further information: "Configuring the measured value output", Page 145

Importing or exporting configuration data

If you want to reuse the configured functions that you have saved in a part, you can export them and import them into another function. The import and export behave differently from what you are familiar with from outside of a part. If you change an imported configuration within a part, the configuration file will not be changed.

Function	Description
ш	Export
	The configuration is exported. If you open and change the file within a different function, then the configuration that is saved in the part will remain unchanged.
r_	Import
	The configuration is imported. If you import the configuration file into a part, the data will be imported. You can change the data, but the configuration file will remain unchanged.
	If you want to change configuration file, you can use the export function to overwrite the file.

Exporting configuration data from a part

Drag the desired function element to the right

> The **Save configuration** dialog box appears

- ► Tap **Save**
- ► Select the folder to which you want to save the configuration
- Specify a name for the XMG file
- Confirm with RET
- ▶ Tap Save
- > The file has been saved

Importing configuration data into a part



- Drag the desired function element to the right
- ► Tap **Open**
- > The **Open configuration** dialog box appears
- Navigate to the folder in which the saved file is stored
- ► Tap the desired XMG file
- ► Tap **Open**
- > The data will be imported

8.4 Back up settings

The product's settings can be backed up as a file so that they are available after a reset to the factory default settings has been performed or for installation on multiple units.



► Tap **Settings** in the main menu



- ▶ Tap Service
- ► Open in succession:
 - Back up and restore
 - Back up settings

Performing a Complete backup

During a complete backup of the configuration, all settings of the product are backed up.

- ► Tap Complete backup
- ▶ If required, connect a USB mass storage device (FAT32 format) to a USB port of the product .
- Select the folder to which you want to copy the configuration data
- Specify a name for the configuration data, e.g. "<yyyy-mm-dd>_config"
- Confirm the entry with RET
- Tap Save as
- Tap **OK** to confirm the successful backup of the configuration
- > The configuration file was backed up


Further information: "Back up and restore", Page 218

Safely removing a USB mass storage device



- ► Tap **File management** in the main menu
- Navigate to the list of storage locations





Disconnect the USB mass storage device

8.5 Back up user files

The user files of the product can be backed up as a file to make it available after a reset to the factory default settings. This, together with the backing up of the settings, enables you to back up the complete configuration of your product.

Further information: "Back up settings", Page 120



All files from all user groups that are stored in the respective folders are backed up and can be restored as user files.

The files in the **System** folder are not restored.

Performing back up

The user files can be backed up as a ZIP file on a USB mass storage device or connected network drive.



► Tap **Settings** in the main menu



- ▶ Tap Service
- Open in succession:
 - Back up and restore
 - Back up user files
- ► Tap Save as ZIP
- ▶ If required, connect a USB mass storage device (FAT32 format) to a USB port of the product
- Select the folder to which you want to copy the ZIP file
- Specify a name for the ZIP file, e.g. "<yyyy-mm-dd>_config"
- ► Confirm the entry with **RET**
- ► Tap Save as
- ► Tap **OK** to confirm successful backup of the user files
- > The user files were backed-up.

Further information: "Back up and restore", Page 218

Safely removing a USB mass storage device



- ▶ Tap **File management** in the main menu
- Navigate to the list of storage locations



- ► Tap Safely remove
- > The message "The storage medium can be removed now." appears
- Disconnect the USB mass storage device

Measuring

9.1 Overview

This chapter describes how you prepare and perform a measurement. You will also learn how to send measured values to a computer.

The methods for capturing the measuring points and positioning the axes depend on the respective machine on which the GAGE CHEK 2000 is used. A general description follows below.



Make sure that you have read and understood the "Basic operation" chapter before carrying out the actions described below.

Further information: "Basic operation", Page 51

Short description

The **Measure** menu provides information about the measured or probed position values of one or more axes. This allows you to easily measure lengths and angles. The **MinMax** function supports you in the acquisition of minimum, maximum, and range. You can transfer the measured values to a computer manually or automatically. Various functions are available for outputting the measured values. With the **D/R** function, you can switch between radius and diameter in the position display. With the **Relative** function, you can measure independently of the selected preset.

9.2 Conducting a measurement

9.2.1 Preparing a measurement

Cleaning the measured object and the measuring machine

Contamination, e.g. from chips, dust and oil residues, leads to incorrect measurement results. The measured object, the holder for the measured object, and the sensor must be clean before you start measuring.

► Clean the measured object, the holder for the measured object, and the sensors with appropriate cleaning products

Stabilizing the temperature of the measured object

The objects to be measured should be stored at the measuring machine for an appropriate amount of time to allow the objects to adjust to the ambient temperature. Since the dimensions of the measured objects vary with temperature changes, the temperature of the measured objects must be stabilized.

This ensures the reproducibility of the measurement. The reference temperature is usually 20 °C.

Stabilize the temperature of the measured objects for an appropriate amount time

Reducing environmental influences

Environmental influences, such as incident light, ground vibration or air humidity, can affect the measuring machine, the sensors or the measured objects, and thus falsify the measurement results. Certain influences, such as incident light, also have a negative effect on the measurement uncertainty.

▶ Eliminate or avoid environmental influences as far as possible

Fixing the measured object in place

The measured object must be fixed in place on the measuring plate or in an appropriate holder, depending on its size.

- Position the measured object in the center of the measuring range
- ▶ Use e.g. modeling clay to fix small measured objects in position
- Use fixtures to fix large measured objects in position
- Make sure that the measured object is fastened neither too loosely nor too tightly

Conducting the reference mark search

With the help of reference marks, the unit can assign axis positions of the encoder to the machine.

If no reference marks for the encoder are provided by a defined coordinate system, you need to perform a reference mark search before you start measuring.



If the reference mark search after unit start is active, then all of the unit's functions will be disabled until the reference mark search has been successfully completed.

Further information: "Reference marks (Encoder)", Page 210



The reference mark search does not need to be performed for serial encoders with EnDat interface, because the axes are automatically homed.

If the reference mark search is active on the unit, then a wizard will ask you to traverse the reference marks of the axes.

- After logging in, follow the instructions of the wizard
- > The Reference symbol stops blinking upon successful completion of the reference mark search

Further information: "Operating elements of the position display", Page 66 Further information: "Activating the reference mark search", Page 116

Starting the reference mark search manually



A manual reference mark search can be performed only by the **Setup** and **OEM** user types.

If the reference mark search was not performed on startup, you can start it manually later.



- Tap Settings in the main menu
- Open in succession:
 - Axes
 - General settings
 - Reference marks
- ▶ Tap Start
- > The Reference symbol blinks
- Follow the instructions of the wizard
- The Reference symbol stops blinking upon successful completion of the reference mark search



9.2.2 Selecting a preset

The following options are available for defining the preset of a measurement:

- Activate an existing preset from the preset table
- Set a position as a preset by zeroing the axis or entering a position value
- Probing a preset with a touch probe

Activating the preset

Prerequisite:

- The Presets function element is available on the function bar Further information: "Adding a function element to the function bar", Page 71
- The preset table contains presets

Further information: "Creating a preset table", Page 142



- Tap Presets
- ▶ The Presets dialog box appears
- ▶ Tap the desired preset



- ▶ Tap Confirm
- > The preset is set
- > The selected preset is displayed in the function element

Setting a position as a preset

Prerequisite:

■ The axes are referenced

Setting the current position as preset

- Approach the desired position
- Long-press the axis key
 - > The active preset in the preset table is overwritten with the current position
 - > The active preset is applied as the new value

Defining the position values of the current position



- Approach the desired position
- ▶ In the working space, tap the **axis key** or the position value
- ▶ Enter the desired position value
- ► Confirm the entry with **RET**
- > The position value is applied to the current position
- > The entered position value is linked with the current position and overwrites the active preset in the preset table
- > The active preset is applied as the new value

Probing the preset

You can use a touch probe to determine presets by probing them. The wizard guides you through each respective step.

Prerequisites:

The touch probe was configured

or

or

The desired probing function is configured; the Select preset function is activated

Further information: "Configuring a touch probe", Page 85

Further information: "Configuring probing functions", Page 135

- ► Tap the desired function element on the function bar:
- Edge probing
- Determining the center line
- Determining the circle centerFollow the instructions of the wizard
- > Measured values are acquired when the stylus deflects
- > The product determines the desired position from the measured values
- > The **Select preset** dialog box appears
- ► To overwrite an existing preset, select the entry from the preset table

or

- ► To add a new preset, enter a new number into the **Selected preset** input field
- ► Confirm the entry with **RET**
- To overwrite a position value, enter the desired value for the corresponding axis under Set position values
- ► Confirm the entry with **RET**

or

- ► In order to apply a measured position value as the new zero point, leave the input fields under **Set position values** empty
- ► Tap **Confirm** in the wizard
- > The position is applied as preset



9.2.3 Measuring lengths and angles

Prerequisites:

■ The axes have been configured

Further information: "Configuring the axes", Page 85

■ The reference mark search was successfully completed

Further information: "Performing the reference mark search after startup",

Page 59




Figure 29: Measure menu

- 1 Current axis positions
 - Select a preset where necessary
 - ▶ Move to the desired position or acquire measured values
 - > The result is provided
 - > You can send the measured values to a computer

Further information: "Sending measured values to a computer", Page 174

9.2.4 Measuring with a touch probe

Prerequisite: The touch probe is configured

Further information: "Configuring a touch probe", Page 85




Figure 30: Measure menu with touch probe

- 1 Current axis position
- 2 Last measured value, captured upon deflection of the stylus
 - Select a preset where necessary
 - Move to the desired position
 - The display of the position is updated when the stylus is deflected
 - > You can send the measured values to a computer

Further information: "Sending measured values to a computer", Page 174

9.2.5 Measuring with probing functions

A touch probe allows you to determine positions by probing. For this purpose, the product provides special probing functions. A wizard guides you through the procedure.

Prerequisites:

- The touch probe has been configured
- The desired probing function has been configured
- When determining a new preset: The **Select preset** function must be activated in the settings of the function element
- When using the **Determining the circle center** probing function: At least two axes are configured with a linear encoder or an angle encoder as linear encoder

Further information: "Configuring a touch probe", Page 85

Further information: "Configuring probing functions", Page 135

Further information: "Configuring the axes", Page 85



Figure 31: Function bar with the function elements for probing functions

- 1 Function elements start the wizard for probing a measured object
- 2 If measured value output is activated, the function element shows the interface for data transmission
 - Tap the desired function element on the function bar:

or

or





Edge probing

Determining the center line

Determining the circle center

- Follow the instructions of the wizard
- The measured values are acquired when the stylus is deflected
- The product determines the desired position based on the measured values
- > When the **Select preset** function is activated, a dialog appears in which you can apply the position as the new preset
- > When the MVO function is activated, the product transmits the measured values to the computer

9.2.6 Acquiring the minimum, maximum, and range

Prerequisite: The MinMax function is configured

Further information: "Configuring the MinMax function", Page 136




Figure 32: Measure menu with active MinMax function

- 1 Minimum, maximum, and range
- 2 Function element when the MinMax function is active

You can activate the **MinMax** function during the measurement in order to determine the following values:

- Minimum: lowest valueMaximum: highest value
- Range: difference between the highest and the lowest value



The individual configuration determines which value are captured and shown in the position display



- Select a preset where necessary
- ► Tap **MinMax** in order to start the acquisition
- > The function element turns green to show that the **MinMax** function is active
- > The position display shows the minimum, maximum, and range for each axis (depending on the configuration)
- ► Conduct the measurement
- In order to interrupt the acquisition, drag the green **MinMax** function element to the right
- > The MinMax function is paused, and the icon turns gray
- Tap the gray MinMax function element in order to continue capturing
- To complete the capture processes, tap the green MinMax function element
- > The MinMax function is deactivated
- > The position display shows the current position of each axis
- > You can send the measured values to a computer

Further information: "Sending measured values to a computer", Page 174



The last measured values remain in the product's buffer memory and can be transferred via measured value output, until you capture new measured values with the **MinMax** function.

9.2.7 Displaying the diameter

Prerequisite: The **Diameter/Radius** function has been configured **Further information:** "Configuring the Diameter/Radius function", Page 138




Figure 33: Measure menu with activated D/R function

- 1 The diameter symbol indicates that the conversion of the position value for the axis is active
- 2 Function element with active D/R function

The **Diameter/Radius** function allows you to double position values in the position display. With radial axes, you can thus switch between the radius and diameter. You can activate and deactivate the conversion by tapping the **D/R** function element on the function bar. When you configure the function element, you can define which axes will be affected by the conversion.



- ▶ In order to display the diameter, tap the **D/R** function element
- > The green lettering of the function element indicates that the **D/R** function is active
- > The product doubles the position values of the selected axes
- > For the axes whose position value is converted, the diameter symbol appears
- ► In order to display the radius, tap the **D/R** function element again
- This conversion is deactivated for all axes.

9.2.8 Performing a relative measurement

Prerequisite: The Relative function has been configured

Further information: "Configuring the Relative function", Page 138




Figure 34: Measure menu with activated Relative function

- 1 Position value referenced to the selected preset
- 2 Position value of the relative measurement, independent of the selected preset
- 3 Function element with active **Relative** function

The **Relative** function allows you to perform relative measurements independently of the selected preset. When the **Relative** function is active, the preset table is barred from editing, so that the zeroing of axes or the overwriting of position values has no effect on the selected preset.



- ► In order to perform a relative measurement, tap the **Relative** function element
- > The green lettering of the function element indicates that the **Relative** function is active
- The position display switches over to the position values of the relative measurement
- > The preset table is barred from editing
- ► Zero the axis as needed

or

- Overwrite the position values as needed
- ▶ Perform the desired measurement



- In order to end the relative measurement, tap the **Relative** function element again
- > The position display switches over to the standard view
- > The preset table is enabled for editing

9.2.9 Measure with dial gage

Overview

The overview shows the current measurement values of all configured axes of the device in the dial gage depiction.




Figure 35: Overview

- 1 Dial gage depiction of the X axis value
- 2 Dial gage depiction of the Y axis value
- 3 Dial gage function element
- 4 Zero the current axis values
- **5** Dial gage depiction of the Z axis value

Depending on the deviation between the nominal value of the measurement and the specified tolerance values and warning values, the dial gage depiction of the measured value appears in a different colors:

Color	Evaluation
Green	The measured value lies within the warning limits.
Orange	The measured value exceeds the warning limit but still lies within the tolerance limit.
Red	The measured value exceeds the tolerance limit.

Opening the overview

To open the overview:



- ▶ Tap the **dial gage** function element on the function bar
- > The overview opens

Single view

The single view shows the current measurement results of the selected axis in the dial gage depiction.




Figure 36: Single view of the dial gage

- 1 Minimum tolerance limit
- 2 Minimum warning limit
- 3 Nominal value
- 4 Maximum warning limit
- 5 Maximum tolerance limit
- 6 Maximum limit
- 7 Actual value
- 8 Minimum limit

Opening the single view

To switch from the overview to the single view of an axis, proceed as follows:

► Tap the desired single view,

or

- ► Swipe across the touchscreen from right to left until the desired single view appears
- > The single view opens

9.2.10 Sending measured values to a computer

Use the functions for **Measured value output** to transfer measured values to a computer manually or automatically.

Prerequisite: Measured-value output must be configured

Further information: "Configuring the measured value output", Page 145

Sending measured values manually



- Conduct a measurement
- ► Tap Manual measured value output
- > The measured values are sent to the computer once

Activating touch-probe triggered output of measured values



- ► Tap Touch-probe triggered output of measured values
- > The green symbol shows that the function is active
- ► Conduct a measurement
- The measured values are sent to the computer each time the stylus deflects
- In order to deactivate the function, tap the Touch-probe triggered output of measured values function element again

Activating continuous output of measured values



- Tap Continuous output of measured values
- > The green symbol shows that the function is active
- ► Conduct a measurement
- The measured values are sent to the computer at a periodic interval
- In order to deactivate the function, tap the **Continuous** output of measured values function element again



In addition, you can activate automatic data transfer individually for each probing function.

Further information: "Configuring probing functions", Page 135

9.2.11 Using part management

Prerequisite: The Part function has been configured

Further information: "Configuring the Part function", Page 156




Figure 37: Measure menu with activated Part function

The **Part** function encompasses the required functions for the object to be measured. When the **Part** function is activated, all of the irrelevant functions are hidden. You can save the required functions separately for every object of measurement.



- ▶ Tap Part
- > The green lettering of the function element indicates that the function is active
- > All other functions will be hidden. Only the functions that you have previously selected are displayed
- ► Tap the desired function
- > The function is activated



If you deactivate the **Part** function, then all of the active functions within the **Part** will also be deactivated.

File management

10.1 Overview

This chapter describes the **File management** menu and its functions.



Make sure that you have read and understood the "Basic operation" chapter before carrying out the actions described below.

Further information: "Basic operation", Page 51

Short description

The **File management** menu shows an overview of the files stored in the product's memory.

Any connected USB mass storage devices (FAT32 format) or available network drives are shown in the list of storage locations. The USB mass storage devices and the network drives are displayed with their name or drive designation.

Calling up



- ► Tap File management in the main menu
- > The file management user interface is displayed




Figure 38: File management menu

- 1 List of available storage locations
- 2 List of folders in the selected storage location

10.2 File types

In the File management menu you can edit the following file types:

Туре	Use	Manage	View	Open	Print
*.mcc	Configuration files	✓	_	-	_
*.dro	Firmware files	✓	_	_	_
*.svg, *.ppm	Image files	✓	_	_	_
*.jpg, *.png, *.bmp	Image files	✓	√	_	_
*.CSV	Text files	✓	_	_	_
*.txt, *.log, *.xml	Text files	✓	✓	_	-
*.pdf	PDF files	✓	✓	_	✓

10.3 Managing folders and files

Folder structure

In the **File management** menu, the files in the **Internal** storage location are saved in the following folders:

Folders	Application
Documents	Document files
System	Audio files and system files
User	User data

Creating a new folder

- Drag the icon of the folder in which you want to create a new folder to the right
- > The operating elements are displayed



- ► Tap Create a new folder
- ► Tap the input field in the dialog and enter a name for the new folder
- ► Confirm entry with **RET**
- ► Tap **OK**
- > A new folder is created

Moving a folder

- Drag the icon of the folder you want to move to the right
- > The operating elements are displayed



- ▶ In the dialog, select the folder to which you want to move the folder
- ► Tap **Select**
- > The folder is moved



Copying a folder

- Drag the icon of the folder you want to copy to the right
- > The operating elements are displayed



- ▶ Tap Copy to
- In the dialog, select the folder to which you want to copy the folder
- ▶ Tap Select
- > The folder is copied



If you copy a folder to the folder it is stored in, the suffix "_1" is appended to the name of the copied folder.

Renaming a folder

- Drag the icon of the folder you want to rename to the right
- > The operating elements are displayed



- Tap Rename folder
- Tap the input field in the dialog and enter a name for the new folder
- Confirm the entry with RET
- ► Tap **OK**
- > The folder is renamed

Moving a file

- Drag the icon of the file you want to move to the right
- > The operating elements are displayed
- ▶ Tap Move to
 - In the dialog, select the folder to which you want to move the file
 - ► Tap Select
 - > The file is moved



If you move a file into a folder containing a file with the same name, that file is overwritten.

Copying a file

- Drag the icon of the file you want to copy to the right
- > The operating elements are displayed
- - In the dialog, select the folder to which you want to copy the file
 - ► Tap Select
 - > The file is copied

Tap Copy to



If you copy a file to the folder it is stored in, the suffix "_1" is appended to the name of the copied file.

Renaming a file

- Drag the icon of the file you want to rename to the right
- > The operating elements are displayed



- ► Tap Rename file
- Tap the input field in the dialog and enter a name for the new file
- Confirm the entry with RET
- Tap **OK**
- > The file is renamed

Deleting a folder or file

The folders and files you delete will be permanently deleted and cannot be recovered. If you delete a folder, all subfolders and files contained in that folder will also be deleted.

- Drag the icon of the folder or file you want to delete to the right
- > The operating elements are displayed



- ► Tap **Delete selection**
- ► Tap **Delete**
- > The folder or file is deleted

10.4 Viewing and opening files

Viewing files



- ► Tap File management in the main menu
- Navigate to the storage location of the desired file
- ► Tap the file
- A preview image (only with PDF and image files) as well as information about the file are displayed




Figure 39: File management menu with preview image and file information

- ▶ Tap View
- > The file contents are displayed
- ► Tap Close to close the view



10.5 Exporting files

You can export files to an external USB mass storage device (FAT32 format) or to the network drive. You can either copy or move the files:

- If you copy files, duplicates of the files will remain stored in the product
- If you move files, the files will be deleted in the product



- ► Tap **File management** in the main menu
- ▶ In the Internal storage location, navigate to the file you want to export
- Drag the icon of the file to the right
- > The operating elements are displayed
- ► To copy the file, tap Copy file



- To move the file, tap Move file
- ► In the dialog, select the storage location to which you want to export the file
- ▶ Tap Select
- The file is exported to the USB mass storage device or the network drive

Safely removing a USB mass storage device



- ► Tap File management in the main menu
- Navigate to the list of storage locations



- ► Tap Safely remove
- > The message "The storage medium can be removed now." appears
- ▶ Disconnect the USB mass storage device

10.6 Importing files

You can import files from a USB mass storage device (FAT32 format) or a network drive into the product. You can either copy or move the files:

- If you copy files, duplicates of the files will remain on the USB mass storage device or the network drive
- If you move files, the files will be deleted from the USB mass storage device or the network drive



- ► Tap **File management** in the main menu
- On the USB mass storage device or network drive, navigate to the file you want to import
- Drag the icon of the file to the right
- > The operating elements are displayed



▶ To copy the file, tap Copy file



- ► To move the file, tap Move file
- ► In the dialog, select the storage location to which you want to save the file
- ► Tap **Select**
- > The file is stored on the product

Safely removing a USB mass storage device



- ► Tap File management in the main menu
- Navigate to the list of storage locations



- Tap Safely remove
- The message "The storage medium can be removed now." appears
- ▶ Disconnect the USB mass storage device

Settings

11.1 Overview

This chapter describes the setting options and the associated settings parameters for the product.

The basic setting options and settings parameters for commissioning and product setup are outlined in the respective chapters:

Further information: "Commissioning", Page 77

Further information: "Setup", Page 123

Short description



Depending on the type of user that is logged in to the product, settings and settings parameters can be edited and changed (edit permission).

If a user logged in to the product has no edit permission for a setting or a settings parameter, the setting or settings parameter is grayed out and cannot be opened or edited.



Depending on the software options that have been activated on the product, various settings and settings parameters are available in the Settings menu.

If, for example, the is not activated on the unit, then the settings parameters that are necessary for this software option are not displayed on the unit.


Function	Description
General	General settings and information
Sensors	Configuration of sensors and sensor-dependent functions
Interfaces	Configuration of interfaces and network drives
User	Configuration of users
Axes	Configuration of connected encoders and error compensation
Service	Configuration of software options, service functions and information

Calling up



► Tap **Settings** in the main menu

11.1.1 Overview of the Settings menu



11.2 General

This chapter describes settings for configuring the operation and display .

11.2.1 Device information

Path: Settings ► General ► Device information

The overview displays basic information about the software.

Parameter	Displays the information
Product designation	Product designation of the product
Part number	ID number of the unit
Serial number	Serial number of the product
Firmware version	Version number of the firmware
Firmware built on	Firmware creation date
Last firmware update on	Date of most recent firmware update
Free memory space	Free memory space in the internal storage location Internal
Free working memory (RAM)	Free RAM on the system
Number of unit starts	Number of times the product was started up with the current firmware
Operating time	Operating time of the product with the current firmware

11.2.2 Screen

Path: Settings ► General ► Screen

Parameter	Explanation
Brightness	Brightness of the screen
	Setting range: 1 % 100 %
	Default setting: 85 %
Energy-save-mode timeout	Time until energy-save mode is activated
	Setting range: 0 min 120 min If the value is set to 0, the power-saving mode is deactivated
	Default setting: 30 minutes
Quit the energy saving mode	Required actions to reactivate the screen
	Tap and drag: Touch the touchscreen and drag the arrow upwards from the lower edge
	■ Tap: Touch the touchscreen
	■ Tap or axis movement : Touch the touchscreen or move the axis
	Default setting: Tap and drag

11.2.3 Display

Path: **Settings** ► **General** ► **Display**

Parameter	Explanation
Digits before the decimal point for size-adjusted axis display	The number of digits in front of the decimal point indicates the size at which the position values are displayed. If the number of digits in front of the decimal point is exceeded, then the display is reduced in size so that all of the digits can be shown. Setting range: 0 6 Default value: 3

11.2.4 Input devices

Path: Settings ➤ General ➤ Input devices

Parameter	Explanation
Mouse substitute for multitouch gestures	Specifies whether mouse operation should replace operation using the touchscreen (multitouch)
	Settings:
	Auto (until first multitouch): Touching the touchscreen causes mouse deactivation
	On (no multitouch): Operation only possible with the mouse, the touchscreen is deactivated
	Off (only multitouch): Operation only possible with the touchscreen, the mouse is deactivated
	Default setting: Auto (until first multitouch)
USB keyboard layout	If a USB keyboard is connected:
	Language selection of the keyboard assignment

11.2.5 Sounds

Path: Settings ► General ► Sounds

The available sounds are grouped into categories. The sounds differ within a category.

Parameter	Explanation
Speaker	Use of the built-in speaker on the rear panel of the product Settings: ON or OFF
	Default setting: ON
Speaker volume	Volume of the product's speaker
	Setting range: 0 % 100 %
	Default setting: 50 %
Measuring point acquired	Sound to be played after a measuring point was acquired
	When you select a setting, the associated sound is played
	Settings: Standard, Guitar, Robot, Outer space, No sound
	Default setting: Standard
Message and Error	Sound to be played when a message is displayed
	When you select a setting, the associated sound is played
	Settings: Standard, Guitar, Robot, Outer space, No sound
	Default setting: Standard
Touch tone	Sound to be played when using a touch element
	When you select a setting, the associated sound is played
	Settings: Standard, Guitar, Robot, Outer space, No sound
	Default setting: Standard
	3 3

11.2.6 Printers

Path: Settings ► General ► Printers



The current firmware of the units in this series does not support this function.

11.2.7 Date and time

Path: Settings ➤ General ➤ Date and time

Parameter	Explanation
Date and time	Current date and time of the product
	Settings: Year, Month, Day, Hour, Minute
	Default setting: Current system time
Date format	Format in which the date is displayed
	Settings:
	■ MM-DD-YYYY: month, day, year
	■ DD-MM-YYYY : day, month, year
	■ YYYY-MM-DD: year, month, day
	Default setting: YYYY-MM-DD (e.g. "2016-01-31")

11.2.8 Units

Path: **Settings** ► **General** ► **Units**

Parameter	Explanation
Unit for linear values	Unit of measure for linear values
	Settings: Millimeters or Inch
	Default setting: Millimeters
Rounding method for linear	Rounding method for linear values
values	Settings:
	Commercial: Decimal digits from 1 to 4 are rounded down, decimal digits from 5 to 9 are rounded up
	Round off: Decimal digits from 1 to 9 are rounded down
	Round up: Decimal digits from 1 to 9 are rounded up
	■ Truncate : Decimal digits are truncated without rounding up or down
	Round to 0 and 5: Decimal digits ≤ 24 or ≥ 75 are rounded to 0, decimal digits ≥ 25 or ≤ 74 are rounded to 5
	Default setting: Commercial
Decimal places for linear values	Number of decimal places for linear values
	Setting range:
	Millimeters: 0 5
	■ Inch: 0 7
	Default value:
	■ Millimeters: 4
	■ Inch: 6

Parameter	Explanation
Unit for angular values	Unit for angular values
	Settings:
	Radian: angles in radian (rad)
	Decimal degrees: angles in degrees (°) with decimal places
	Deg-Min-Sec: angles in degrees (°), minutes ['] and seconds ["]
	Default setting: Decimal degrees
Rounding method for angular	Rounding method for decimal angular values
values	Settings:
	 Commercial: Decimal digits from 1 to 4 are rounded down, decimal digits from 5 to 9 are rounded up
	Round off: Decimal digits from 1 to 9 are rounded down
	Round up: Decimal digits from 1 to 9 are rounded up
	Truncate: Decimal digits are truncated without rounding up or down
	Round to 0 and 5: Decimal digits ≤ 24 or ≥ 75 are rounded to 0, decimal digits ≥ 25 or ≤ 74 are rounded to 5
	Default setting: Commercial
Decimal places for angular	Number of decimal places for angular values
values	Setting range:
	Radian: 0 7
	Decimal degrees: 0 5
	■ Deg-Min-Sec: 0 2
	Default value:
	Radian: 5
	Decimal degrees: 3
	Deg-Min-Sec: 0
Decimal separator	Separator for the display of values
	Settings: Point or Comma
	Default setting: Point

11.2.9 Copyrights

Path: **Settings** ► **General** ► **Copyrights**

Parameter	Meaning and function
Open source software	Display of the licenses of the software used

11.2.10 Service info

Path: Settings ► General ► Service info

Parameter	Meaning and function
HEIDENHAIN - Customer service	Display of a document containing HEIDENHAIN service addresses
OEM service info	Display of a document containing service information from the machine manufacturer
	 Default: document containing HEIDENHAIN service addresses
	Further information: "Adding documentation", Page 117

11.2.11 Documentation

Path: **Settings** ► **General** ► **Documentation**

Parameter	Meaning and function	
Operating Instructions	Display of the operating instructions stored on the product Default: no document; the document in the desired language can be added	
	Further information: "Documentation", Page 220	

11.3 Sensors

This chapter describes settings for configuring the sensors.

11.3.1 Touch probe

Path: **Settings** ► **Sensors** ► **Touch probe**

Parameters	Explanation
Touch probe	Activates or deactivates the connected touch probe for use
	Setting range: ON or OFF
	Default value: OFF
Diameter	Diameter of the touch probe
	■ Setting range: ≥ 0.0001
	Default value: 6.0000
Evaluation of the ready signal	Possibility of setting whether the ready signal of the touch probe should be evaluated
	Setting range: ON or OFF
	Default value: ON

11.4 Interfaces

This chapter describes settings for configuring networks, network drives, and USB mass storage devices.

11.4.1 Network

Path: Settings ► Interfaces ► Network ► X116



Contact your network administrator for the correct network settings for configuring the product.

Parameter	Explanation	
MAC address	Unique hardware address of the network adapter	
DHCP	Dynamically assigned network address of the product	
	Settings: ON or OFF	
	Default value: ON	
IPv4 address	Network address consisting of four octets	
	The network address is automatically assigned if DHCP is active, or it can be entered manually	
	Setting range: 0.0.0.1 255.255.255.255	
IPv4 subnet mask	Identifier within the network, consisting of four octets	
	The subnet mask is automatically assigned if DHCP is active, or it can be entered manually.	
	Setting range: 0.0.0.0 255.255.255.255	
IPv4 standard gateway	Network address of the router connecting a network	
	The network address is automatically assigned if DHCP is active, or it can be entered manually.	
	Setting range: 0.0.0.1 255.255.255.255	
IPv6 SLAAC	Network address with extended namespace	
	Only required if supported in the network	
	Settings: ON or OFF	
	Default value: OFF	
IPv6 address	Automatically assigned if IPv6 SLAAC is active	
IPv6 subnet prefix length	Subnet prefix in IPv6 networks	
IPv6 standard gateway	Network address of the router connecting a network	
Preferred DNS server	Primary server for mapping the IP address	
Alternative DNS server	Optional server for mapping the IP address	

11.4.2 Network drive

Path: Settings ► Interfaces ► Network drive



Contact your network administrator for the correct network settings for configuring the product.

Parameter	Explanation		
Name	Folder name displayed in the file management		
	Default value: Share (cannot be changed)		
Server IP address or host name	Name or network address of the server		
Shared folder	Name of the shared folder		
User name	Name of the authorized user		
Password	Password of the authorized user		
Show password	Display of the password in plain text Settings: ON or OFF Default value: OFF		
Network drive options	Configuration of the Authentication for encrypting the password in the network Settings: None Kerberos V5 authentication Kerberos V5 authentication and packet signing NTLM password hashing NTLM password hashing with signing		
	 NTLMv2 password hashing NTLMv2 password hashing with signing Default value: None Configuration of the Mount options Settings: Default value: nounix,noserverino 		

11.4.3 USB

Path: Settings ► Interfaces ► USB

Parameter	Explanation
Automatically detect attached USB mass storage devices	Automatic recognition of a USB mass storage device Settings: ON or OFF
	■ Default setting: ON

11.4.4 RS-232

Path: Settings ► Interfaces ► RS-232 ► X32

The parameters of the **RS-232** adapter are output.

Parameter	Explanation
Baud rate	Configuration of the transfer rate
	Setting range: 1 115200
Data bits	Selection of the number of data bits
	Settings:
	5 bits
	■ 6 bits
	■ 7 bits
	■ 8 bits
Parity	Selection of the parity bit for verification
	Settings:
	None
	Even
	■ Odd
	Space
	■ Mark
Stop bits	Selection of the stop bit for synchronization
	Settings:
	■ 1 bit
	2 bits
Flow control	Selection of the data flow
	Settings:
	None
	Hardware
	Xon/Xoff

11.4.5 Data transfer

Path: Settings ► Interfaces ► Data transfer



The **Standard** and **Steinwald** data formats transfer measured values only when the following axis names are assigned: X, Y, Z, Q, R, D, L, W, A, C, f, Lx, Ly, or Lz.

The minimum, maximum, and range values are transferred only if the axis names X, Y, or Q are assigned.

Parameter	Explanation
RS-232	Selection of the serial port
	Settings:
	■ None
	■ X32
	Default value: None
Data format for data transfer	Selection of the data format for measured value output
	Settings:
	Standard
	Steinwald
	MyFormat1 (template for copying)
	Any data formats you have defined yourself
	Default value: Standard
Data format for touch-probe-	Selection of the data format for measured value output
triggered data transfer	Settings:
	Standard
	Steinwald
	MyFormat1 (template for copying)
	Any data formats you have defined yourself
	Default value: Standard
Data format for continuous data	Selection of the data format for measured value output
transfer	Settings:
	Standard
	Steinwald
	MyFormat1 (template for copying)
	 Any data formats you have defined yourself
	Default value: Standard

Parameter	Explanation
Data format for switching-	Selection of the data format for measured value output.
function-triggered data transfer	You must assign a digital input for the Trigger measured value output switching function.
	Further information: "Switching functions", Page 199
	Settings:
	Standard
	Steinwald
	MyFormat1 (template for copying)
	Any data formats you have defined yourself
	Default value: Standard

11.4.6 Switching functions

Path: Settings ► Interfaces ► Switching functions

Parameter	Explanation	
Axes	Configuration of the inputs for the purpose of setting all of the axes, or individual axes, to zero	
Switch the unit for linear values	Assignment of the digital input in accordance with the pin layout	
Switch the unit for angular	in order to execute the respective function	
values	Default setting: Not connected	
Trigger measured value output	Assignment of the digital input in accordance with the pin layout in order to trigger a transmission of measured values.	
	You can assign the data format you desire.	
	Further information: "Data transfer", Page 198	
	Default setting: Not connected	
Reset MinMax measurement	Assignment of the digital input in accordance with the pin layout in order to reset a MInMax measurement.	
	Default setting: Not connected	

11.4.7 Position-dependent switching functions

Path: Settings ▶ Interfaces ▶ Position-dependent switching functions

The position-dependent switching functions enable you to set logical outputs depending on the position of an axis in a defined reference system.

Parameter	Explanation
Output	Selecting the desired output
	X113.04 (Dout 0)

11.5 User

This chapter describes settings for configuring users and user groups.

11.5.1 **OEM**

Path: Settings ▶ User ▶ OEM

The **OEM** (Original Equipment Manufacturer) user has the highest level of permissions. This user is allowed to configure the product's hardware (e.g. connection of encoders and sensors). He can create **Setup** and **Operator**-type users, and configure the **Setup** and **Operator** users. The **OEM** user cannot be duplicated or deleted. This user cannot be logged in automatically.

Parameters	Explanation	Edit permission
Name	Name of the user	_
	■ Default value: OEM	
First name	First name of the user	_
	Default value: –	
Department	Department of the user	_
	Default value: –	
Group	Group of the user	_
	Default value: oem	
Password	Password of the user	OEM
	Default value: oem	
Language	Language of the user	OEM
Auto login	On restart of the product: Automatic login of the last logged-in user Default value: OFF	-
Remove user account	Removal of the user account	_

11.5.2 Setup

Path: Settings ► User ► Setup

The **Setup** user configures the product for use at the place of operation. This user can create **Operator**-type users. The **Setup** user cannot be duplicated or deleted. This user cannot be logged in automatically.

Parameters	Explanation	Edit permission
Name	Name of the user	_
	Default value: Setup	
First name	First name of the user	_
	Default value: –	
Department	Department of the user	_
	Default value: –	
Group	Group of the user	_
	Default value: setup	

Parameters	Explanation	Edit permission
Password	Password of the user Default value: setup	Setup, OEM
Language	Language of the user	Setup, OEM
Auto login	On restart of the product: Automatic login of the last logged-in user	-
	Default value: OFF	
Remove user account	Removal of the user account	_

11.5.3 Operator

Path: **Settings** ▶ **User** ▶ **Operator**

The **Operator** user is permitted to use the basic functions of the product. An **Operator**-type user cannot create additional users, but is allowed to edit various operator-specific settings, such as his name or the language. A user of the **Operator** group can be logged in automatically as soon as the product is switched on.

Parameters	Explanation	Edit permission
Name	Name of the user	Operator, Setup, OEM
	Default value: Operator	
First name	First name of the user	Operator, Setup, OEM
Department	Department of the user	Operator, Setup, OEM
	Default value: –	
Group	Group of the user	_
	Default value: operator	
Password	Password of the user	Operator, Setup, OEM
	Default value: operator	
Language	Language of the user	Operator, Setup, OEM
Auto login	On restart of the product: Automatic login of the last logged-in user	Operator, Setup, OEM
	Settings: ON or OFF	
	Default value: OFF	
Remove user account	Removal of the user account	Setup, OEM

11.5.4 Adding User

Path: Settings ▶ User ▶ +

Parameter	Explanation
+	Adds a new user of the type Operator
丁	Further information: "Entering and configuring users", Page 128
	It is not possible to add further OEM and Setup -type users.

11.6 Axes

This chapter describes settings for configuring the axes and assigned devices.



Not all of the described parameters and options may be available, depending on the product version, configuration and the connected encoders.

11.6.1 Reference marks

Path: Settings ► Axes ► General settings ► Reference marks

Parameters	Explanation
Reference mark search after	Setting for the reference mark search after unit start
unit start	Settings:
	ON: The reference mark search must be performed after startup
	 OFF: No prompt for a mandatory reference mark search is displayed after startup of the product
	■ Default value: ON
All users can cancel reference mark search	Specifies whether the reference mark search can be canceled by all user types
	Settings
	ON: The reference mark search can be canceled by users of any type
	 OFF: The reference mark search can only be canceled by users of the OEM or Setup type
	■ Default value: OFF
Reference mark search	Start starts the reference mark search and opens the workspace
Reference mark search status	Indicates whether the reference mark search was successful
	Display:
	Successful
	Unsuccessful
Stop of reference mark search	Indicates whether the reference mark search was canceled
-	Display:
	■ Yes
	■ No

11.6.2 Information

Path: Settings ► Axes ► General settings ► Information

Parameters	Explanation
Assignment of the encoder inputs to the axes	Shows the assignment of the encoder inputs to the axes
Assignment of the analog outputs to the axes	Shows the assignment of the analog outputs to the axes
Assignment of the analog inputs to the axes	Shows the assignment of the analog inputs to the axes
Assignment of the digital outputs to the axes	Shows the assignment of the digital outputs to the axes
Assignment of the digital inputs to the axes	Shows the assignment of the digital inputs to the axes



With the **Reset** buttons, the assignments for the inputs and outputs can be reset.

11.6.3 Error compensation

Path: Settings ► Axes ► General settings ► Error compensation

Parameter	Explanation
Nonlinear error compensation (NLEC)	Mechanical influences on the ${f X}$ and ${f Y}$ axes are compensated
Squareness error compensation (SEC)	Mechanical influences on the squareness of the X , Y and Z axes relative to each other are compensated

11.6.4 Nonlinear error compensation (NLEC)

Path: Settings ► Axes ► General settings ► Error compensation ► Nonlinear error compensation (NLEC)

Parameter	Explanation
Compensation	Mechanical influences on the axes of the machine are compensated
	Settings:
	ON: Compensation is active
	OFF: Compensation is not active
	Default value: OFF
Number of supporting points	Number of measuring points for error compensation on both axes (X and Y) of the encoder
	Setting range: 1 99 (X and Y)
	Default value: 2 (X and Y)

Parameter	Explanation	
Spacing of the supporting points	Spacing of the compensation points on the axes (X and Y) Setting range: 0.00001 mm 100.00000 mm (X and Y) Default value: 1.00000 mm (X and Y)	
Read deviations of calibration standard	A file containing the deviations of the calibration standard is read	
Import table of supporting points	 Uploading a file in .txt-format with position information regarding the supporting points in .xml format with position information regarding the supporting points and the deviations of the calibration standard 	
Export table of supporting points	A file containing the position indications of the supporting points and the deviations of the calibration standard is saved	
Table of supporting points	Opens the table of supporting points for manual editing	

11.6.5 Squareness error compensation (SEC)

Path: Settings ► Axes ► General settings ► Error compensation ► Squareness error compensation (SEC)

Parameter	Explanation
XY plane	Mechanical influences on the squareness of the axes relative to
XZ Plane	each other are compensated
	── Setting range: 85° 95°
YZ plane	Default value: 90

11.6.6 Alias assignment for axis names

Path: Settings ► Axes ► General settings ► Alias assignment for axis names

You can assign new axis names for the following axes: C1, C2, and C3. The respective axis name is a two-digit numerical value, a two-character combination of letters, or a two-character combination of a numerical value and a letter.

Parameter	Explanation
C1	Setting range: 00 99 and aA xX
C2	■ Default value: X (for C1)
C3	Default value: Y (for C2)
	Default value: Z (for C3)

11.6.7 <Axis name> (settings of the axis)

Path: Settings ► Axes ► <Axis name>

Parameters	Explanation
Axis name	Selection of the axis name displayed in the position preview

Parameters	Explanation	
Axis type	Definition of the axis type	
	Settings:	
	Not defined	
	Axis	
	 Coupled axis: Axis whose position value is offset against a principal axis 	
	Coupled axes do not appear in the position display. The position axis shows only the principal axis with the calculated position value of both axes.	
	For coupled axes, the product adapts the axis name automatically. The axis name consists of the name of the principal axis and the selected calculation type, e.g. +X.	
	■ Default value: Axis	
Encoder	Configuration of the connected encoder	
	Further information: "Encoder", Page 206	
Error compensation	Configuration of the linear error compensation LEC or segmented linear error compensation SLEC	
	Further information: "Linear error compensation (LEC)", Page 215	
	Further information: "Segmented linear error compensation (SLEC)", Page 215	
Coupled main axis	For axes of the Coupled axis type:	
	Selecting the principal axis to be coupled with the axis	
	Default value: None	
Calculation with main axis	For axes of the Coupled axis type:	
	Calculation type for the position values of the principal (main) axis and coupled axis Settings:	
	 +: The position values are added (principal axis + coupled axis) 	
	 -: The position values are subtracted (principal axis – coupled axis) 	
	Default value: +	

11.6.8 Encoder

Path: Settings ► Axes ► <Axis name> ► Encoder

Settings for encoders with interfaces of the EnDat 2.2 type

Parameter	Explanation	
Encoder input	Assignment of the encoder input to the axis of the product	
	Settings:	
	Not connected	
	■ X1	
	■ X2	
	■ X3	
	Further information: "Device overview", Page 43	
Interface	Automatically detected EnDat interface type	
ID label	Information about the encoder that was read out from the electronic ID label	
Diagnosis	Results of encoder diagnostics, evaluation of encoder function (e.g., based on functional reserves)	
Encoder model	Connected encoder model	
	Settings:	
	Linear encoder: Linear axis	
	Angle encoder: Rotary axis	
	Angle encoder as linear encoder: Rotary axis is displayed as linear axis	
	Default value: Depending on the connected encoder	
Mechanical ratio	For display of a rotary axis as a linear axis: traverse path in mm per revolution	
	■ Setting range: 0.1 mm 1000 mm	
	■ Default value: 1.0	
Reference point displacement	Configuration of the offset between the reference mark and the zero point	
	Further information: "Reference point displacement", Page 211	

Using an Angle encoder as linear encoder

Certain parameters must be taken into account when configuring angle encoder or rotary encoder as a linear encoder, in order to prevent an overrun of the system.

- The mechanical ratio must be chosen such that the maximum traverse range of 21474.483 mm is not exceeded
- The reference mark shift should only be used when considering the maximum traverse range of ±21474.483 mm, since this limit applies both with and without a reference mark shift
- Only for multiturn rotary encoders with EnDat 2.2: the rotary encoder must be mounted such that an overrun of the rotary encoder does not affect the machine coordinates negatively

Settings for encoders with interfaces of the type 1 V_{PP} or 11 μA_{PP}

Parameter Explanation	
Encoder input	Assignment of the encoder input to the axis of the product Settings: Not connected
	■ X1
	■ X2
	■ X3
	Further information: "Device overview", Page 43
Incremental signal	Signal of the connected encoder
	Settings:
	1 Vpp: Sinusoidal voltage signal
	11 μApp: Sinusoidal current signal
	Default value: 1 Vpp
Encoder model	Connected encoder model
	Settings:
	Linear encoder: Linear axis
	Angle encoder: Rotary axis
	Angle encoder as linear encoder: Rotary axis is displayed as linear axis
	Default value: Depending on the connected encoder
Signal period	For linear encoders Length of a signal period
	Setting range: 0.001 μm 1000000.000 μm
	Default value: 20.000
Line count	For angle encoders and for display of a rotary axis as a linear axis.
	Number of lines
	Setting range: 1 1000000
	Default value: 1000
Teach sequence	Starts the teach sequence for determining the Line count for an angle encoder based on a specified angle of rotation.
Display mode	For angle encoders and for the display of a rotary axis as a linear axis.
	Settings:
	■ -∞ ∞
	■ 0° 360°
	■ -180° 180°
	■ Default value: - ∞ ∞
Mechanical ratio	For display of a rotary axis as a linear axis: traverse path in mm per revolution
	Setting range: 0.1 mm 1000 mm
	Default value: 1.0
	= Delault value. 1.0
 Reference marks	Configuration of the Reference marks

Parameter	Explanation
Analog filter frequency	Frequency value of the analog low-pass filter
	Settings:
	 33 kHz: Suppression of interference frequencies above 33 kHz
	400 kHz: Suppression of interference frequencies above 400 kHz
	Default value: 400 kHz
Ferminating resistor	Dummy load to avoid reflections
	Settings: ON or OFF
	Default value: ON
Frror monitor	Monitoring of signal errors
	Settings:
	Off: Error monitoring not active
	Amplitude: Error monitoring of the signal amplitude
	■ Frequency : Error monitoring of the signal frequency
	■ Frequency & amplitude: Error monitoring of the signal
	amplitude and signal frequency
	Default value: Frequency & amplitude
	A warning or error message is displayed if one of the limit values for error monitoring is exceeded.
	The limit values depend on the signal of the connected encoder: Signal 1 Vpp, setting Amplitude
	■ Warning with voltage ≤ 0.45 V
	■ Error message with voltage ≤ 0.18 V or ≥ 1.34 V
	■ Signal 1 Vpp , setting Frequency
	■ Error message with frequency ≥ 400 kHz
	■ Signal 11 μApp , setting Amplitude
	■ Warning with current ≤ 5.76 µA
	■ Error message with current ≤ 2.32 μA or ≥ 17.27 μA
	■ Signal 11 μApp, setting Frequency
	■ Error message with frequency ≥ 150 kHz
Counting direction	Signal detection during axis movement
-	Settings:
	Positive: The direction of traverse corresponds to the counting direction of the encoder
	 Negative: The direction of traverse does not correspond to the counting direction of the encoder
	 Default value: Positive
Diagnosis	Results of encoder diagnostics, evaluation of encoder function (e.g., based on Lissajous figure)

Settings for encoders with interfaces of the TTL type

Parameter	Explanation	
Encoder input	Assignment of the encoder input to the axis of the product	
	Settings:	
	■ X21	
	■ X22	
	■ X23	
	Further information: "Device overview", Page 43	
Interface	Automatically detected TTL interface type	
Encoder model	Connected encoder model	
	Settings:	
	Linear encoder: Linear axis	
	Angle encoder: Rotary axis	
	Angle encoder as linear encoder: Rotary axis is displayed as	
	linear axis	
	Default value: Depending on the connected encoder	
Signal period	For linear encoders	
	Length of a signal period	
	Setting range: 0.001 μm 1000000.000 μm	
	Default value: 20.000	
Output signals per revolution	For angle encoders and for display of a rotary axis as a linear axis Number of output signals	
	Setting range: 1 10000000	
	Default value: 18000	
Teach sequence	Starts the teach sequence for determining the Output signals per revolution for an angle encoder based on a specified angle	
	of rotation.	
Display mode	For angle encoders and for the display of a rotary axis as a linear	
	axis.	
	Settings:	
	■ - ∞ ∞	
	■ 0° 360°	
	■ -180° 180°	
	■ Default value: - ∞ ∞	
Mechanical ratio	For display of a rotary axis as a linear axis: traverse path in mm per revolution	
	■ Setting range: 0.1 mm 1000 mm	
	Default value: 1.0	
Reference marks	Configuration of the Reference marks	
Neterence marks	Further information: "Reference marks (Encoder)", Page 210	
Terminating resistor	-	
Terminating resistor	Dummy load to avoid reflections Settings: ON or OFF	

Parameter	Explanation	
Error monitor	Monitoring of signal errors	
	Settings:	
	Off: Error monitoring not active	
	Frequency: Error monitoring of the signal frequency	
	Default value: Frequency	
	A warning or error message is displayed if one of the limit values for error monitoring is exceeded.	
	The limit values depend on the signal of the connected encoder:	
	Error message with frequency ≥ 5 MHz	
Counting direction	Signal detection during axis movement	
	Settings:	
	Positive: The direction of traverse corresponds to the counting direction of the encoder	
	Negative: The direction of traverse does not correspond to the counting direction of the encoder	

11.6.9 Reference marks (Encoder)

Path: Settings ► Axes ► <Axis name> ► Encoder ► Reference marks



The reference mark search does not need to be performed for serial encoders with EnDat interface, because the axes are automatically homed.

Parameters	Explanation
Reference mark	Definition of the type of reference mark
	Settings:
	None: There is no reference mark
	One: The encoder has one reference mark
	■ Coded : The encoder has distance-coded reference marks
	For encoders with TTL interface:
	Reverse coded: The encoder has inverse-coded reference marks
	Default value: One
Maximum traverse path	For linear encoders with coded reference marks: maximum traverse path for determining the absolute position
	Setting range: 0.1 mm 10000.0 mm
	Default value: 20.0
Nominal increment	For angle encoders with coded reference marks: maximum nominal increment for determining the absolute position
	Setting range: > 0° 360°
	Default value: 10.0

Parameters	Explanation	
Interpolation	For encoders with TTL interface:	
	Interpolation value of the encoders and integrated interpolation for the evaluation of the coded reference marks.	
	Settings:	
	None	
	2-fold	
	■ 5-fold	
	■ 10-fold	
	20-fold	
	■ 50-fold	
	Default value: None	
Inversion of reference mark pulses	Specifies whether the reference mark pulses are evaluated in inverted form	
	Settings	
	ON: Reference pulses are evaluated in inverted form	
	OFF: Reference pulses are not evaluated in inverted form	
	Default value: OFF	
Reference point displacement	Configuration of the offset between the reference mark and the zero point	
	Further information: "Reference point displacement", Page 211	

11.6.10 Reference point displacement

Path: Settings ► Axes ► <Axis name> ► Encoder ► Reference marks ► Reference point displacement

Parameters	Explanation	
Reference point displacement	Activation of offset calculation between reference mark and datum of the machine	
	Setting range: ON or OFF	
	Default value: OFF	
Reference point displacement	Manual input of the offset (in mm or degrees according to the selected encoder type) between reference mark and datum	
	Default value: 0.00000	
Current position for reference point shift	Apply applies the current position as an offset (in mm or degrees, depending on the selected encoder model) between the reference mark and the zero point	

11.6.11 Diagnostics for encoders with EnDat interface

Path: Settings ► Axes ► <Axis name> ► Encoder ► Diagnosis

Message Description		
Encoder error	Encoder errors indicate a malfunction of the encoder Examples of encoder errors that may be displayed: Failure of the light unit Incorrect signal amplitude Incorrect position Overvoltage Undervoltage supply Overcurrent	
Encoder warning	 Battery failure Encoder warnings indicate that certain tolerance limits of the encoder have been reached or exceeded Examples of encoder warnings that may be displayed: Frequency collision Temperature exceedance Light-source control reserve Battery charge Reference point 	

The messages can have the following status:

Status	Evaluation	
OK!	The encoder is within the specification	
Not supported	Message not supported by the encoder	
Error!	Servicing/maintenance recommended; detailed analyses recommended (e.g., with PWT 101)	

Path: Settings ► Axes ► <Axis name> ► Encoder ► Diagnosis ► Functional reserves

Parameter	Explanation	
Absolute track	Displays the functional reserves of the absolute track	
Incremental track	Displays the functional reserves of the incremental track	
Position value calculation	Displays the functional reserves of position value calculation	
Position	Displays the actual current position of the encoder	

The product displays the functional reserves in a bar graph:

Color	Range	Evaluation
Yellow	0 % to 25 %	Servicing/maintenance recommended; testing recommended (e.g., with PWT 101)
Green	25 % to 100 %	The encoder is within the specification

11.6.12 Diagnostics for encoders with 1 $V_{PP}/11 \mu A_{PP}$

Path: Settings ► Axes ► <Axis name> ► Encoder ► Diagnosis

Parameter	Explanation
Amplitude A	Display of amplitude A in volts (V)
Amplitude B	Display of amplitude B in volts (V)
Asymmetry	Asymmetry value
Rapid traverse speed for radial movements	Phase deviation from 90°
Freeze graph	 Freezing of Lissajous figure Settings: ON: The graph is frozen and is not updated when the encoder is moved OFF: The graph is not frozen and is updated when the encoder is moved Default value: OFF
Show tolerance range	Display of tolerance circles in a range from 0.6 V to 1.2 V Settings: ON: Two red circles are shown OFF: Tolerance circles are hidden Default value: OFF
Encoder input for comparative measurement	Display of another encoder at another encoder input for comparative measurement; the Freeze graph parameter allows you to superimpose the circles Settings: Selection of desired encoder input Default value: Not connected
	The parameter is available only if another encoder with 1 V _{PP} or 11 µA _{PP} interface is connected.
Freeze comparative	The Lissajous figure of the encoder at the encoder

Freeze comparative graph

The Lissajous figure of the encoder at the encoder input is frozen for comparative measurement Settings:

- **ON**: The graph is frozen and is not updated when the encoder is moved
- **OFF**: The graph is not frozen and is updated when the encoder is moved
- Default value: **OFF**



The parameter is available only if another encoder with 1 V_{PP} or 11 μA_{PP} interface is connected.

11.6.13 Linear error compensation (LEC)

Path: Settings ► Axes ► <Axis name> ► Error compensation ► Linear error compensation (LEC)

Parameter	Explanation
Compensation	Mechanical influences on the axes of the machine are compensated
	Settings:
	ON: Compensation is active
	OFF: Compensation is not active
	Default value: OFF
	If Compensation is active, the Nominal length and Actual length cannot be edited or generated.
Nominal length	Input field for the length of the calibration standard according to the manufacturer's specifications
	Input: Millimeters or degrees (depending on the encoder)
Actual length	Input field for entering the measured length (actual distance traversed)
	Input: millimeters or degrees (depending on the encoder)

11.6.14 Segmented linear error compensation (SLEC)

Path: Settings ► Axes ► <Axis name> ► Error compensation ► Segmented linear error compensation (SLEC)

Parameters	Explanation
Compensation	Mechanical influences on the axes of the machine are compensated
	Settings:
	ON: Compensation is active
	OFF: Compensation is not active
	Default value: OFF
	When Compensation is active, then the Table of supporting points cannot be edited or created.
Table of supporting points	Opens the table of supporting points for manual editing
Create table of supporting points	Opens the menu for creating a new Table of supporting points
	Further information: "Create table of supporting points",

Page 216

11.6.15 Create table of supporting points

Path: Settings ► Axes ► <Axis name> ► Error compensation ►

Segmented linear error compensation (SLEC) ▶ Create table of supporting points

Parameters	Explanation
Number of supporting points	Number of supporting points on the mechanical axis of the machine
	Setting range: 2 200
	Default value: 2
Spacing of the supporting points	Spacing of the supporting points on the mechanical axis of the machine
	Default value: 100.00000
Start point	The start point defines the position starting from which the compensation is applied to the axis
	Default value: 0.00000
Create	Creates a new table of supporting points based on the entries

11.7 Service

This chapter describes settings for product configuration, for maintaining the firmware and for enabling software options.

This chapter describes the settings for the product configuration and for the maintenance of the firmware.

11.7.1 Firmware information

Path: Settings ► Service ► Firmware information

The following information on the individual software modules is displayed for service and maintenance.

Parameter	Explanation	
Core version	Version number of the microkernel	
Microblaze bootloader version	Version number of the Microblaze bootloader	
Microblaze firmware version	Version number of the Microblaze firmware	
Extension PCB bootloader version	Version number of the bootloader (expansion board)	
Extension PCB firmware version	Version number of the firmware (expansion board)	
Boot ID	ID number of the boot process	
HW Revision	Revision number of the hardware	
C Library Version	Version number of the C library	
Compiler Version	Version number of the compiler	
Touchscreen Controller version	Version number of the touchscreen controller	
Qt build system	Version number of the Qt compilation software	
Qt runtime libraries	Version number of the Qt runtime libraries	
Kernel	Version number of the Linux kernel	
Login status	Information on the logged-in user	
SystemInterface	Version number of the system interface module	
BackendInterface	Version number of the backend interface module	
Guilnterface	Version number of the user interface module	
TextDataBank	Version number of the text database module	
Optical edge detection	Version number of the optical edge detection module	
Metrology	Version number of the metrology module	
NetworkInterface	Version number of the network interface module	
OSInterface	Version number of the operating system interface module	
PrinterInterface	Version number of the printer interface module	
Programming	Version number of the programming module	
system.xml	Version number of the system parameters	
axes.xml	Version number of the axis parameters	
encoders.xml	Version number of the encoder parameters	
ncParam.xml	Version number of the NC parameters	

Parameter	Explanation		
io.xml	Version number of the parameters for inputs and outputs		
opticalEdge.xml	Version number of the parameters for OED		
peripherals.xml	Version number of the parameters for peripherals		
slec.xml	Version number of the parameters for segmented linear error compensation (SLEC)		
lec.xml	Version number of the parameters for linear error compensation (LEC)		
nlec.xml	Version number of the parameters for nonlinear error compertion (NLEC)		
microBlazePVRegister.xml	Version number of the "Processor Version Register" of MicroBlaze		
info.xml	Version number of the information parameters		
audio.xml	Version number of the audio parameters		
metrology.xml	Metrology parameters		
network.xml	Version number of the network parameters		
os.xml	Version number of the operating system parameters		
runtime.xml	Version number of the runtime parameters		
serialPort.xml	Version number of the parameters of the serial interface		
users.xml	Version number of the user parameters		
GI Patch Level	Patch level of the golden image (GI)		

11.7.2 Back up and restore

Path: Settings ► Service ► Back up and restore

The unit's settings or user files can be backed up as a file so that they are available after a reset to the factory default settings has been performed or for installation on multiple units.

Parameters	Explanation	
Restore settings	Restoring of the backed up settings	
	Further information: "Restore settings", Page 234	
Back up settings	Backing up of settings of the product	
	Further information: "Back up settings", Page 120	
Restore user files	Restoring of user files of the product	
	Further information: "Restore user files", Page 233	
Back up user files	Backing up of user files of the product	
	Further information: "Back up user files", Page 121	

11.7.3 Firmware update

Path: Settings ► Service ► Firmware update

The firmware is the operating system of the product. You can import new versions of the firmware via the product's USB port or the network connection.



Prior to the firmware update, you must comply with the release notes for the respective software version and the information they contain regarding reverse compatibility.



In order to be on the safe the side, the current settings must be backed up if the unit's firmware is going to be updated.

Further information: "Updating the firmware", Page 226

11.7.4 Reset

Path: Settings ► Service ► Reset

If necessary, you can reset the unit's settings to the factory default settings or to the condition at delivery. Software options are deactivated and subsequently need to be reactivated with the available license key.

Parameter	Explanation
Reset all settings	The settings are reset to factory default settings
	Further information: "Reset all settings", Page 235
Reset to shipping conditions	Resetting of the settings to the factory default setting and deletion of the user files from the unit's memory area
	Further information: "Reset to shipping conditions", Page 235

11.7.5 OEM area

Path: Settings ► Service ► OEM area

Parameters	Explanation		
Documentation	Addition of OEM documentation, e.g. service information		
	Further information: "Adding documentation", Page 117		
Startup screen	Changing the startup screen (e.g., with one's own company logo)		
	Further information: "Startup screen", Page 220		
Remote access for screenshots	Permitting a network connection with the ScreenshotClient program so that ScreenshotClient can take screenshots of the unit from a computer		
	Settings:		
	■ ON : Remote access is possible		
	■ OFF : Remote access is not possible		
	Default value: OFF		

11.7.6 Startup screen

Path: Settings ► Service ► OEM area ► Startup screen

Parameter	Explanation	
Add startup screen	Selecting the image file that is to be displayed as opening scree (file type: PNG or JPG)	
	Further information: "Adding a startup screen", Page 117	
Delete startup screen	Delete clears the user-defined opening screen and restores the default view	

11.7.7 Documentation

Path: Settings ► Service ► Documentation

The product provides the possibility to upload the corresponding Operating Instructions in the desired language. The Operating Instructions can be copied from the supplied USB mass storage device to the product.

The latest version can be downloaded from the download area at **www.heidenhain.com**.

Parameters	Explanation
Add Operating Instructions	Adding the Operating Instructions in the desired language

11.7.8 Software options

Path: Settings ► Service ► Software options



Software options need to be enabled on the product via a license key. Before you can use the associated hardware components, you need to enable the respective software option.

Further information: "Activating the Software options", Page 81

Parameter	Explanation	
Overview	Overview of all software options that are active on the product	
Request options	Creation of a license key request that can be submitted to a HEIDENHAIN service agency	
	Further information: "Requesting license key", Page 81	
Request trial options Creation of a license key request that can be submitt HEIDENHAIN service agency		
	Further information: "Requesting license key", Page 81	
Activate options Activation of the software options via license key or license ke		
	Further information: "Activating a license key", Page 82	
Reset trial options	Reset of the trial options by entering a license key	

12

Servicing and maintenance

12.1 Overview

This chapter describes the general maintenance work on the product.



The following steps must be performed only by qualified personnel.

Further information: "Personnel qualification", Page 25



This chapter contains a description of maintenance work for the product only. Any maintenance work on peripheral devices is not described in this chapter.

Further information: Manufacturer's documentation for the respective peripheral devices

12.2 Cleaning

NOTICE

Cleaning with sharp-edged objects or aggressive cleaning agents

Improper cleaning will cause damage to the product.

- Never use abrasive or aggressive cleaners, and never use strong detergents or solvents
- Do not use sharp-edged objects to remove persistent contamination


Cleaning the housing

Use only a cloth dampened with water and a mild detergent for cleaning the exterior surfaces

Cleaning the screen

Activate cleaning mode to clean the display. This switches the unit to an inactive state without interrupting the power supply. The screen is switched off in this state.







- ► Tap Cleaning mode
- > The screen switches off
- ▶ Use a lint-free cloth and a commercially available glass cleaner to clean the screen



- ➤ To deactivate the cleaning mode, tap anywhere on the touchscreen
- > An arrow appears at the bottom of the screen
- Drag the arrow up
- The screen is switched on and shows the user interface last displayed

12.3 Maintenance plan

The product is largely maintenance-free.

NOTICE

Operating defective devices

Operating defective devices may result in serious consequential damage.

- ▶ Do not repair or operate the device if it is damaged
- Replace defective devices immediately or contact a HEIDENHAIN service agency



The following steps are only to be performed by electrical specialists.

Further information: "Personnel qualification", Page 25

M	aintenance step	Interval	Corrective action
>	All labels and symbols provided on the product must be checked for readability	Annually	Contact HEIDENHAIN service agency
•	Inspect electrical connections for damage and check their function	Annually	 Replace defective cables. Contact HEIDENHAIN service agency if required
>	Check power cables for faulty insulation and weak points	Annually	 Replace power cables according to the specification

12.4 Resuming operation

When operation is resumed, e.g. when the product is reinstalled after repair or when it is remounted, the same measures and personnel requirements apply as for mounting and installing the product.

Further information: "Mounting", Page 35 **Further information:** "Installation", Page 41

When connecting the peripheral devices (e.g. encoders), the operating company must ensure safe resumption of operation and assign authorized and appropriately qualified personnel to the task.

Further information: "Obligations of the operating company", Page 25

12.5 Updating the firmware

The firmware is the operating system of the product. You can import new versions of the firmware via the product's USB port or the network connection.



Prior to the firmware update, you must comply with the release notes for the respective software version and the information they contain regarding reverse compatibility.



In order to be on the safe the side, the current settings must be backed up if the unit's firmware is going to be updated.

Prerequisite

- The new firmware is available as a *.dro file
- To update the firmware over the USB port, the current firmware must be stored on a USB mass storage device (FAT32 format)
- To update the firmware via the network interface, the current firmware must be available in a folder on the network drive

Starting a firmware update



- ► Tap **Settings** in the main menu
- ▶ Tap Service
- ► Open in succession:
 - Firmware update
 - Continue
- > The service application is launched

Updating the firmware

The firmware can be updated from a USB mass storage device (FAT32 format) or via a network drive.



- ► Tap Firmware update
- ▶ Tap Select
- ► If required, connect a USB mass storage device to a USB port of the product
- Navigate to the folder containing the new firmware



If you have accidentally tapped the wrong folder, you can return to the previous folder.

- ► Tap the file name that is displayed above the list
- Select the firmware
- ► Tap **Select** to confirm the selection
- > The firmware version information is displayed
- ► Tap **OK** to close the dialog



The firmware update cannot be canceled once the data transfer has started.

- ► Tap **Start** to start the update
- > The screen shows the progress of the update
- ► Tap **OK** to confirm successful update
- ► Tap **Finish** to terminate the service application
- > The service application is terminated
- > The main application is launched
- If automatic user login is active, the user interface is displayed in the **Measure** menu
- If automatic user login is not active, the User login menu is displayed



- ► Tap File management in the main menu
- Navigate to the list of storage locations
- ► Tap Safely remove
- The message "The storage medium can be removed now." appears
- Disconnect the USB mass storage device

12.6 Encoder diagnostics

The diagnostic function allows you to perform a basic functional check of the encoders. For absolute encoders with EnDat interface, the messages from the encoder and its functional reserves are displayed. For incremental encoders with 1 V_{PP} or 11 μA_{PP} interface, the displayed values allow you to evaluate the fundamental functioning of the encoders. Based on this initial diagnostic option for encoders, you can initiate further actions for more detailed testing or repair.




The PWT 101 or PWM 21 from HEIDENHAIN provides further inspection and testing capabilities.

For more information, please refer to **www.heidenhain.com**.

12.6.1 Diagnostics for encoders with 1 V_{PP}/11 μA_{PP} interface

For encoders with 1 $V_{PP}/11~\mu A_{PP}$ interface, you can evaluate the functioning of the encoder based on the signal amplitudes, asymmetry, and phase deviation. These values are also displayed graphically as a Lissajous figure.



- 1 Lissajous figure
- 2 Amplitude A
- 3 Amplitude B
- **4** Asymmetry
- **5** Phase deviation
- 6 Amplitude tolerances

For encoders with 1 $V_{PP}/11 \mu A_{PP}$ interface, the following values are displayed:

- Amplitude A
- Amplitude B
- Asymmetry
- Rapid traverse speed for radial movements

The following parameters are available for evaluation:

Parameter	Explanation	
Freeze graph	Freezing of Lissajous figure Settings: ON: The graph is frozen and is not updated when the encoder is moved OFF: The graph is not frozen and is updated when the encoder is moved	
	Default value: OFF	
Show tolerance range	Display of tolerance range for the amplitudes 1 V _{PP} : 0.6 V to 1.2 V 11 μA _{PP} : 7 μA _{PP} to 16 μA _{PP}	
	Settings: ON: The tolerance range is displayed OFF: The tolerance range is hidden Default value: OFF	
Encoder input for comparative measurement	Display the encoder of another encoder input for comparison; the signals can be superimposed for comparison Settings: Selection of desired encoder input Default value: Not connected	
	The parameter is available only if another encoder with 1 V _{PP} or 11 μA _{PP} interface is connected.	
Freeze comparative graph	The Lissajous figure of the encoder at the encoder input is frozen for comparative measurement Settings: ON: The graph is frozen and is not updated when the encoder is moved OFF: The graph is not frozen and is updated when the encoder is moved Default value: OFF	
	The parameter is available only if another encoder with 1 V _{PP} or 11 μA _{PP} interface is connected.	



► Tap **Settings** in the main menu



- ► Tap **Axes**
- ▶ Open in succession:
 - <Axis name>
 - Encoder
 - Diagnosis
- ▶ To display the signals and values, move the encoder

12.6.2 Diagnostics for encoders with EnDat interface

You can check the encoders with EnDat interface for proper functioning by reading out the errors or warnings and by evaluating their functional reserves.

Depending on the encoder, not all of the functional reserves and messages are supported.

Functional reserves




Figure 40: Example of functional reserves of a length gauge

- 1 Minimum percentage value of functional reserves at this specific position
- 2 Absolute track
- 3 Incremental track
- 4 Position value calculation
- **5** Current position of encoder

The following functional reserves are displayed for absolute encoders with EnDat interface:

- Absolute track
- Incremental track
- Position value calculation

The product displays the functional reserves in a bar graph:

Color	Range	Evaluation
Yellow	0 % to 25 %	Servicing/maintenance recommended
Green	25 % to 100 %	The encoder is within the specification



► Tap **Settings** in the main menu



- ► Tap **Axes**
- ► Open in succession:
 - <Axis name>
 - Encoder
 - Diagnosis
 - Functional reserves
- ▶ To display the **Functional reserves**, move the encoder

Errors and warnings

The messages displayed by the product for the serial interface are classified as follows:

Message	Description
Encoder error	Encoder errors indicate a malfunction of the encoder Examples of encoder errors that may be displayed: Failure of the light unit Incorrect signal amplitude Incorrect position Overvoltage Undervoltage supply Overcurrent
	Battery failure
Encoder warning	Encoder warnings indicate that certain tolerance limits of the encoder have been reached or exceeded Examples of encoder warnings that may be displayed: Frequency collision Temperature exceedance Light-source control reserve Battery charge Reference point

The messages can have the following status:

Status	Evaluation	
OK!	The encoder is within the specification	
Not supported	Message not supported by the encoder	
Error!	Servicing/maintenance recommended; detailed analyses recommended (e.g., with PWT 101)	



► Tap **Settings** in the main menu



- ► Tap **Axes**
- ► Open in succession:
 - <Axis name>
 - Encoder
 - Diagnosis
- > Errors and warnings are displayed

12.7 Restoring files and settings

You can restore saved files and settings to a device. The following sequence should be followed when restoring files and settings:

- Restore OEM-specific folders and files
- Restore user files
- Restore settings

An automatic restart of the product is performed only after the settings have been restored.

12.7.1 Restore OEM-specific folders and files

Backed-up OEM-specific folders and files of the product can be loaded onto a device. This allows you to restore the configuration of a device while restoring the settings.

Further information: "Restore settings", Page 234

If servicing becomes necessary, an exchange unit can thus be operated with the configuration of the failed unit once the settings have been restored, provided that both units use the same or compatible firmware versions.



Tap Settings in the main menu



- ▶ Tap Service
- Tap OEM area
- Open in succession:
 - Back up and restore
 - Restore OEM specific folders and files
- Tap Load as ZIP
- ▶ If required, connect a USB mass storage device (FAT32 format) to a USB port of the product
- Navigate to the folder containing the backup file
- Select the backup file
- ▶ Tap Select
- ► Confirm the successful transfer with **OK**



There is no automatic restart when the OEM-specific folders and files are restored. A restart is performed when the settings are restored.

Further information: "Restore settings", Page 234

To restart the product with the transferred OEM-specific folders and files, switch the product off and then back on



- Tap File management in the main menu
- Navigate to the list of storage locations
- Tap Safely remove
 - The message "The storage medium can be removed now." appears
 - Disconnect the USB mass storage device

12.7.2 Restore user files

Backed-up user files of the product can be loaded into the product again. Existing user files will be overwritten. This, together with the restoring of the settings, enables you to restore the complete configuration of a unit.

Further information: "Restore settings", Page 234

If servicing becomes necessary, a replacement unit can be operated with the configuration of the failed unit after restoring. This requires that the version of the old firmware matches that of the new firmware or that the versions are compatible.



All files from all user groups that are stored in the respective folders are backed up and can be restored as user files.

The files in the **System** folder are not restored.



- ► Tap **Settings** in the main menu
- ▶ Open in succession:
- ▶ Tap Service
- Open in succession:
 - Back up and restore
 - Restore user files
- Tap Load as ZIP
- ▶ If required, connect a USB mass storage device (FAT32 format) to a USB port of the product
- ▶ Navigate to the folder containing the backup file
- Select the backup file
- ► Tap Select
- ► Confirm the successful transfer with **OK**



There is no automatic restart when the user files are restored. A restart is performed when the settings are restored.

"Restore settings"

► To restart the product with the transferred user files, switch the product off and then back on



- ▶ Tap **File management** in the main menu
- Navigate to the list of storage locations
- Tap Safely remove
 - > The message "The storage medium can be removed now." appears
 - Disconnect the USB mass storage device



12.7.3 Restore settings

Backed-up settings can be restored to the product. The current configuration of the product is replaced in the process.



Software options that were active when the settings were backed up must be activated before restoring the settings.

A restore can be necessary in the following cases:

During commissioning, the settings are set on a product and transferred to all identical products

Further information: "Steps for commissioning", Page 80

After a reset, the settings are copied back to the product
 Further information: "Reset all settings", Page 235



- ► Tap **Settings** in the main menu
- Open in succession:
 - Service
 - Back up and restore
 - Restore settings
- ► Tap Complete restoration
- ▶ If required, connect a USB mass storage device (FAT32 format) to a USB port of the product
- Navigate to the folder containing the backup file
- Select the backup file
- ► Tap **Select**
- ► Confirm the successful transfer with **OK**
- > The system is shut down
- ► To restart the product with the transferred configuration data, switch the product off and then back on



- Tap File management in the main menu
- Navigate to the list of storage locations



- ► Tap Safely remove
- The message "The storage medium can be removed now." appears
- ▶ Disconnect the USB mass storage device

12.8 Reset all settings

You can reset the settings of the product to the factory defaults if required. The software options are deactivated and must be subsequently reactivated with the available license key.



- ► Tap **Settings** in the main menu
- ▶ Tap Service
- ► Open in succession:
 - Reset
 - Reset all settings
- Enter password
- Confirm the entry with RET
- ► To show the password in plain text, activate **Show password**
- ► Tap **OK** to confirm the action
- ► Tap **OK** to confirm the reset
- ► Tap **OK** to confirm shutdown of the device
- > The product is shut down
- > All settings are reset
- > To restart the product, switch it off and then back on

12.9 Reset to shipping conditions

You can reset the settings of the product to the factory defaults and delete the user files from product's memory area. The software options are deactivated and must be subsequently reactivated with the available license key.



- ► Tap **Settings** in the main menu
- ► Tap Service
- ► Open in succession:
 - Reset
 - Reset to shipping conditions
- Enter password
- Confirm the entry with RET
- To show the password in plain text, activate Show password
- ► Tap **OK** to confirm the action
- ► Tap **OK** to confirm the reset
- ► Tap **OK** to confirm shutdown of the device
- > The product is shut down
- > All settings are reset and the user files are deleted
- > To restart the product, switch it off and then back on

13

What to do if ...

13.1 Overview

This chapter describes the causes of faults or malfunctions of the product and the appropriate corrective actions.



Make sure that you have read and understood the "Basic operation" chapter before carrying out the actions described below.

Further information: "Basic operation", Page 51

13.2 System or power failure

Operating system data can be corrupted in the following cases:

- System or power failure
- Switching off the product without shutting down the operating system

If the firmware is damaged, the product starts a Recovery System that displays short instructions on the screen.

With restoration, the Recovery System overwrites the damaged firmware with a new firmware previously saved to a USB mass storage device. During this procedure the settings of the product are deleted.

13.2.1 Restoring the firmware

- On a computer, create the folder "heidenhain" on a USB mass storage device (FAT32 format).
- ▶ In the "heidenhain" folder, create the folder "update"
- Copy the new firmware to the "update" folder
- ► Rename the firmware "recovery.dro"
- Switch off the product
- Connect a USB mass storage device to a USB port of the product
- Switch on the product
- > The product starts the Recovery System
- > The USB mass storage device is detected automatically
- > The firmware is installed automatically
- > After a successful update, the firmware is automatically renamed "recovery.dro.[yyyy.mm.dd.hh.mm]"
- Restart the product on completion of the installation
- > The product starts up with the factory defaults

13.2.2 Restore settings

Reinstalling the firmware resets the product to the factory defaults. This deletes the setting, including the error compensation values and the activated software options.

To restore settings, you must either reconfigure them on the unit yourself or restore previously backed up settings on the unit.



Software options that were active when the settings were backed up must be activated before restoring the settings on the product.

Activating software options

Further information: "Activating the Software options", Page 81

Restoring settings

Further information: "Restore settings", Page 234

13.3 Malfunctions

If faults or malfunctions that are not listed in the "Troubleshooting" table below occur during operation, refer to the machine tool builder's documentation or contact a HEIDENHAIN service agency.

13.3.1 Troubleshooting



The following troubleshooting steps must be performed only by the personnel indicated in the table.

Further information: "Personnel qualification", Page 25

Fault	Cause of fault	Correction of fault	Personnel
The status LED remains dark after switch-on	There is no supply voltage	► Check the power cable	Electrical specialist
	The product does not function properly	Contact a HEIDENHAIN service agency	Qualified personnel
A blue screen appears when the unit starts up	Firmware error during startup	 If this fault occurs for the first time, switch the product off and then on again If the fault recurs, contact a HEIDENHAIN service agency 	Qualified personnel
After startup, the product does not recognize any entries made on the touchscreen	Incorrect hardware initialization	Switch the product off and then on again	Qualified personnel
Axes do not count despite movement of the encoder	Incorrect connection of the encoder	 Correct the connection Contact the encoder manufacturer's service agency 	Qualified personnel
Axes are miscounting	Incorrect settings of the encoder	Check the encoder settings Page 91	Qualified personnel

Fault	Cause of fault	Correction of fault	Personnel
Connection to the network is not possible	Defective connection	Check the cable and the correct connection to X116	Qualified personnel
	Incorrect settings of the network	Check the network settings Page 132	Qualified personnel
The connected USB mass storage device is not detected	Defective USB connection	 Check the correct position of the USB mass storage device in the port Use another USB port 	Qualified personnel
	The type or format- ting of the USB mass storage device is not supported	 Use another USB mass storage device Format USB mass storage device with FAT32 	Qualified personnel
The unit starts in recovery mode (text only mode)	Firmware error during startup	 If this fault occurs for the first time, switch the product off and then on again If the fault recurs, contact 	Qualified personnel
		a HEIDENHAIN service agency	
User login is not possible	Password does not exist	 As user with higher permission level, reset the password Page 128 	Qualified personnel
		To reset the OEM password, contact the HEIDENHAIN service agency	
Data transfer does not work	Incorrect settings for data transfer	Check the configuration of the interface in the settings	Qualified personnel

Removal and disposal

14.1 Overview

This chapter contains information and environmental protection specifications that must be observed for correct disassembly and disposal of the device.

14.2 Removal



Removal of the product must be performed only by qualified personnel.

Further information: "Personnel qualification", Page 25

Depending on the connected peripherals, the removal may need to be performed by an electrical specialist.

In addition, the same safety precautions that apply to the mounting and installation of the respective components must be taken.

Removing the product

To remove the product, follow the installation and mounting steps in the reverse order.

Further information: "Installation", Page 41 Further information: "Mounting", Page 35

14.3 Disposal

NOTICE

Incorrect disposal of the product!

Incorrect disposal of the product can cause environmental damage.



- ▶ Do not dispose of electrical waste and electronic components in domestic waste
- The integrated backup battery must be disposed of separately from the product
- ► Forward the product and the backup battery to recycling in accordance with the applicable local disposal regulations
- ► If you have any questions about the disposal of the product, please contact a HEIDENHAIN service agency

Specifications

15.1 Overview

This chapter contains an overview of the product data and drawings with the product dimensions and mating dimensions.


15.2 Product data

Device	
Housing	Aluminum cast housing
Housing dimensions	200 mm x 169 mm x 41 mm
Fastener system, mating dimensions	Mounting hole pattern 50 mm x 50 mm
Display	
Visual display unit	LCD Widescreen (15:9)color screen 17.8 cm (7")800 x 480 pixels
Display step	Selectable, min. 0.00001 mm
User interface	User interface (GUI) with touchscreen
Electrical data	
Supply voltage	 AC 100 V 240 V (±10 %) 50 Hz 60 Hz (±5 %) Max. input power 38 W
Buffer battery	Lithium battery type CR2032; 3.0 V
Overvoltage category	II .
Number of encoder inputs	3
Encoder interfaces	 1 V_{PP}: maximum current 300 mA, max. input frequency 400 kHz 11 µA_{PP}: maximum current 300 mA, max. input frequency 150 kHz EnDat 2.2: maximum current 300 mA TTL: maximum current 300 mA, max. input frequency 5 MHz: maximum current
Interpolation at 1 V _{PP}	4096-fold
Touch probe connection	 Voltage supply DC 5 V or DC 12 V 5 V or floating switching output Four digital inputs: TTL DC 0 V to +5 V low-active One digital output TTL DC 0 V to +5 V Maximum load 1 kΩ Max. cable length with HEIDENHAIN cable 30 m

Electrical data	
Data interface	1 USB 2.0 Hi-Speed (Type A), maximum current 500 mA
	■ 1 Ethernet 10/100 Mbit/1 Gbit (RJ45)
Environment	
Operating temperature	0 °C to +45 °C
Storage temperature	–20 °C to +70 °C
Relative air humidity	10 % to 80 % RH, non-condensing
Altitude	≤ 2000 m
General information	
Directives	■ EMC Directive 2014/30/EU
	Low Voltage Directive 2014/35/EU
	RoHS Directive 2011/65/EU
Pollution degree	2
Protection EN 60529	Front panel and side panels: IP 65
	Rear panel: IP 40
Mass	■ 1.3 kg
	With Single-Pos stand: 1.35 kg
	With Duo-Pos stand 1.45 kg
	With Multi-Pos stand: 1.95 kg
	With Multi-Pos holder: 1.65 kg

15.3 Product dimensions and mating dimensions

All dimensions in the drawings are in millimeters.






Figure 41: Housing dimensions for products




Figure 42: Dimensions of the rear panel

15.3.1 Product dimensions with Single-Pos stand




Figure 43: Product dimensions with Single-Pos stand

15.3.2 Product dimensions with Duo-Pos stand




Figure 44: Product dimensions with Duo-Pos stand

15.3.3 Product dimensions with Multi-Pos stand




Figure 45: Product dimensions with Multi-Pos stand

15.3.4 Product dimensions with Multi-Pos holder




Figure 46: Product dimensions with Multi-Pos holder

16	Index	Diagnostics for encoders with EnDat interface	file types
_		Dial gage	Short description
Α		Activate axes	Firmware update
	sories 31	Activate the switching	Folder
	a startup screen 117	function	copying180
	nt conditions 245	configuring	creating
	bly 36	Enter values 141	deleting
	feedback75	General parameters 141	moving
	91, 94	Opening the overview 172	renaming
	s assignment for axis	Opening the single view 173	Folders
	es 86	Overview	managing 179
Sett	ings 204	Single view 173	Folder structure 179
В		Documentation	Functional reserves
	101 100	Addendum	function bar
Backing	g up user files 121, 160	download	Function elements 69
С		OEM 117	Add 7
	tion 102	Dragging 53	Adding 154
	ng the screen 224	Duo-Pos	Open
	number 58		Save 72
	ssioning 80	E	
	iter 49	Electrical specialist	G
Config		Encoders	Gestures
_	gage function 139	Axis parameter configuration (1	Dragging 53
	neter/Radius function 138	Vpp, 11 μApp) 91	Holding 53
	ction elements 134	Configuring axis parameters	Operation 52
	stering function	(EnDat)90	Swiping 53
	sured value output 145	Configuring axis parameters	Tapping 52
	Max function	(TTL)	Ground connection, 3-wire cable 49
	vork drive 133	energy saving mode 56	
	function 156, 157	Error compensation	Н
	sets 142	Calibration 102	HEIDENHAIN encoders 87
	ping functions 135	linear error compensation 98,	Holding 53
	tive function	215	1
	hscreen 133	Methods 97	
	keyboard 134	Nonlinear axis error	Informational notes 2
	uring network settings 132	compensation 100	Input devices
_	cting encoders 45	Nonlinear error compensation	connect
	cting touch probes	203	Operation 52
Conne		performing 97	Installation
	nputer 49	segmented linear error	Installation Instructions
	ction overview	compensation 99, 215	Items supplied 30
	d axis115	Squareness error compensation.	L
Coapio	a axio	114, 204	
D		Table of supporting points 216	Language 50, 70, 129
Damag	je in transit 33	Error messages 73	setting 59, 79, 129 License key
Data fo	ormats parameter	Errors and warnings 231	Activating 82
para	meter 148	F	Entering
Stei	nwald 148		requesting8
date ar	nd time 84, 128, 191	File	linear error compensation (LEC). 98
	al places 84, 128, 191	copying	Lissajous figure
	al separators191	deleting	
Device	•	exporting	M
insta	alling 42	importing	Main menu 6
Diagno	stics	moving	Maintenance plan
Erro	rs and warnings 231	Opening	Malfunctions
Fund	ctional reserves 230	renaming	Measure
	stics for encoders with 214	File management	

Diagnostics for encoders with.. 214

Menu 62	confirm	56	59, 79, 125	5, 163
Measured value output	drop-down list	55	Repackaging	
Configuring 145	Function elements		rounding methods 84	
Data format, selecting 147	Main menu		RS-232 adapters	
Data format parameters 148	plus/minus button	54		
Data formats 151	Screen keyboard	54	S	
Functions146	slider	55	Safety precautions	
Measured values, sending 174	slide switch	55	general	
Measured-value output	toggle switch	55	Peripheral devices	26
Contents, selecting 155	undo	55	ScreenshotClient	
Measurement	Operating Instructions	17	Information	
Acquiring the minimum,	updating 1		Scrolling the function bar	·67
maximum, and range 169	Operation		Segmented linear error	
Displaying the diameter 170	Audio feedback	-	compensation (SLEC)	99
Part management 175	Energy saving mode	56	Settings	
Performing 166	Function elements	69	Backing up	
Preparing 162	General operation	52	Menu	
Relative 171	Gestures and mouse actions.		Restore	
Touch probe 167	Messages		Setup	
Menu	Operating elements		Single-Pos	
File management 63	Touchscreen and input		Storage	
Measure 62	devices		Swiping	53
Settings 65	Wizard		Switch-off	
Switch-off 66	Operator	25	Menu	
User login 64	Overview of new and modified		Symbols and fonts used	
Vessages	functions		marking text	
closing74	P		Symbols on the product.	26
viewing 73			Т	
MinMax	Part 1	00		•
Activating a switching	Configuring 156, 1	-	Table of supporting point	
function 137		58	adjusting	
mounting 36	changing 80, 126, 1		creating	
Duo-Pos stand 38	creating 1		Tapping	52
Multi-Pos holder 40	default password 58, 78, 1		Touchscreen	100
Multi-Pos stand 39	Personnel qualification	25	configuring	
Single-Pos stand	Pin layout	4.5	Operation	52
Mouse actions	encoders		U	
configuring 133	line voltage		units of measure 84	1 128 191
Dragging53	network	70	Uploading license file	
Holding 53	switching inputs	1 /	USB keyboard	
Operation 52	Power connector	+ 0	User	
Swiping 53	Preset table		configuring	130
Tapping 52	Creating 1	142	creating	
Moving functions on the function	Product	00	Default password	
oar	commissioning		Login	
Multi-Pos 39, 40	Setting up		Logout	
0	Switch-offSwitch-on		User login	
Obligations of the operating	Product data		user types	
Obligations of the operating	Froduct data	244	User files	
company 25 DEM	Q		Restoring	233
adding documentation 117	Qualified personnel	25	User ID	
_	Qualified personnel		User interface	
Deleting the startup screen 220	R		After start-up	60
modifying startup screen 117 Operating elements	Reference mark search		Factory default setting	
add 55	activating 1	116	File management mer	
back 56	Conducting 1		Main menu	
close 55	performing after startup		Measure menu	
0.000				

Settings menu	64 64
W	
Wiring switching inputs and outputs Wizard Workspace	74
customize	67

17 List of figures

Figure 1:	Dimensions of rear panel of the product	36
Figure 2:	Product mounted on Single-Pos stand	37
Figure 3:	Cable routing on Single-Pos stand	37
Figure 4:	Product mounted on Duo-Pos stand	38
Figure 5:	Cable routing on Duo-Pos stand	38
Figure 6:	Product mounted on Multi-Pos stand	39
Figure 7:	Cable routing on Multi-Pos stand	39
Figure 8:	Product mounted on Multi-Pos holder	40
Figure 9:	Cable routing on Multi-Pos holder	40
Figure 10:	Rear panel on devices with ID 1089181-01	44
Figure 11:	Screen keyboard	54
Figure 12:	The user interface in the product's factory default setting	60
Figure 13:	User interface	61
Figure 14:	Measure menu	62
Figure 15:	File management menu	63
Figure 16:	User login menu	64
Figure 17:	Settings menu	65
Figure 18:	Display of messages in the workspace	73
Figure 19:	Display of messages in the wizards	74
Figure 20:	The ScreenshotClient user interface	119
Figure 21:	Example of an absolute measurement	140
Figure 22:	Example of a difference measurement	140
Figure 23:	Example of a value input for an axis	141
Figure 24:	Example of a transfer for the X and Y axes with the active MinMax function in th Standard	
Figure 25:	Example of a transfer for the X and Y axes with the active MinMax function in th Steinwald	
Figure 26:	Data format MyFormat1.xml	152
Figure 27:	Display of selected contents for Measured value output	155
Figure 28:	Example of active Part function with selected functions	156
Figure 29:	Measure menu	166
Figure 30:	Measure menu with touch probe	167
Figure 31:	Function bar with the function elements for probing functions	168
Figure 32:	Measure menu with active MinMax function	169
Figure 33:	Measure menu with activated D/R function	170
Figure 34:	Measure menu with activated Relative function	171
Figure 35:	Overview	172
Figure 36:	Single view of the dial gage	173
Figure 37:	Measure menu with activated Part function	175
Figure 38:	File management menu	178
Figure 39:	File management menu with preview image and file information	181
Figure 40:	Example of functional reserves of a length gauge	230
Figure 41:	Housing dimensions for products	246
Figure 42:	Dimensions of the rear panel	246
Figure 43:	Product dimensions with Single-Pos stand	247

Figure 44:	Product dimensions with Duo-Pos stand	247
Figure 45:	Product dimensions with Multi-Pos stand	248
Figure 46:	Product dimensions with Multi-Pos holder	248

HEIDENHAIN

DR. JOHANNES HEIDENHAIN GmbH

Dr.-Johannes-Heidenhain-Straße 5

83301 Traunreut, Germany

2 +49 8669 31-0

FAX +49 8669 32-5061

E-mail: info@heidenhain.de

Technical support FAX +49 8669 32-1000 Measuring systems +49 8669 31-3104 Measuring systems 449 8669 31-3104
E-mail: service.ms-support@heidenhain.de

NC support 49 8669 31-3101
E-mail: service.nc-support@heidenhain.de

NC programming 449 8669 31-3103
E-mail: service.nc-pgm@heidenhain.de

PLC programming 449 8669 31-3102
E-mail: service.plc@heidenhain.de APP programming ② +49 8669 31-3106 E-mail: service.app@heidenhain.de

www.heidenhain.de

